



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLK3063Z HONDA VEZEL 1.5X CVT

Page No. 1-1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMEN T
<u>PARTS (LIST ITEMS)</u>				
1	Front door RH		950.00	bt ✓
1	Front bumper		802.00	Rp
1	Front bumper side retainer LH/RH @2*\$18		36.00	Rp
1	Front fender RH		580.00	bt ✓
1	Front fender shield		130.00	2 photo. de ✓
1	Front wheel arch garnish RH		153.00	de ✓
1	Front rocker panel lower side garnish		378.00	dis ✓
1	Front door hinge upper RH		45.00	7 bt ✓
1	Front door hinge lower RH		45.00	7 bt ✓
1	Front bonnet (repair refer to labour and paint)		0.00	Rp
1	Front fender LH (repair refer to labour and paint)		0.00	Rp
Part Items Total:			3119.00	
			-20% -623.80	
			2495.20	
<u>SPECIAL NETT ITEMS</u>				
1	Front fender shield clips		35.00	20 net ✓
1	Front bumper clips		35.00	30 net ✓
1	Front rim RH		580.00	net ✓ 350
SN Items Total:			650.00	
Total Parts			3145.20	370.

2317
1853.60



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLK3063Z HONDA VEZEL 1.5X CVT

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	700
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00	1000 800
3	To perform anti-rust treatment on affected areas	120.00	60 40
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	150.00	30
5	Check and adjust wheel alignment	100.00	80
6	To remove and refix/replace front LH door fittings, trimmings, garnish, glass window and ect	120.00	60
7	Resealing of off peak car license plate at LTA including inspection fees	100.00	60 1990
Labour Total :		2990.00	
TOTAL (PARTS & LABOUR):		6135.20	

Tan Jiah 97495749/67418437
17/11/20 @ 420pm

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Resurvey after repair
Tan Jiah 17/11/20 @ 420pm

1853.60
370
1990
24
220

4457.60 6 days
L15 \$3550