

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0855/2020/NS
DATE	:	9-Nov-20
WIP	:	56908

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR CHAN PERRY M
ADDRESS	:	22 CHOA CHU KANG ST 64 #02-04 SINGAPORE 689094
TELEPHONE	:	HP +65 92340491
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800072304-02
VEHICLE NO	:	SMA 9335 R
MODEL CODE	:	AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR	:	22/6/2018
ENGINE NO	:	CHZ 933727
CHASSIS NO	:	WAUZZZ8V5JA110102
MILEAGE	:	46813KM
DATE IN	:	9-Nov-20
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	8-Nov-20
PLACE OF ACCIDENT	:	LOYANG AVE TOWARDS TPE

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 9335 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	? /
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 700.00	? 500 /
3	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS.	S/N \$ 700.00	X n n
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	/
SUB TOTAL LABOUR CHARGES		: \$ 2,880.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 9335 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	2750
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS.	\$ 5,500.00	2300
7	TO TOW BACK VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	Xm
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 14,452.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 9335 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>cm</i>		\$	1,842.00 1473.60
2 FRONT BUMPER FIXING PARTS <i>? Xnn</i>		\$	185.00 ✓
3 FRONT BUMPER GUIDE SECTION - LH/RH <i>X ? Xsn</i>	2	\$	76.00 ✓
4 FRONT BUMPER GRILLE - CENTRE <i>cm</i>		\$	159.00 126.80
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>? cm</i>		\$	293.00 234.40
6 FRONT BUMPER CLOSING ELEMENT - LH/RH <i>Xsn</i>	2	\$	586.00
7 RADIATOR GRILLE <i>cm</i>		\$	1,406.00 1124.80
8 RADIATOR GRILLE CLOSING ELEMENT <i>? cm</i>		\$	189.00 150.80
9 AIRCON STICKER <i>re</i>	NEC	\$	8.00 5.68
10 CAUTION SIGN STICKER <i>re</i>	NEC	\$	14.00 10.80
11 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>X ? Xsn</i>	2	\$	372.00
12 FRONT REINFORCEMENT BEAM <i>bt</i>		\$	715.00 578.60
13 FRONT BUMPER FOAM FILLER PIECE <i>cm</i>		\$	187.00 149.60
14 FOAM FILLER PIECE COVER <i>de</i>		\$	121.00 96.40
15 SIGNAL HORN RETAINER - LH HIGH TONE <i>? Xsvl</i>		\$	197.00
16 SIGNAL HORN RETAINER - RH LOW TONE <i>? Xsvl</i>		\$	197.00
17 FRONT FENDER - LH/RH <i>L/R</i>	1	\$	1,682.00 672.80
18 FRONT FENDER ATTACHMENT PARTS <i>Xnn</i>		\$	71.00
19 FRONT FENDER BRACKET - LH/RH <i>Xsvl</i>	2	\$	94.00
20 FRONT FENDER BRACE - LH/RH <i>Xsvl</i>	2	\$	190.00
SUB TOTAL SPARE PARTS	:	\$	8,584.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 9335 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21 FRONT FENDER CLOSING ELEMENT - LH/RH <i>? X su</i>	2	\$	122.00
22 WHEEL HOUSING LINER - LH/RH <i>X su</i>	2	\$	334.00
23 WHEEL HOUSING LINER ATTACHMENT PARTS <i>X su</i>		\$	57.00
24 BONNET <i>bt</i>		\$	2,709.00 <i>2167.20</i>
25 BONNET ATTACHMENT PARTS <i>? X su</i>		\$	163.00
26 BONNET LID HINGE - LH/RH <i>bt / photo</i>	2	\$	122.00 <i>96.48</i>
27 BONNET EDGE PROTECTION - FRONT <i>rec</i>		\$	28.00 <i>21.84</i>
28 BONNET SAFETY CATCH <i>? X su</i>		\$	89.00
29 BONNET STRIKER - LH/RH <i>? X su</i>	2	\$	218.00
30 BONNET CATCH HOOK <i>? X su</i>		\$	63.00
31 BONNET LID LOCK <i>X su</i>	2	\$	423.00
32 BONNET BOWDEN CABLE - CENTRE <i>X su</i>		\$	57.00
33 BONNET LID LOCK CABLE <i>X su</i>		\$	73.00
34 BONNET SOUND ABSORBER <i>X su</i>		\$	217.00
35 PLENUM CHAMBER COVER <i>X su</i>		\$	177.00 <i>141.60</i>
36 BONNET GAS FILLED STRUT <i>X su</i>		\$	118.00
37 LED HEADLIGHT - LH/RH <i>? LHeem</i>	1	\$	10,910.00 <i>4364.00</i>
38 LIFT CYLINDER - LH/RH <i>? X su</i>	2	\$	282.00
39 LIFT CYLINDER HOSE <i>? X su</i>		\$	67.00
40 WATER DEFLECTOR STRIP - LH/RH <i>X su</i>	1	\$	132.00 <i>52.80</i>
SUB TOTAL SPARE PARTS	:	\$	16,361.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 9335 R


S/N PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES S/NETT	REMARKS
41 LOCK CARRIER <i>cm /</i>		\$	719.00	575.20
42 AIRCON CONDENSER <i>? dented /</i>		\$	517.00	413.20
43 ADDITIONAL RADIATOR <i>? bt /</i>		\$	859.00	687.20
44 RADIATOR <i>? bt /</i>		\$	941.00	752.80
45 READY MIX COOLANT <i>Rec /</i>		\$	91.00	72.32
46 RADIATOR BRACKET <i>? damaged</i>	2	\$	79.00	62.88
47 RADIATOR BUSH - LOWER <i>? fsv</i>	2	\$	19.00	
48 TEMPERATURE SENSOR BRACKET <i>? fsv</i>		\$	18.00	
49 RADIATOR AIR GUIDE - LH/RH <i>? cm /</i>	2	\$	48.00	38.40
50 RADIATOR AIR GUIDE - UPPER CENTRE <i>? cm /</i>		\$	12.00	9.36
51 AIR INTAKE AIR DUCT COVER <i>? cm /</i>		\$	28.00	22.00
52 AIR INTAKE AIR GUIDE - FRONT <i>? cm /</i>		\$	54.00	43.20
53 AIR INTAKE AIR GUIDE <i>? fsv</i>		\$	64.00	
54 AIR INTAKE AIR GUIDE SEAL <i>? fsv</i>		\$	13.00	
55 AIR INTAKE AIR DUCT <i>? fsv</i>		\$	19.00	
56 WATER DRAINAGE HOSE <i>? fsv</i>		\$	32.00	
57 AIR INTAKE AIR FILTER <i>? fsv</i>		\$	269.00	
58 FRONT NO PLATE <i>bt /</i>	S/N	\$	60.00	/
59 SUNDRIES <i>? cm /</i>		\$	300.00	37.52
TOTAL SPARE PARTS	:	\$	29,087.00	
TOTAL LABOUR CHARGES	:	\$	14,452.00	
GRAND TOTAL	:	\$	43,539.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0855/2020/NS

Date

9-Nov-20

Service Advisor

George Wong

Pages

1 of 1

Regn No

SMA 933S R

Model No

Audi A3 SB 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT CATCH HOOK <i>bt</i>	\$ 63.00	49.76
TOTAL		\$ 63.00	

For Premium Automobiles Pte Ltd

Rene
20/11/2020

Authorised Signature

