

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0855/2020/NS
DATE : 9-Nov-20
WIP : 56908

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR CHAN PERRY M
ADDRESS : 22 CHO A CHU KANG ST 64
#02-04
SINGAPORE 689094
TELEPHONE : HP +65 92340491
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800072304-02
VEHICLE NO : SMA 9335 R
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 22/6/2018
ENGINE NO : CHZ 933727
CHASSIS NO : WAUZZZ8V5JA110102
MILEAGE : 46813KM
DATE IN : 9-Nov-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Nov-20
PLACE OF ACCIDENT : LOYANG AVE TOWARDS TPE

 PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 9335 R**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	?
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULES.	S/N \$ 700.00	?
3	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS.	S/N \$ 700.00	X
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	/
SUB TOTAL LABOUR CHARGES		: \$ 2,880.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 9335 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00 2750	
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS.	\$ 5,500.00 2300	
7	TO TOW BACK VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00 X	
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 14,452.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 9335 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>cm</i>		\$ 1,842.00	
2 FRONT BUMPER FIXING PARTS ?		\$ 185.00	
3 FRONT BUMPER GUIDE SECTION - LH/RH <i>x ?</i>	2	\$ 76.00	
4 FRONT BUMPER GRILLE - CENTRE <i>cm</i>		\$ 159.00	
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ?		\$ 293.00	
6 FRONT BUMPER CLOSING ELEMENT - LH/RH <i>x</i>	2	\$ 586.00	
7 RADIATOR GRILLE <i>cm</i>		\$ 1,406.00	
8 RADIATOR GRILLE CLOSING ELEMENT ?		\$ 189.00	
9 AIRCON STICKER <i>nc</i>	NEC	\$ 8.00	
10 CAUTION SIGN STICKER <i>nc</i>	NEC	\$ 14.00	
11 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>x ?</i>	2	\$ 372.00	
12 FRONT REINFORCEMENT BEAM <i>bt</i>		\$ 715.00	
13 FRONT BUMPER FOAM FILLER PIECE <i>cm</i>		\$ 187.00	
14 FOAM FILLER PIECE COVER <i>dc</i>		\$ 121.00	
15 SIGNAL HORN RETAINER - LH HIGH TONE ?		\$ 197.00	
16 SIGNAL HORN RETAINER - RH LOW TONE ?		\$ 197.00	
17 FRONT FENDER - LH/RH <i>bt R</i>	2	\$ 1,682.00	
18 FRONT FENDER ATTACHMENT PARTS <i>x</i>		\$ 71.00	
19 FRONT FENDER BRACKET - LH/RH <i>x</i>	2	\$ 94.00	
20 FRONT FENDER BRACE - LH/RH <i>x</i>	2	\$ 190.00	
SUB TOTAL SPARE PARTS	:	\$ 8,584.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 9335 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 FRONT FENDER CLOSING ELEMENT - LH/RH 2 ^{2X}	2	\$	122.00	
22 WHEEL HOUSING LINER - LH/RH X	2	\$	334.00	
23 WHEEL HOUSING LINER ATTACHMENT PARTS X		\$	57.00	
24 BONNET bt ✓		\$	2,709.00	
25 BONNET ATTACHMENT PARTS ?		\$	163.00	
26 BONNET LID HINGE - LH/RH bt ✓ photo	2	\$	122.00	
27 BONNET EDGE PROTECTION - FRONT rec ✓		\$	28.00	
28 BONNET SAFETY CATCH ?		\$	89.00	
29 BONNET STRIKER - LH/RH 2 ?	2	\$	218.00	
30 BONNET CATCH HOOK ?		\$	63.00	
31 BONNET LID LOCK X	2	\$	423.00	
32 BONNET BOWDEN CABLE - CENTRE X		\$	57.00	
33 BONNET LID LOCK CABLE X		\$	73.00	
34 BONNET SOUND ABSORBER X		\$	217.00	
35 PLENUM CHAMBER COVER X		\$	177.00	
36 BONNET GAS FILLED STRUT X		\$	118.00	
37 LED HEADLIGHT - LH/RH ?	2	\$	10,910.00	
38 LIFT CYLINDER - LH/RH ?	2	\$	282.00	
39 LIFT CYLINDER HOSE ?		\$	67.00	
40 WATER DEFLECTOR STRIP - LH/RH su ✓	2	\$	132.00	
SUB TOTAL SPARE PARTS	:	\$	16,361.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 9335 R

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 LOCK CARRIER <i>cm /</i>		\$	719.00
42 AIRCON CONDENSER <i>?</i>		\$	517.00
43 ADDITIONAL RADIATOR <i>?</i>		\$	859.00
44 RADIATOR <i>?</i>		\$	941.00
45 READY MIX COOLANT <i>Rec /</i>		\$	91.00
46 RADIATOR BRACKET <i>?</i>	2	\$	79.00
47 RADIATOR BUSH - LOWER <i>?</i>	2	\$	19.00
48 TEMPERATURE SENSOR BRACKET <i>?</i>		\$	18.00
49 RADIATOR AIR GUIDE - LH/RH <i>?</i>	2	\$	48.00
50 RADIATOR AIR GUIDE - UPPER CENTRE <i>?</i>		\$	12.00
51 AIR INTAKE AIR DUCT COVER <i>? X</i>		\$	28.00
52 AIR INTAKE AIR GUIDE - FRONT <i>? cm /</i>		\$	54.00
53 AIR INTAKE AIR GUIDE <i>?</i>		\$	64.00
54 AIR INTAKE AIR GUIDE SEAL <i>?</i>		\$	13.00
55 AIR INTAKE AIR DUCT <i>?</i>		\$	19.00
56 WATER DRAINAGE HOSE <i>?</i>		\$	32.00
57 AIR INTAKE AIR FILTER <i>?</i>		\$	269.00
58 FRONT NO PLATE <i>bt /</i>	S/N	\$	60.00
59 SUNDRIES <i>?</i>		\$	300.00
TOTAL SPARE PARTS	:	\$	29,087.00
TOTAL LABOUR CHARGES	:	\$	14,452.00
GRAND TOTAL	:	\$	43,539.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

Pte Ltd - UBI
n MD Nazri

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 68 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Rasul - Hp 90010068

: 10/11/2020 @ 1530

: 10 days

: EXCESS: TBA

: Resurvey before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT