

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 11/11/2020

Reference: SKT7338U
CHEVROLET /
CAPTIVA C140
Make: 2.4D FWD 6AT

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SKT7338U
CHASSIS NO.: KL1CA26UJFB014288
ENGINE NO.: LE9142820037

TP III
Jasper.

Name of insured .: Alpine Car Rental Pte Ltd
Date of accident.:

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Rear Tailgate <i>Dented</i>	\$ 2,860.00
2	1	Chverolet Lettering <i>2m</i>	\$ 56.00
3	1	Captiva Lettering with LT <i>1m</i>	\$ 57.00
4	1	LT Lettering	\$ 20.00
5	1	Rear Tailgate Windscreen with Moulding <i>new</i>	\$ 1,053.00
6	1	LH Tailgate Hinge <i>3m</i>	\$ 86.00
7	1	RH Tailgate Hinge <i>1m</i>	\$ 86.00
8	1	Rear Tailgate Inner Trim <i>new</i>	\$ 283.00
9	1	Rear Tailgate Weatherstrip <i>off</i>	\$ 145.00
10	1	Rear Tailgate Latch <i>3m</i>	\$ 180.00
11	1	Rear Tailgate Striker <i>1m</i>	\$ 60.00
12	1	LHR Taillamp <i>3m</i>	\$ 1,475.00
13	1	RHR Taillamp <i>1m</i>	\$ 1,475.00
14	1	LHR Upper Bumper <i>3m</i>	\$ 328.00
15	1	RHR Upper Bumper <i>1m</i>	\$ 328.00
16	1	LHR Bumper Bracket <i>3m</i>	\$ 65.00
17	1	RHR Bumper Bracket <i>1m</i>	\$ 65.00
18	1	Rear Bumper Lower <i>Dented</i>	\$ 885.00
19	1	LHR Centre Bumper Guide <i>new</i>	\$ 65.00
20	1	RHR Centre Bumper Guide <i>new</i>	\$ 65.00
21	1	LHR Bumper Reflector <i>crushed</i>	\$ 662.00
22	1	RHR Bumper Reflector <i>crushed</i>	\$ 662.00
23	1	Rear Bumper Lower Moulding - Sill Plate <i>Dented</i>	\$ 570.00
24	1	Rear Bumper Towing Cover <i>new</i>	\$ 45.00

25	1	Rear Bumper Reinforcement Bar	Best	\$ 566.00	✓
26	1	Rear End Panel	Rear	\$ 458.00	+
27	1	Rear End Panel Trim	Rear	\$ 190.00	+
28	1	Exhaust RH - Muffler, Tail Pipe	2	\$ 1,885.00	+
29	1	Exhaust LH - Muffler, Tail Pipe	2	\$ 1,885.00	+
30	1	Exhaust Mounting RH	Green	\$ 60.00	+
31	1	Exhaust Mounting LH		\$ 60.00	+
32	1	Reverse Sensor(3 points)	Dead	\$ 440.00	✓
33	1	Reverse Sensor wiring harness	Not needed	\$ 330.00	✓

7253
 6527.70
Parts Total: \$ 17,450.00
Less 10%: \$ 1,745.00
Total : \$ 15,705.00

Labour

No.	Labour Description	Price (SGD)
Rear portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 3,300.00
2	Carry out spray painting on accident affected area	\$ 2,700.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 110.00
4	To remove and refix reverse sensor and conduct test	\$ 110.00
5	To remove and refix reverse camera and conduct test	\$ 110.00
6	To conduct transfer of parts from old tailgate to new tailgate	\$ 110.00
7	To conduct water leakage test after repairs of vehicle	\$ 110.00
8	To remove and replace exhaust pipe	\$ 110.00
9	To remove and refit fuel tank to facilitate accident repair	\$ 110.00
10	To remove and refix rear tail gate windscreen	\$ 110.00

2360
Labour Total : \$ 6,880.00

Others

No.	Qty	Other Description	Price (SGD)
Rear portion			
1	10	Rear Tailgate Inner Trim Clips	\$ 65.00
2	10	Rear Bumper Lower Clips	\$ 65.00
3	10	Rear End Panel Trim Clips	\$ 65.00
4	1	Rear Tailgate Windscreen Thermal Film	\$ 190.00
5	1	Rear Windscreen Sealant	\$ 90.00

110
Other Total: \$ 475.00

Total: \$ 23,060.00
GST 7%: \$ 1,614.20
GRAND TOTAL: \$ 24,674.20

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

  **Suhaimi Ong**

Service Executive
Suhaimi Ong
HP : 8298 8933 Fax:6844 5185

Adrian L
L/S 11/11/20

04 Days

Supplementary : 301.50

Total: 9299.20

L/S: 7.4K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Attn : Motor Claim Department.

Date: 13/11/2020

From: 1st Autoworks Pte Ltd

Dear Sirs

RE: VEHICLE NO: SKT7338U
CHASIS NO:KL1CA26UJFB014288

Supplementary Items

Further to our estimate dated 11/11/2020, we append hereunder the additional Parts & labour required in respect of the repair as carried to the above vehicle for your kind attention.

Parts

<u>No.</u>	<u>Qty</u>	<u>Description</u>	<u>Amount</u>
1	1	Keyless receiver sensor <i>ould</i>	335.00 ✓

Total: 335.00

Total: 335.00

Less 10%: 33.50

7 % GST: 21.11

Grand Total: 322.61

Adrian
13/11/20
[Signature]

This is only an estimate and should additional work be found necessary to be carried out in the course of repairs, extra materials and labour cost will be charged accordingly. You will be informed prior actions to be taken. **Parts prices are subjected to change.**

Yours faithfully

 **Suhaimi Ong**

Service Advisor

Suhaimi ong

DID : 6844 1985 Fax: 68445185

335
301.50