

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJU 3210L

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Not Notified

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 04/11/2020
TP Veh Reg No: SMU5722C

*Penalty After Repair
2 days*

Estimate No: ES2190765/YISHUN
Date: 16 Aug 2021
Policy No: 5115128361
Veh Reg No: SJU3210L
Make/Model: MINI COOPER 1.6L A/T
ABS D/AB 2WD 2DR
Chassis No: WMWMR32030TL36422
Engine No: B342I587
Reg. Date: 30/11/2009

Estimate Repair Cost to Vehicle No :SJU3210L

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
1 REMOVE AND REFIT REAR BUMPER ASSY, REFLECTORS. REPAIR, REALIGN REAR BUMPER.	300.00	1 LA	300.00	180
2 PUTTY AND RESPRAY ON REAR BUMPER.	300	1 LA	300.00	220
3 REMOVE AND REFIT REVERSE SENSOR & RESET SYSTEM.	50	1 LA	50.00	40
			650.00	650.00
Total				S\$ 650.00
Add GST @ 7%				45.50
Total Amount Payable				S\$ 695.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE