

SERVICE ESTIMATE

5986 - C00001 SL: SERVICE SALES - PC

Mr Tan Yew Kiat
102 Siang Kuang Avenue

Singapore
Singapore 347998

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 06/11/2020

WIP No. . : 48700

Veh.In/Out:

*Tel.No. . : Mobile: 98162228

Reg.No. . : EY6000U

Reg.date .: 20/03/2015

Mileage ... : 0

Chassis No: SAJAC05M4FPU66801

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Tan Yew Kiat

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REPAIR REAR RH FENDER ETC		0	3600.00	0		3,600.00	S
800	TO SPRAYPAINT ON REAR BUMPER & FENDER RHR		0	2400.00	0		2,400.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		0	525.00	0		525.00	S
0031	TO REPLACE REAR RH RIM		0	50.00	0		50.00	S
419	WHEEL ALIGNMENT		0	280.00	0		280.00	S
	BUMPER COVER REAR XF	1.0	EA	2195.10			2,195.10	S
	REAR VALANCE V6 S207	1.0	EA	659.90			659.90	S
	WHEEL-ROAD-ALLOY	1.0	EA	1035.00			1,035.00	S

Gross Total. 10,745.00

Labour Total 6,855.00
Parts Total 3,890.00
Package Total 0.00

Net..... 10,745.00
GST @ 7.0% 752.15
Total..... 11,497.15
Paid..... 0.00
Please Pay.. 11,497.15

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated