

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.. 201929175W

Model : **Mercedes Benz C180 Kompressor**Registraion No : **SKD 8149 B**Chassis No: **WDD2040452A655883**Year of Manufacturing: **2011**

S/No	Qty	Items	Unit Price	Amount
1	1	Bootlid ?	\$ 1,570.80	\$ 1,570.80
2	1	Bootlid Lock X NN	\$ 394.50	\$ 394.50
3	1	Bootlid Logo / MC	\$ 58.90	\$ 58.90
4	1	Bootlid Weatherstrip ?	\$ 280.70	\$ 280.70
	1	Bootlid Inner Trim X NN	\$ 564.70	\$ 564.70
5	1	Rear Bumper / R	\$ 1,456.80	\$ 1,456.80
6	1	Rear Bumper Retainer (RH) - R	\$ 58.50	\$ 58.50
7	1	Rear Bumper Retainer (LH) - R	\$ 58.50	\$ 58.50
8	1	Rear Bumper Bracket (RH) ?	\$ 37.80	\$ 37.80
9	1	Rear Bumper Bracket (LH) ?	\$ 37.80	\$ 37.80
10	1	Rear Bumper Inner Frame Center ?	\$ 182.50	\$ 182.50
11	1	Rear Bumper Reinforcement ?	\$ 797.60	\$ 797.60
12	1	Rear Bumper Lower Lip ?	\$ 978.40	\$ 978.40
13	1	Tail Lamp (RH) ?	\$ 789.40	\$ 789.40
14	1	Tail Lamp (LH) ?	\$ 789.40	\$ 789.40
15	1	Exhaust Pipe (RH) X	\$ 2,127.80	\$ 2,127.80
16	1	Exhaust Pipe (LH) X	\$ 2,127.80	\$ 2,127.80
17	1	Exhaust Pipe Gasket X	\$ 25.50	\$ 25.50
18	1	Exhaust Pipe Mounting X	\$ 95.40	\$ 95.40
19	1	End Panel ?	\$ 1,365.60	\$ 1,365.60
20	1	End Panel Top Garnish ?	\$ 159.40	\$ 159.40

\$ 13,957.80**-5% \$ 697.89****Total for spare parts \$ 13,259.91****Special Nett**

1	1	Rear Bumper Clip set /	\$ 50.00	\$ 50.00
2	1	End Panel Top Garnish Clip set - MC	\$ 50.00	\$ 50.00
3	1	Reverse Sensor set ?	\$ 450.00	\$ 450.00
4	1	End Panel Sealant ?	\$ 85.00	\$ 85.00
5	1	Tail Lamp Clip set \$ / MC	\$ 30.00	\$ 30.00

Total for SP \$ 665.00**Sub-Total for Parts : \$ 13,924.91**

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	900.00 400
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	800.00 500
3		To check wiring system to facilitate repair and refit the same	\$	60.00 30
4		Apply rust proofing on the adjacent panels	\$	80.00 }
5		To supply under coating / putty on parts replaced	\$	50.00 }
6		To perform water seepage test after repair	\$	80.00 XIN
7		Remove and refit rear end panel lining and garnish to facilitate repair	\$	80.00 60
8		Remove and refit rear bumper sensor	\$	60.00 40
TOTAL AMOUNT :			\$	2,110.00
OVERALL COST:			\$	16,034.91

4 Days.

Insurance Repair.

After repair photos.

Gino Ruf

13/11/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____