

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

Adnan

Lick

Indi

Blk 1 Kaki Bukit Ave 6

09/11/2020

01-43

Singapore 417883

TP III
Jasper

Accident date: 07-11-2020

Estimated repair cost for vehicle no: SLJ8458R NISSAN QASHQAI 1.2 CVT 18'

CHASSIS: SJNFBAJ11U1796315

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>torn</i>		\$1,934.50 614.60
2	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
3	1	Front R/H Bumper Side Retainer <i>Payd</i>		\$29.60 ✓
4	1	Front R/H Bumper Fog Lamp		\$323.70 X
5	1	Front R/H Bumper Fog Lamp Cover		\$130.10 X
6	1	Front R/H Bumper Fog Lamp Rear Cover		\$130.10 +
7	1	Front R/H Head Lamp <i>cut</i>		\$3,243.00 2961
8	1	Front R/H Head Lamp Lower Bracket <i>new</i>		\$28.10 X
9	1	Front R/H Fender <i>dented</i>		\$753.60 683
10	1	Front R/H Fender Cowling <i>new</i>		\$128.30 X
11	10	Front R/H Fender Cowling Clip <i>new</i>	\$6.50	\$65.00 X
12	1	Front R/H Fender Arch Protector <i>dented</i>		\$654.00 483
13	8	Front R/H Fender Arch Protector Clip <i>new</i>	\$6.50	\$52.00 20
14	1	Front R/H Door <i>Repair</i>		\$1,666.20 X
15	2	Front R/H Door Hinge <i>new</i>	\$69.10	\$138.20 X
16	1	Front R/H Rim <i>cut</i>		\$1,681.50 800 (SN)
17	1	Front R/H Tyre <i>new</i>		\$450.00 X
18	1	Front R/H Knuckle Arm <i>dented</i>		\$557.00 ✓
19	1	Front R/H Knuckle Arm Bearing <i>new</i>		\$348.60 218
20	1	Front R/H Lower Arm <i>Bent</i>		\$345.50 224
21	1	Front R/H Shock Absorber <i>Bent</i>		\$563.30 421
22	1	Front R/H Shock Absorber Mounting <i>new</i>		\$256.80 X
23	1	Front R/H Drive Shaft <i>new</i>		\$1,625.30 X
24	1	Front Steering Rack <i>Bent</i>		\$1,917.90 X
25	1	Front Stabilizer Bar <i>new</i>		\$401.20 X

8159.10

Subtotal :- \$17,188.50

734319

S.N: 800

Labour charges

To remove & refit front undercarriage, drive shaft & steering rack	\$450.00 350
To check wheel alignment	\$150.00 80
To check wiring	\$200.00 30
Towing fee	\$150.00 60
Tuff kote	\$150.00 X
Panel beating	\$1,600.00 500
Spray painting	\$1,600.00 600

Subtotal :- \$4,300.00

Total:- \$21,488.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 9763.19

L/S: 7.8K

06 Days

7.8K

06 Days