



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2103039

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 29/04/2021
Reference CC4/FCI20012359/Aes3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SGA 5544B
Insured Veh. SHC 179H
Claim No. D20004587MFSH
Policy No. D-20094921MFSH
Accident Date 09/11/2020
Inspection Date 11/11/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20012359/Aes3q2	
			Date: 29/04/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 179H	Veh. Inspected	SGA 5544B	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20004587MFSH	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	11/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC SIR	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	1995	
Chassis No.	JHMEK44500S000407	Colour	WHITE	
Odometer	351907 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	205/50 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/50 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/50 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/11/2020	Inspection Date	11/11/2020	
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 5544B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET LOCK	DAMAGED	86.40	86.40
1	FRONT BONNET LOCK BRACKET	BENT	48.00	48.00
2	FRONT BONNET HINGES @\$43.20	BENT	86.40	86.40
1	FRONT SUPPORT PANEL	DISTORTED	680.00	680.00
1	FRONT GRILLE	CRACKED	310.00	310.00
1	FRONT GRILLE RIM	NOT NECESSARY	180.00	-
2	FRONT HEADLAMP @\$880.00	N/S CUT	1,760.00	569.00
2	FRONT HEADLAMP LOWER BRACKET @\$54.00	NOT NECESSARY	108.00	-
1	FRONT BUMPER	DISTORTED	660.00	660.00
2	FRONT BUMPER SIDE HOLDER @\$46.80	NECESSARY	93.60	93.60
1	FRONT BUMPER LOWER CENTRE GRILLE	DEFORMED	110.00	110.00
1	SET FRONT BUMPER CLIPS	NECESSARY	60.00	30.00
1	FRONT LH FENDER	DISTORTED	580.00	580.00
1	FRONT LH FENDER INNER SHIELD	NOT NECESSARY	108.00	-
1	SET FRONT LH FENDER INNER SHIELD CLIPS	NOT NECESSARY	60.00	-
1	FRONT LH WHEEL HOUSING	TO REPAIR SEE LABOUR	672.00	-
1	AIRCOND CONDENSER	BENT	580.00	580.00
1	AIRCOND LIQUID PIPE	NOT NECESSARY	228.00	-
1	AIRCOND SUCTION HOSE	NOT NECESSARY	216.00	-
1	AIRCOND DISCHARGE HOSE	NOT NECESSARY	252.00	-
1	AIRCOND COMPRESSOR	NOT NECESSARY	960.00	-
1	RADIATOR	BENT	1,500.00	855.00
1	RADIATOR FAN	CUT	62.40	62.40
1	RADIATOR FAN COWLING	DAMAGED	82.80	82.80
1	RADIATOR FAN MOTOR	DAMAGED	372.00	282.00
2	HORN @\$84.00	NOT NECESSARY	168.00	-
1	WIPER TANK	DEFORMED	99.60	99.60
	LESS 20% DISCOUNT		-2,024.64	-1,043.04
			8,098.56	4,172.16



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BONNET (SN)	DISTORTED	1,800.00	1,000.00
2	FRONT BONNET SIDE LOCK @\$150.00 (SN)	DAMAGED	300.00	200.00
1	FRONT BUMPER LOWER LIP(SN)	DISTORTED	650.00	450.00
1	OIL COOLER (SN)	BENT	900.00	600.00
	LESS 20% DISCOUNT		-730.00	-
			2,920.00	2,250.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	MISSING	50.00	30.00
1	FRONT NUMBER PLATE HOLDER (SN)	MISSING	50.00	30.00
			100.00	60.00
	<u>LABOUR</u>			
	REMOVE & REINSTALL AIR CON FILL IN GAS.		150.00	120.00
	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF FRONT LH WHEEL HOUSING .		1,600.00	1,000.00
	RESPRAY PAINTING .		1,300.00	1,100.00
	WIRING .		100.00	30.00
	SPRAY TUFF COAT.		150.00	60.00
	TOWING FEES.		60.00	60.00
			3,360.00	2,370.00
GRAND TOTAL			14,478.56	8,852.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,000.00

Report Ref No. CC4/FCI20012359/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGA 5544B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGA 5544B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

