



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2101116

36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV Date 22/02/2021  
Reference CC4/FCI20012362/Gra3q2  
Code FCI2

### PROFESSIONAL SERVICE FEE

Vehicle No. XD 8401T  
Insured Veh. SHC 8477U  
Claim No. D20004562MFSH  
Policy No. D-20094922MFSH  
Accident Date 07/11/2020  
Inspection Date 11/11/2020

Description	Total
Third Party Express Settlement	600.00
<b>Subtotal</b>	<b>600.00</b>
<b>GST (7%)</b>	<b>42.00</b>
<b>Grand Total</b>	<b>642.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20012362/Gra3q2	
			Date: 22/02/2021	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 8477U	Veh. Inspected	XD 8401T	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20004562MFSH	Excess (\$)	0.00	
Assign From	CHRIS	Assign Date	11/11/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAN TGM 18.280	c.c	6871	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WMAN08ZZ7DY296490	Colour	YELLOW	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	6 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	6 mm	
R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	6 mm	
L/H Rear Tyre	295/80 R22.5	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/11/2020	Inspection Date	11/11/2020	
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 8401T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b>			
	TO SUPPLY VERDEGRO US-100K (TMA'S) TRUCK MOUNTED ATTENUATORS (PASS NCHRP350 STS LEVER 3 C/W HYDRAULIC LIFT UP).		59,800.00	42,000.00
	TO SUPPLY LABOUR FOR INSTALLATION.		3,000.00	1,000.00
			62,800.00	43,000.00
	<b>GRAND TOTAL</b>		<b>62,800.00</b>	<b>43,000.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>43,000.00</b>

Report Ref No. CC4/FCI20012362/Gra3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



TEL: 6256 3561 FAX: 6256 4315

PHOTOGRAPHS FOR VEHICLE NO. XD 8401T

## INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. XD 8401T

### RE-INSPECTION

