

ASS. REC. BY: Marcus

REF:

CC4/ASM 20012364/Ugs3

ASSIGNMENTFrom: Date:
Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBA9623P

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

Good
Vehicle: IN / OUTVeh No: GBA 9623P Yr Regn: 4, 08
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace c.c. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 500859 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

COE 29-4-2023 MYA #9250
NOT #7750

24/11/20 1/5 @ 7000 confirmed with Aln.

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) _ S + RS _ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

4m ccilia

Not Advised 17/11/20
d/s 27000/ 8 days.

VEHICLE No: GBA 9623P

1PC	TAILGATE	2	\$2,149.00X
1PC	TAILGATE REAR LOGO	nu	\$68.60 ✓
1PC	TAILGATE 'TOYOTA' STICKER	nu	\$65.00 ✓
1PC	TAILGATE 'HIACE' STICKER	nu	\$62.00 ✓
1PC	TAILLAMP O/S	CR	\$388.20 ✓
1PC	TAILLAMP LOWER GARNISH O/S	25	\$161.00 ✓
1PC	TAILLAMP LOWER PANEL O/S	DD	\$492.50 ✓
1PC	REAR BUMPER	25	\$488.20 ✓
1PC	REAR BUMPER SIDE RETAINER O/S	CR	\$145.50 ✓
1SET	REAR BUMPER CLIPS	nu	\$50.00 ✓
1PC	REAR FENDER O/S	3.05/500	\$1,992.10 ✓
1PC	REAR AIR VENT	25	\$82.50 ✓
1PC	REAR END PANEL	2	\$689.20 X
1PC	FRONT BUMPER	DD	\$581.10 ✓
1PC	FRONT BUMPER CENTRE GRILLE	2w	\$133.20 ✓
2PCS	FRONT BUMPER SIDE RETAINERS @\$66.50	11	\$133.00 X
1PC	FRONT BUMPER BEAM	2	\$580.10 X
2PCS	FRONT BUMPER BEAM BRACKETS \$95.00	11	\$190.00 ✓
1PC	FRONT BUMPER TOP RETAINER	25	\$245.50 X
2PCS	FRONT BUMPER BRACKETS \$255.10	25	\$510.20 ✓
1SET	FRONT BUMPER CLIPS	nu	\$50.00 ✓
1PC	FRONT BRACE PANEL	25	\$161.20 ✓
1PC	FRONT SUPPORT PANEL	2	\$745.10 X
1PC	BONNET	20/200	\$707.95 ✓
1PC	BONNET LOGO	nu	\$68.50 ✓
1PC	BONNET LOCK	8u	\$199.20 X
2PCS	HEADLAMPS @\$850.00	CR	\$1,700.00 ✓
1PC	CONDENSER	11	\$1,219.00 X
1PC	RADIATOR	11	\$1,688.20 X
1PC	FRONT GRILLE	CR	\$655.10 ✓
			\$16,401.15

S.NETT

1PC	TAILGATE 70KM/H STICKER	nu	\$20.00/0
1PC	REAR WINDSCREEN SEALANT	11	\$50.00 X
1SET	REAR BUMPER REVERSE SENSOR	11	\$280.00 X
1PC	FRONT BUMPER LICENCE PLATE	25	\$20.00/4

TO CHECK WIRING

TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$50.00 30
TO DISMANTLE & REFIX REAR WINDSCREEN	\$80.00 50
TO DISMANTLE & REFIX TAILGATE MECHANISM	11 \$150.00 X
	11 \$100.00 X

TO REFILL AIR CON GAS
 TO SPRAY RUST PROOFING
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

11 \$120.00 X
 \$100.00 80
 \$1,800.00 1400
 \$2,000.00 1180
 \$21,171.15

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-8064.4
 252
 P-6048.30

S.V-24
 L-2740

8812.30
 202
 7049