



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC20011600/Qsd3e2-1 Date: 23/12/2020 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 2283X	Veh. Inspected	SLB 3133C	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/20/20/VC05/023814	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	11/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER 2.0	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JF1SJGK85GG067453	Colour	BLACK	
Odometer	106897 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	PIRELLI	6 mm	
L/H Front Tyre	235/55 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/55 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/55 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/10/2020	Inspection Date	26/10/2020	
Survey held at	DYNAMICS MECHANIC PTE LTD 184 WOODLANDS INDUSTRIAL PARK E5 #01-03/04 SINGAPORE 757514			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	