



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVENUE 6 #01-39 AUTOBAY@KAKI BUKIT SINGAPORE 417883 ON BEHALF OF MUHAMMAD RASUL BIN HAZMAN			Ref: CS/TP20012372/Uqf3e2 Date: 27/11/2020 Code: TP510	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.		Veh. Inspected	FBD 156P
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	11/11/2020
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CB400	c.c	399
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	NC421003882	Colour	GREY
	Odometer	-	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	120/70 ZR17	MICHELIN	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	180/55 ZR17	MICHELIN	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/11/2020	Inspection Date	11/11/2020
	Survey held at	CHOO MOTOR SPRAY PAINTER 1 KAKI BUKIT AVENUE 6 #01-39 AUTOBAY@KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	