

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5430Z**AAD2011-049***Not Withheld**Resurvey B4 point*

Vehicle No.: 10 NOV 2020
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHC5430Z

JTDKB3FU703092432

TOYOTA

PRIUS GEN 4

08/11/2020

30/10/2020

		LIST	
	PART		
1	COVER, REAR BUMPER	\$ B/L/Tn 485.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ Rn 332.70	✓
1	GUARD, REAR BUMPER, CENTER	\$ Tn 374.50	✓
1	PANEL SUB-ASSY, QUARTER, LH	\$ R 871.50	X
1	RETAINER, REAR BUMPER SIDE, RH	\$ L 132.60	X
1	RETAINER, REAR BUMPER SIDE, LH	\$ Dis 132.60	✓
1	COVER, REAR FLOOR (CTR)	\$ Bn 229.90	✓
1	COVER, FLOOR UNDER, NO.1 (LH)	\$ Dis 175.10	✓
1	COVER, FLOOR UNDER, NO.2 (RH)	\$ L 241.90	X
1	REFLECTOR ASSY, REFLEX, LH	\$ CM 39.00	✓
1	REFLECTOR ASSY, REFLEX, RH	\$ L 39.00	X
1	COVER, REAR BUMPER, LOWER	\$ Mir 22.00	✓
1	PANEL SUB-ASSY, BACK DOOR	\$ Rn 1,147.80	✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ CM 913.60	✓
1	ORNAMENT SUB-ASSY, BACK DOOR	\$ Rn 47.90	✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$ Rn 54.60	✓
1	PLATE, BACK DOOR NAME, NO.1	\$ Rn 54.60	✓
1	PAN, REAR FLOOR	\$ R 583.40	X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$ Rn 651.00	✓
1	LINER, REAR WHEEL HOUSE, LH	\$ L 139.80	X
1	LAMP ASSY, REAR, LH (BOOT)	\$ L 293.60	X
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	\$ CM 261.00	✓
1	LENS & BODY, REAR COMBINATION LAMP, LH	\$ L 339.60	✓
1	UNIT ASSY, HEADLAMP, LH	\$ M3CM 2,637.60	✓
1	UNIT ASSY, HEADLAMP, RH	\$ L 2,637.60	X
1	COVER, FRONT BUMPER HOLE, LH	\$ L 30.20	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2011-049

SHC5430Z

- 1 COVER, FRONT BUMPER
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 EMBLEM ASSY, RADIATOR GRILLE
- 1 GRILLE SUB-ASSY, RADIATOR

\$	Bu	521.00	✓
\$	SVC	716.60	X
\$	Dir	59.30	✓
\$	Sm	59.30	X
\$	SVC	80.20	X
\$	CM	105.80	✓
\$	SVC	422.50	X
TOTAL	\$	14,833.40	
25%	\$	3,708.35	
	\$	11,125.05	

Special Nett

- 1 FRT NUMBER PLATE WITH HOLDER
- 1 REAR NUMBER PLATE WITH HOLDER
- 1SET PARKING AID
- 1SET FRT BUMPER CLIP
- 1SET REAR BUMPER CLIP
- 1 WHEELHOUSE LINER CLIP
- 1 REAR BUMPER PROTECTOR
- 1 REAR BUMPER RETAINER CLIP
- 1 BOOTLID STICKER 'TRANSCAB'
- 1 BOOTLID STICKER '65553333'
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 BUMPER CENTRE GUARD CLIP

\$	Nu	120.00	45SN
\$	Ry	120.00	45SN
\$	short	700.00	220SN
\$	Nu	80.00	66SN
\$	Nu	85.00	66SN
\$	nn	70.00	X
\$	nn	180.00	X
\$	nn	75.00	X
\$	Nu	100.00	30SN
\$	Nu	100.00	30SN
\$	Nu	150.00	40SN
\$	Nu	200.00	120SN
\$	Nu	130.00	30SN
\$	nn	80.00	X
TOTAL	\$	1,630.00	
TOTAL PARTS	\$	12,755.05	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 60h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5430Z**AAD2011-049**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	180L
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	60L
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	900L
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	1320L
To reinstall rear bumper parking sensor.	\$	170.00	50L
To Check Electrical Lighting Concerned.	\$	170.00	40L
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	~ 170.00	X
TOTAL	\$	5,230.00	
Over All Total	\$	17,985.05	

(PART-BY-PART) Repair Days**20 Days****7 days****For Official Use**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: