

Section A - Accident Details

Registration Number	SHB5953L
Case Reference Number	TAX/11/20/2022
Registration Date	19/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	S AASAITHAMBY
Type of Accident	Stationary Object
Accident Date and Time	10/11/2020 7:30 PM
Accident Reported Date and Time	11/11/2020 11:21 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108763
Special Instruction to ARC, if any	DROVE IN / FRONT PORTION/ NTUC - LKK
Prepared Date and Time	11/11/2020 1:48 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,278.00	\$200.00
Total Spare Part Cost	\$10,531.42	\$632.39
Total Other Cost	\$600.00	(\$132.39)
TOTAL COST	\$12,916.42	\$900.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	12/11/2020 4:11 PM	13/11/2020 11:23 AM
Signature		
Remarks	Total number of repair days = 3 DAYS SUP = + 1 DAY	
	L/S, after paint photo.	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		5142047030	COVER ASSY, ENGINE	1.00	\$180.10	25.00	\$135.08	Replace	Replace
		5261147140	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.73	Replace	Replace
Total					250.40		187.81		

CRA
CRU

$$\begin{array}{r}
 632.42 \\
 + 200.00 \\
 + 280.00 \\
 \hline
 1112.42 \\
 - 202 \\
 \hline
 889.94
 \end{array}$$

4589.00/-

3 days