

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 25 Nov 2020

**Preliminary Advice**

|                    |                                                                                             |                         |              |
|--------------------|---------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLA315U                                                                                   | Accident Date           | : 28/10/2020 |
| TP Vehicle No      | : SMC5724S                                                                                  | Assignment Date         | : 23/11/2020 |
| Make               | : HONDA CIVIC                                                                               | Est. Duration of Repair | : 10         |
| Date of Inspection | : 11/11/2020                                                                                |                         |              |
| Inspection At      | : FASTECH AUTO PTE LTD (HQ)<br>1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |          |               |
|-----------------------------|----------|---------------|
| Repairer's Estimate (Gross) | :S\$     | 38,533.30     |
| Revised Amount              | :S\$     | 14,126.56     |
| Check Items (Estimated)     | :S\$     | 0.00          |
| Total                       | :S\$     | 14,126.56     |
| <br>Lump Sum Repair         | <br>:S\$ | <br>11,300.00 |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( X ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis.