



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department
Contact : 62238122 Fax No. : 62244174

with Cecilia
not approved
for
d/s @ 8500
8 days.
11/11/20
the photo attached

Estimate : ES707786

Date : 11/11/2020
Vehicle Num. : SJU 9712R
Make/Model : SUZUKI SWIFT SPORT
Chassis/Eng# :
Accident Date : 11/11/2020
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1PC	LIST ITEMS : FRONT BUMPER		690.95
2.	2PCS	FRONT BUMPER SIDE RETAINER <i>2.5</i>	35.15	70.30 <i>1PC</i>
3.	1PC	FRONT BUMPER REINFORCEMENT <i>mscra</i>		230.05
4.	1PC	FRONT BUMPER REINFORCEMENT COVER <i>top Bent</i>		155.50
5.	1PC	FRONT BUMPER LOWER BEAM <i>top crs</i>		183.85
6.	1PC	N/S FRONT BUMPER LOWER SKIRT <i>Bent</i>		181.65
7.	1PC	N/S FOG LAMP <i>2.5</i>		226.45
8.	1PC	N/S FOG LAMP GARNISH <i>crs</i>		71.05
9.	1PC	N/S FRONT FENDER <i>2.5</i>		359.65
10.	1PC	N/S FRONT FENDER INNER SHIELD <i>70cm</i>		86.45
11.	1PC	N/S FRONT FENDER INNER COVER <i>2.5</i>		43.55
12.	1PC	N/S HEADLAMP <i>320</i>		587.10
13.	1PC	N/S HEADLAMP PANEL <i>486-ft</i>		93.35
14.	1PC	N/S HEADLAMP LOWER BRACKET <i>NS</i>		28.70
15.	1PC	RADIATOR SUPPORT PANEL ASSY <i>NS</i>		683.45
16.	1PC	HORN <i>11</i>		58.90
17.	1PC	N/S FRONT FENDER TOP GARNISH <i>marked</i>		77.15
18.	1PC	N/S ANTI- ROLL BAR LINKAGE <i>11</i>		88.70
19.	1PC	ANTI ROLL BAR <i>Bent</i>		355.70
20.	2PCS	ANTI ROLL BAR BUSH <i>Bent</i>	16.58	33.16
21.	1PC	FRONT BUMPER LOWER BEAM COVER <i>crs</i>		138.95
22.	1PC	N/S FRONT WHEEL BEARING <i>188-20</i>		250.70

CONTINUE / ...

Insurance Company will hence notify the Surveyor of the following:

- To resurvey the vehicle after spray painting
- To resurvey the damaged part(s) during resurvey
- The estimate is valid only upon confirmation
- Third party survey is on a "Without Prejudice" basis
- No alterations/modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Estimate : ES707786

Date : 11/11/2020

Vehicle Num. : SJU 9712R

Make/Model : SUZUKI SWIFT SPORT

Chassis/Eng# :

Accident Date : 11/11/2020

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1PC	N/S FRONT SHOCK ABSORBER <i>Bent</i>		351.50 /
24.	1PC	N/S FRONT SHOCK ABSORBER MOUNTING <i>11</i>		49.85 X
25.	1PC	N/S FRONT LOWER ARM <i>Buc</i>		298.40 /
26.	1PC	N/S FRONT KNUCKLE ARM <i>Bent</i>		335.30 /
27.	1PC	N/S FRONT HUB <i>Bent</i>		286.50 X
28.	1PC	N/S FRONT DRIVESHAFT <i>Buc</i>		1,163.70 X
29.	1PC	STEERING RACK ASSY <i>Buc</i>		2,460.20 X
30.	1PC	FRONT CROSSMEMBER <i>Bent/cur</i>		1,095.10 /
31.	1PC	BONNET <i>Buc</i>		730.40 /
32.	2PCS	BONNET HINGES <i>11</i>	48.55	97.10 X
33.	1PC	N/S WIPER GARNISH <i>11</i>		150.55 X
34.	1PC	FUSE BOX CW WITH WIRE HARNESS <i>11</i>		1,209.16 X
35.	1PC	FUSE BOX COVER <i>11</i>		59.60 X
36.	1PC	N/S ENGINE UNDERCOVER <i>11</i>		55.85 /
37.	1PC	RADIATOR <i>11</i>		806.15 X
38.	1PC	AIR-CON CONDENSER <i>11</i>		628.15 X
39.	1PC	N/S A PILLAR OUTER <i>11</i>		585.30 /
40.	1PC	N/S FRT WHEELHOUSE PANEL <i>11</i>		683.50 X
41.	1PC	FRONT WINDSCREEN GLASS MOULDING <i>11</i>		96.90 /
42.	1PC	BONNET SEAL <i>11</i>		48.35 /
List TotalS\$:				15,886.87
15.00% Discount S\$:				2,383.03
				13,503.84

CONTINUE / ...

2070.61
152
601201

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Estimate : ES707786

Date : 11/11/2020

Vehicle Num. : SJU 9712R

Make/Model : SUZUKI SWIFT SPORT

Chassis/Eng# :

Accident Date : 11/11/2020

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPECIAL NETT ITEMS :				
1.	1SET	FRONT BUMPER CLIP <i>nee</i>		50.00 ✓
2.	1SET	N/S FRONT FENDER INNER SHIELD CLIP <i>nee</i>		50.00 ✓
3.	1PC	HORN BRACKET <i>11</i>		50.00 X <i>SM</i>
4.	1PC	N/S FRONT RIM <i>Buf</i>		800.00 <i>450</i>
5.	2PCS	MICHELLIN PILOT SPORT 4 17 INCH <i>tyre ep 250 500 S/N DM 350.00 125</i>		700.00 <i>172</i>
6.	1BTL	ENGINE OIL <i>11</i>		120.00 X
7.	1SET	DENSO HORN <i>11</i>		150.00 X
8.	1BTL	TRANSMISSION FLUID <i>11</i>		120.00 X
9.	1PC	N/S ROCKER PANEL SKIRT <i>D.S</i>		800.00 <i>500</i>
10.	1PC	N/S ROCKER PANEL SKIRT CLIP <i>nee</i>		50.00 ✓
11.	1PC	BONNET INSULATOR CLIP <i>nee</i>		50.00 <i>30</i>
12.	1PC	BONNET STICKER <i>11</i>		40.00 X
13.	1PC	BONNET SEALANT <i>11</i>		80.00 X
14.	1SET	N/S ENGINE UNDERCOVER CLIPS <i>11</i>		50.00 X
15.	1PC	IU BRACKET <i>11</i>		26.00 X
16.	1BTL	FRT WS SEALANT <i>nee</i>		50.00 <i>140</i>
17.	1SET	FRT WINDSCREEN INNER SEAL <i>nee</i>		45.00 <i>30</i>
18.	1BTL	COOLANT <i>11</i>		35.00 X
Special Nett Total S\$:				3,266.00
LABOUR :				
TO CHECK LIGHT SYSTEM				50.00 X <i>NN</i>

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Estimate : ES707786

Date : 11/11/2020

Vehicle Num. : SJU 9712R

Make/Model : SUZUKI SWIFT SPORT

Chassis/Eng# :

Accident Date : 11/11/2020

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		COMPUTERIZED WHEEL ALIGNMENT	60	120.00
		ANTI-RUST	100	150.00
		TO APPLY BODY SEALANT ON BODY JOINTS	11 X	150.00
		TO REMOVE/REFIT DASHBOARD TO FACILITATE REPAIRS	200	300.00
		TO REMOVE/REFIT INNER TRIMS AND GARNISHES	11 X	180.00
		TO VACCUM, REOIL AND REGAS AIR CON	11 X	120.00
		TO RECONNECT BROKEN WIRES AND REPLACE FUSE BOX	80	250.00
		TO LIFT ENGINE, DROP GEARBOX TO FACILITATE REPAIRS	11 X	450.00
		TO REMOVE/REFIT FRT WINDSCREEN GLASS	✓	120.00
		TO REPLACE FRONT UNDERCARRIAGE	300	400.00
		TO CONDUCT CHASSIS ALIGNMENT	11 X	300.00
		TO PLUG IN DISGNOSTIC AND CLEAR CODES	11 X	250.00
		LABOUR/PANEL BEATING	1200	2,000.00
		TO PUTTY AND RESPRAY	1300	1,800.00
		Labour Total S\$:		6,640.00

E. & O.E.

Total S\$:

23,409.84


for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

p - 6010.01
s/n - 1325
L-3360
10695.01
201
RFB.

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg