



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Estimate : ES707786

Date : 11/11/2020

Vehicle Num. : SJU 9712R

Make/Model : SUZUKI SWIFT SPORT

Chassis/Eng# :

Accident Date : 11/11/2020

Claim No. :

Reference :

Policy No. :

S/N Quantity Particular Unit Price Amount S\$

1.	1PC	FRONT BUMPER			690.95
2.	2PCS	FRONT BUMPER SIDE RETAINER	35.15		70.30
3.	1PC	FRONT BUMPER REINFORCEMENT			230.05
4.	1PC	FRONT BUMPER REINFORCEMENT COVER			155.50
5.	1PC	FRONT BUMPER LOWER BEAM			183.85
6.	1PC	N/S FRONT BUMPER LOWER SKIRT			181.65
7.	1PC	N/S FOG LAMP			226.45
8.	1PC	N/S FOG LAMP GARNISH			71.05
9.	1PC	N/S FRONT FENDER			359.65
10.	1PC	N/S FRONT FENDER INNER SHIELD			86.45
11.	1PC	N/S FRONT FENDER INNER COVER			43.55
12.	1PC	N/S HEADLAMP			587.10
13.	1PC	N/S HEADLAMP PANEL			93.35
14.	1PC	N/S HEADLAMP LOWER BRACKET			28.70
15.	1PC	RADIATOR SUPPORT PANEL ASSY			683.45
16.	1PC	HORN			58.90
17.	1PC	N/S FRONT FENDER TOP GARNISH			77.15
18.	1PC	N/S ANTI- ROLL BAR LINKAGE			88.70
19.	1PC	ANTI ROLL BAR			355.70
20.	2PCS	ANTI ROLL BAR BUSH	16.58		33.16
21.	1PC	FRONT BUMPER LOWER BEAM COVER			138.95
22.	1PC	N/S FRONT WHEEL BEARING			250.70

CONTINUE / ...

Insurance Company please notify
the Surveyor at the following:
 • To resurvey the car after spray painting
 • To resurvey the car (part(s)) during resurvey
 • The car must be returned to confirmation
 • The survey must be on a "Without Prejudice" basis
 • No alterations/modifications is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Estimate : ES707786

Date : 11/11/2020

Vehicle Num. : SJU 9712R

Make/Model : SUZUKI SWIFT SPORT

Chassis/Eng# :

Accident Date : 11/11/2020

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1PC	N/S FRONT SHOCK ABSORBER <i>Bent</i>		351.50 /
24.	1PC	N/S FRONT SHOCK ABSORBER MOUNTING <i>11</i>		49.85 x
25.	1PC	N/S FRONT LOWER ARM <i>Buc</i>		298.40 /
26.	1PC	N/S FRONT KNUCKLE ARM <i>Bent</i>		335.30 /
27.	1PC	N/S FRONT HUB <i>Bent</i>		286.50 x
28.	1PC	N/S FRONT DRIVESHAFT <i>Buc</i>		1,163.70 x
29.	1PC	STEERING RACK ASSY <i>Buc</i>		2,460.20 x
30.	1PC	FRONT CROSSMEMBER <i>Bent/buc</i>		1,095.10 /
31.	1PC	BONNET <i>Buc</i>		730.40 /
32.	2PCS	BONNET HINGES <i>11</i>	48.55	97.10 x
33.	1PC	N/S WIPER GARNISH <i>11</i>		150.55 x
34.	1PC	FUSE BOX CW WITH WIRE HARNESS <i>11</i>		1,209.16 x
35.	1PC	FUSE BOX COVER <i>11</i>		59.60 x
36.	1PC	N/S ENGINE UNDERCOVER <i>11</i>		55.85 /
37.	1PC	RADIATOR <i>11</i>		806.15 x
38.	1PC	AIR-CON CONDENSER <i>11</i>		628.15 x
39.	1PC	N/S A PILLAR OUTER <i>11/Bent</i>		585.30 /
40.	1PC	N/S FRT WHEELHOUSE PANEL <i>11</i>		683.50 x
41.	1PC	FRONT WINDSCREEN GLASS MOULDING <i>11</i>		96.90 /
42.	1PC	BONNET SEAL <i>11</i>		48.35 /
List TotalS\$:				15,886.87
15.00% Discount S\$:				2,383.03
				13,503.84

CONTINUE / ...

2070.61
152
601201

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Estimate : ES707786

Date : 11/11/2020

Vehicle Num. : SJU 9712R

Make/Model : SUZUKI SWIFT SPORT

Chassis/Eng# :

Accident Date : 11/11/2020

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1SET	SPECIAL NETT ITEMS :		
2.	1SET	FRONT BUMPER CLIP <i>ner</i>		50.00 ✓
3.	1PC	N/S FRONT FENDER INNER SHIELD CLIP <i>ner</i>		50.00 ✓
4.	1PC	HORN BRACKET <i>11</i>		50.00 X <i>50</i>
5.	1PC	N/S FRONT RIM <i>Buf</i>		800.00 <i>450</i>
6.	2PCS	MICHELLIN PILOT SPORT 4 17 INCH <i>tyre 2P 250 50R S/N</i>	350.00 <i>125</i>	700.00 <i>475</i>
7.	1BTL	ENGINE OIL <i>11</i>		120.00 X
8.	1SET	DENSO HORN <i>11</i>		150.00 X
9.	1BTL	TRANSMISSION FLUID <i>11</i>		120.00 X
10.	1PC	N/S ROCKER PANEL SKIRT <i>D.S</i>		800.00 <i>500</i>
11.	1PC	N/S ROCKER PANEL SKIRT CLIP <i>ner</i>		50.00 ✓
12.	1PC	BONNET INSULATOR CLIP <i>ner</i>		50.00 <i>30</i>
13.	1PC	BONNET STICKER <i>11</i>		40.00 X
14.	1PC	BONNET SEALANT <i>11</i>		80.00 X
15.	1SET	N/S ENGINE UNDERCOVER CLIPS <i>nn</i>		50.00 X
16.	1PC	IU BRACKET <i>11</i>		26.00 X
17.	1BTL	FRT WS SEALANT <i>ner</i>		50.00 <i>40</i>
18.	1SET	FRT WINDSCREEN INNER SEAL <i>ner</i>		45.00 <i>30</i>
18.	1BTL	COOLANT <i>11</i>		35.00 X
Special Nett Total S\$:				3,266.00
LABOUR :				
TO CHECK LIGHT SYSTEM				50.00 <i>XNN</i>

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00, IOB BUILDING
SINGAPORE 049711

Attention : Motor Claim Department

Contact : 62238122 Fax No. : 62244174

Estimate : ES707786

Date : 11/11/2020
Vehicle Num. : SJU 9712R
Make/Model : SUZUKI SWIFT SPORT
Chassis/Eng# :
Accident Date : 11/11/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		COMPUTERIZED WHEEL ALIGNMENT	60	120.00
		ANTI-RUST	100	150.00
		TO APPLY BODY SEALANT ON BODY JOINTS	11 X	150.00
		TO REMOVE/REFIT DASHBOARD TO FACILITATE REPAIRS	200	300.00
		TO REMOVE/REFIT INNER TRIMS AND GARNISHES	11 X	180.00
		TO VACCUM, REOIL AND REGAS AIR CON	11 X	120.00
		TO RECONNECT BROKEN WIRES AND REPLACE FUSE BOX	80	250.00
		TO LIFT ENGINE, DROP GEARBOX TO FACILITATE REPAIRS	11 X	450.00
		TO REMOVE/REFIT FRT WINDSCREEN GLASS	✓	120.00
		TO REPLACE FRONT UNDERCARRIAGE	300	400.00
		TO CONDUCT CHASSIS ALIGNMENT	11 X	300.00
		TO PLUG IN DISGNOSTIC AND CLEAR CODES	11 X	250.00
		LABOUR/PANEL BEATING	1200	2,000.00
		TO PUTTY AND RESPRAY	1300	1,800.00
		Labour Total S\$:		6,640.00

E. & O.E.

Total S\$: 23,409.84

=====


for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

P - 6010.01
S/N - 1325
L - 3360
10685.01
201
8126.

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg