

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20012396/ETF3E2
Date: 17/11/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	ML000510
Claimant Vehicle No : SHA2110C	Insured Vehicle No :	SMP1874A
Date of Loss: 10/11/2020	Nature of Claim:	TP Claim No: M2005606

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2110C	Engine No:	G4LEKU296299
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU164519
Reg. Date:	02/07/2019 (Man. Year: 2019)	Odometer:	138516 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,138.04	2,706.12	1,431.92	34.60
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,390.00	800.00	590.00	42.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,539.04	3,517.12	2,021.92	36.50
+ GST 7.00/7.00% (S\$)	387.73	246.20	141.53	36.50
Nett Amount (S\$)	5,926.77	3,763.32	2,163.45	36.50

INSPECTION

Date of Assignment:	12/11/2020 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	11/11/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2020)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA2110C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT RH DOOR ASSY	Dented	1,797.20 FL	-	*1,797.20 FL
2	1		*REAR RH DOOR ASSY	Repair	1,789.90 FL	-	*- FL
3	1		*FRT RH SIDE MIRROR	Broken	1,391.70 FL	-	*1,391.70 FL
4	1		*FRT DOOR COMFORTDELGRO LOGO	Necessary	75.00 F	-	*75.00 FS
5	1		*REAR DOOR APPS AND TEL. NOS STICKER	Necessary	80.00 F	-	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,133.80	3,343.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	995.76	637.78

Total Parts (\$\$)	4,138.04	2,706.12
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	320.00
2	SPRAYPAINT	New	700.00	400.00
3	CHECK WIRING	New	50.00	30.00
4	TRANSFER DOOR PARTS	New	240.00	50.00
Gross Labour Cost (\$\$)			1,390.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >