



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI20012397/Etf3e2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 25-11-2020



Code : FCI2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9787L	Veh. Inspected	GBD 6851B
Policy No.		Coverage (\$)	0.00
Claim No.	D20004607MFSH	Excess (\$)	0.00
Assign From	CHRIS LIM	Assign Date	11/11/2020

#### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KDH2010149151	Colour	WHITE
Odometer	231340	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	BRIDGESTONE	4 mm
L/H Front Tyre	195 R15C	BRIDGESTONE	4 mm
R/H Rear Tyre	195 R15C	BRIDGESTONE	4 mm
L/H Rear Tyre	195 R15C	BRIDGESTONE	4 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	09/11/2020	Inspection Date	12/11/2020
Survey held at	MUN HOONG MOTOR TRADING BLK 5033 AMG MO KIO IND PK 2 #01-273 SINGAPORE 569537		

#### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------