



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2100382

INV Date 18/01/2021

Reference CC4/LPC20012398/R1ps3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. XE 3776P

Insured Veh. YK 8881S

Claim No. 20/20/20/VC00/023757

Policy No. Z/20/VC00/108041

Accident Date 09/10/2020

Inspection Date 12/11/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC20012398/R1ps3q2 Date: 18/01/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YK 8881S	Veh. Inspected	XE 3776P	
Policy No.	Z/20/VC00/108041	Coverage (\$)	0.00	
Claim No.	20/20/20/VC00/023757	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	12/11/2020	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FUSO FP51	c.c	11967	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	FP51SDA20243	Colour	RED	
Odometer	228725 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	AUSTONE	8 mm	
L/H Front Tyre	295/80 R22.5	AUSTONE	8 mm	
R/H Rear Tyre	295/80 R22.5 (D)	AUSTONE	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	AUSTONE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/10/2020	Inspection Date	12/11/2020	
Survey held at	NO.8 TUAS AVE 18			
Repairer	VENDA ENGINEERING & TRADING PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 3776P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	BENT	2,259.31	2,259.31
1	FRT BUMPER RIGHT REAR COVER	DEFORMED	140.29	140.29
1	FRT STEP LOWER GARNISH	CRACKED	595.11	595.11
1	FRT RIGHT FENDER	SCRATCHED	1,162.98	1,162.98
1	FRT RIGHT DOOR	BENT	3,064.73	3,064.73
1	FRT RIGHT DOOR LAMP	BROKEN	118.77	118.77
1	FRT HEADLAMP REAR AIR DUCT	SERVICEABLE	99.25	-
	LESS 25% DISCOUNT		-1,860.11	-1,835.30
			5,580.33	5,505.89
	<u>SPECIAL NETT ITEMS</u>			
1	COMPANY LOGO STICKER (SN)	NECESSARY	280.00	150.00
			280.00	150.00
	<u>LABOUR</u>			
	REMOVE & RENEW FRT BUMPER ,RIGHT DOOR ,STEP BRACKET ,RIGHT FENDER.		800.00	600.00
	TRANSFER PARTS.		120.00	80.00
	RENEW COMPANY LOGO STICKER .		80.00	40.00
	SPRAY PAINT FRT BUMPER ,RIGHT DOOR ,FENDER .		660.00	600.00
			1,660.00	1,320.00
	GRAND TOTAL		7,520.33	6,975.89
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,550.00

Report Ref No. CC4/LPC20012398/R1ps3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 3776P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 3776P

RE-INSPECTION

