



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: alex@carzauto.com.sg Tel: 65 6493 1924 Fax: 65 6493 1928

Insurance Company: **First Capital Insurance Ltd**
Motor Claims Department
 Address: 30 Robinson Road
 #10-01/02 Robinson Towers
 Singapore 048546
 Telephone: Fax:

Make/ Model : TOYOTA WISH Date: 10/11/2020
 Chassis No : ZNE10-0326963 Vehicle No: SGN 2817 R
 Date/Time of Accident : 28/10/2020 12:10

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR					
ITEMS	DESCRIPTION (LIST PARTS)	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	Tail Gate / pp.	1	\$ 1,145.60	25%	\$ 859.20
2	Tail Gate Windscreen Glass Moulding / Nec	4	\$ 263.60	200 25%	\$ 197.70
3	Tail Gate Logo / Nec	1	\$ 49.25	25%	\$ 36.94
4	Tail Gate Inner Lock / Jam	1	\$ 399.45	350 25%	\$ 299.59
5	Tail Gate Inner Trim Cover X SUC	1	\$ 408.20	X 25%	\$ 306.15
6	Tail Gate Weatherstrip / CRU.	1	\$ 219.40	25%	\$ 164.55
7	Tail Gate Shockabsorber X SUC	2	\$ 459.80	X 25%	\$ 344.85
8	Rear Bumper / CRU.	1	\$ 698.70	25%	\$ 524.03
9	Rear Bumper Side Retainer / BK	2	\$ 246.60	200 25%	\$ 184.95
10	Rear Bumper Bracket X SUC	2	\$ 249.10	X 25%	\$ 186.83
11	Rear Bumper Reflector / CRU.	2	\$ 158.40	25%	\$ 118.80
12	Rear Tail Lamp RH X SUC	1	\$ 408.25	X 25%	\$ 306.19
13	Rear Tail Lamp Lower Bracket RH X SUC	1	\$ 19.20	X 25%	\$ 14.40
14	Rear End Panel Inner Lower / pp	1	\$ 159.85	25%	\$ 119.89
15	Rear End Panel Outer / pp	1	\$ 430.65	25%	\$ 322.99
16	Rear End Panel Top Garnish X SUC	1	\$ 139.80	X 25%	\$ 104.85
17	Rear End Panel Top Board X SUC	1	\$ 208.90	X 25%	\$ 156.68
18	Rear Fender Splashield X SUC	2	\$ 333.36	X 25%	\$ 250.02
19	Rear Silencer Top Head Seal X SUC	1	\$ 159.95	X 25%	\$ 119.96
TOTAL LIST COST PRICE & AFTER DISCOUNT					\$ 4,618.55

3,618.55
 - 25%
 2,708.84

SPECIAL NETT ITEM					
SPECIAL ITEMS	DESCRIPTION (SPECIAL NETT PARTS)	QTY	PRICE \$		FINAL PRICE \$
1	Tail Gate Windscreen Sealant RH / Nec.	1	\$ 60.00		\$ 60.00
2	Rear No Plate X SUC	1	\$ 50.00		\$ 50.00
3	Rear Bumper Clip / NPC	10	\$ 65.00		\$ 650.00
4	Rear Reverse Sensor / splash.	1	\$ 280.00		\$ 280.00
TOTAL SPECIAL NETT ITEM					\$ 455.00

30
 30
 200
 260

Labour Works / Panel Beating Related Works

Job Scope	Quotation
TO REMOVE & RENEW REAR DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED PARTS	\$ 950.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 900.00

Labour Works

Job Scope	Quotation
TO REMOVE/ REFIX WIRING CHECKS	\$ 60.00

800
 600


30

COAT AFFECTED AREA	\$	100.00
REMOVE AND REFIX REAR WINDSCREEN	\$	120.00
TO REMOVE/ REFIX INTERIOR UPHOLSTERY	\$	100.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$	100.00
TO REMOVE AND REPLACE TAIL GATE MECHANISM	\$	100.00
OTHER LABOUR COST	\$	580.00

40
30
30
60
1,710

GRAND TOTAL \$ 7,503.55

Handwritten signature



CARZ AUTO SERVICES PTE LTD

Person Incharge: Mr Teric Chia
Job Title: Motor Claim
Mobile: 65 8725 4540
Email: teric@carzauto.com.sg

Repair day - 5 days

LIS After paintwork

Repair day -

Sun Pm (Lkk)

12/11/2020

TP without prejudice

2,708.89
260
1,710
4,678.89
- 20%
3,743.11

415
\$2,500

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____