

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SGS5402H
 MODEL : HONDA ACCORD
 DATE OF ACCIDENT : 10.11.20
 TIME OF ACCIDENT : 12:05HRS

28	REAR CHASSIS FRAME EXTENSION <i>Reps</i>	1	\$ 735.00	\$ 735.00	<i>+</i>
29	REAR SPARE TYRE BOLT <i>2</i>	1	\$ 23.40	\$ 23.40	<i>+</i>
30	REAR EXHAUST INSULATOR <i>1pc</i>	1	\$ 90.10	\$ 90.10	<i>+</i>
31	REAR EXHAUST MOUNTING <i>1pc</i>	4	\$ 39.40	\$ 157.60	<i>+</i>

5939.10
4751.28
 TOTAL PRICE \$ 9,315.70
 LESS 20% \$ 1,863.14
 SUB TOTAL PRICE \$ 7,452.56

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
2	REAR BUMPER CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
3	TAILLAMP CLIP (SET) <i>Neu</i>	1	\$ 40.00	\$ 40.00	<i>20</i>
4	TAILLAMP PANEL RH SEALANT <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
5	BOOTLID NUMBER PLATE LAMP GARNISH CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
6	BOOTLID INSULATOR CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	<i>+</i>
7	BOOTLID EMBLEM 'EURO R' (SPECIAL TYPE)	1	\$ 120.00	\$ 120.00	<i>60</i>
8	REAR FENDER SEALANT RH <i>Neu</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
9	REAR FENDER INNER TRIM CLIPS (SET) <i>2pc</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
10	REAR FENDER COWLING CLIP (SET) <i>1pc</i>	1	\$ 60.00	\$ 60.00	<i>+</i>
11	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
12	REAR END PANEL INSULATION SEAL <i>Neu</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
13	REAR FLOOR PANEL BOTTOM COVER CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
14	REAR FLOOR PANEL TOP BOARD (SPECIAL TYPE) <i>Neu</i>	1	\$ 380.00	\$ 380.00	<i>+</i>
15	REAR WINDSCREEN INNER SEAL <i>Neu</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
16	REAR WINDSCREEN SEALANT <i>Neu</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
17	REAR EXHAUST BOX (SPECIAL TYPE) <i>1pc</i>	1	\$ 1,800.00	\$ 1,800.00	<i>+</i>
18	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	<i>20</i>

450
 TOTAL \$ 3,560.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	<i>1200</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>1000</i>
3	TUFF COAT	\$ 250.00	<i>100</i>
4	WIRING CHECK	\$ 120.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 180.00	<i>80</i>

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SGS5402H
 MODEL : HONDA ACCORD
 DATE OF ACCIDENT : 10.11.20
 TIME OF ACCIDENT : 12:05HRS

6	CONDUCT WATER LEAKAGE TEST	\$ 100.00	+
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
8	REAR CHASSIS ALIGNMENT	\$ 250.00	+
9	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	+
11	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

2640

TOTAL \$5,140.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,012.56
 TOTAL LABOUR COST : \$ 5,140.00
 TOTAL REPAIR COST : \$ 16,152.56

Adrian Lij
 4/5 11/11/20.
 09 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

total: 7841.28

4/5: 6.2K

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: