

KARZ WORKS PTE LTD
53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934
(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

CHINA TAIPING

REPAIR PERFORMA INVOICE

Vehicle number	FBK4466G
Make / Model	LAMBRETTA V200
Chassis number	VDLLPB017JS003013
Accident date	9/11/20
Reference	KK2011-16

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT FAIRING panel	350.00 <i>cut</i> 300.
1	FRONT LH FAIRING CHROME GARNISH (MIDDLE)	120.00 <i>cut</i> 60
1	FRONT LH FAIRING CHROME GARNISH (BTM)	120.00 <i>cut</i> 60.
1	FRONT LH SIGNAL LAMP	95.00 <i>cut</i>
1	FRONT RH SIGNAL LAMP	95.00 <i>x nn</i>
1	FRONT FENDER	250.00 <i>cut</i> 150
* 1 SET	FRONT FORK	shifted 550.00 <i>R-R</i> 150 alignment
* 1	LH MIDDLE FAIRING	350.00 <i>cut</i> 200
1	LH MIDDLE FAIRING CHROME GARNISH	120.00 <i>cut</i> 60
1	HANDLE BAR	400.00 <i>x nn</i>
1	BRAKE LEVER <i>RH</i>	85.00 <i>cut</i> 45
1	GEAR LEVER <i>LH</i>	85.00 <i>x nn</i>
1 SET	BALANCER	120.00 <i>cut</i> 60
1 SET	WING MIRROR	150.00 <i>cut</i> 100
1	EXHAUST MUFFLER	600.00 <i>Rx</i>
1	EXHAUST CHROME COVER	280.00 <i>cut</i> 180
1	STAND	65.00 <i>x nn</i>
<i>RH chrome garnish middle cut -</i> <i>RH chrome garnish bottom cut -</i> <i>RH fender guard ddr</i> <i>RH pillion foot rest cut -</i>		3835.00 1310
Less 10 %		383.50 6% 1179.
Subtotal		3451.50
Balance C/F		3451.50
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	GEAR SHIT SHAFT OIL SEAL	24.00 <i>x nn</i>
2	FORK OIL SEAL	120.00 <i>? net</i>
1 BOT	FORK OIL	60.00 <i>? net</i>
1	REAR BOX	500.00 <i>x nn</i> 180
Subtotal		704.00
Balance C/F		4155.50
S/No	LABOUR AND MISCELLANEOUS CHARGES	
Balance B/F		4155.50
1	REPLACE , REALIGN AND ADJUST ABOVE DAMGE PARTS AND CHECK WIRING AND LIGHTNING SYSTEM	600.00 <i>200</i>
2	TO KNOCK, STRAIGHTEN CHASSIS AND BODY BALANCING	<i>nn</i> 380.00 <i>150? plus to</i>
3	TO REMOVE/REFIT, REPLACE FRONT FORK TUDES	180.00 <i>120</i>
4	SPRAY PAINTING	380.00 <i>200</i>
Subtotal		1540.00
Grand total		5695.50

Tanpin 97495949 'wp'
Lumpsum
Repair after repair
12/11/20 @ 3:55pm
5 days
Front fork alignment/pressing \$150
670.

KARZ WORKS PTE LTD
 53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
 SINGAPORE 408934
 (TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

CHINA TAIPING

REPAIR PERFORMA INVOICE

Vehicle number	FBK4466G
Make / Model	LAMBRETTA V200
Chassis number	VDLLPB017JS003013
Accident date	9/11/20
Reference	KK2011-16

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	RH CHROME GARNISH MIDDLE	cut 120.00 ✓ 60
1	RH CHROME GARNISH BTM	cut 120.00 ✓ 60
1	RH PILLION FOOTREST	cut 80.00 ✓
1	FRONT REPAIRING panel centre garnish 603	cut 350.00 ✓ 150
		670.00
	Less 10 %	67.00
	Subtotal	603.00
	Balance C/F	603.00
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	RH PROTECTION BAR 250	cut 250.00 ✓ 180 sw
	Subtotal	250.00
	Balance C/F	853.00

1179
 180.
 670
 315
 180
 2524
 2/5/2000 #
 0.5 days #