

Bifrost Auto Pte Ltd

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: 65 64524457 / Fax: +65 64524584

CO. Reg. No.: 201929175W

Model : **Nissan Teana 2.0 XL CVT**

Registration No : **SLE 7681 U**

Chassis No: **MNTBBAL33Z0005894**

Year of Manufacturing: **2016**

S/No	Qty	Items	Unit Price	Amount	
1	1	Bootlid X NN	\$ 1,124.50	\$ 1,124.50	
2	1	Bootlid Lock X NN	\$ 245.80	\$ 245.80	
3	1	Bootlid Lock Sensor X NN	\$ 154.40	\$ 154.40	
4	1	Bootlid Weatherstrip X NN	\$ 185.60	\$ 185.60	
5	1	Bootlid Centre Chrome Moulding X NN	\$ 394.70	\$ 394.70	
6	1	Bootlid Logo X NN	\$ 58.90	\$ 58.90	
7	1	Bootlid Emblem-Teana X NN	\$ 96.40	\$ 96.40	
8	1	Bootlid Emblem - 2.0 XL X NN	\$ 58.90	\$ 58.90	
9	1	Bootlid Embelm - Xtronic CVT X NN	\$ 94.50	\$ 94.50	
10	1	Bootlid Inner Trim X NN	\$ 212.40	\$ 212.40	
11	1	Tail Lamp (RH) X NN	\$ 670.50	\$ 670.50	
12	1	Tail Lamp Panel (RH) X NN	\$ 194.70	\$ 194.70	
13	1	Tail Lamp (LH) X NN	\$ 670.50	\$ 670.50	
14	1	Tail Lamp Panel (LH) X NN	\$ 194.70	\$ 194.70	
15	1	Rear Bumper ✓ DE	\$ 954.70	\$ 954.70 680	
16	1	Rear Bumper Retainer (RH) X NN	\$ 38.90	\$ 38.90	
17	1	Rear Bumper Retainer (LH) X NN	\$ 38.90	\$ 38.90	
18	1	Rear Bumper Bracket (RH) X NN	\$ 96.50	\$ 96.50	
19	1	Rear Bumper Bracket (LH) X NN	\$ 96.50	\$ 96.50	
20	1	Rear Reinforcement X NN	\$ 460.50	\$ 460.50	
21	1	Rear Bumper Sponge ✓ CRA	\$ 187.40	\$ 187.40 ✓	
22	1	End Panel X Repair	\$ 660.40	\$ 660.40	
23	1	End Panel Top Garnish X NN	\$ 154.20	\$ 154.20	
24	1	Spare Wheel Panel X NN	\$ 1,128.90	\$ 1,128.90	
25	1	Spare Wheel Board X NN	\$ 717.90	\$ 717.90	
26	1	Spare Wheel Sponge X NN	\$ 539.40	\$ 539.40	
				\$ 9,430.70	867.4
				-10% -20% \$ 1,886.14	
Total for spare parts				\$ 7,544.56	780.66

Special Nett

1	1	Rear Bumper Clip set	✓ NEC	\$	50.00	\$	50.00	30
2	1	End Panel Top Garnish Clip set	✗ NN	\$	50.00	\$	50.00	
3	1	Reverse Sensor set	✗ NN	\$	300.00	\$	300.00	
4	1	End Panel Sealant	✗ NN	\$	85.00	\$	85.00	
5	1	Tail Lamp Clip set	✗ NN	\$	30.00	\$	30.00	

Total for SP \$ 515.00
Sub-Total for Parts : \$ 8,059.56

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as- mention repair parts, inclusive of replacement parts.	\$	900.00 300
2		To putty and spray paint on all accident damage parts and other accident affected areas	\$	800.00 200
3		To check wiring system to facilitate repair and refit the same	\$	60.00 ✗ NN
4		Apply rust proofing on the adjacent panels	\$	80.00 ✗ NN
5		To supply under coating / putty on parts replaced	\$	50.00 ✗ NN
6		To perform water seepage test after repair	\$	80.00 ✗ NN
7		Remove and refit rear end panel lining and garnish to facilitate repair	\$	80.00 60
8		Remove and refit rear bumper sensor	\$	60.00 40

TOTAL AMOUNT : \$ 2,110.00 600
OVERALL COST: \$ 10,169.56

1410.66

-20%: 1100

3 Days

