

Kp

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES2090908/AMK

Date: 12 Nov 2020

Policy No: 5114404657

Veh Reg No: SMN4099L

Make/Model: HONDA FIT 1.3 GF CVT A

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 09/11/2020

TP Veh Reg No: SKT518M

Chassis No: GK33418264

Engine No: L13B3932754

Reg. Date: 07/08/2019

Not Authorized

Return By paint

18 days

Estimate Repair Cost to Vehicle No :SMN4099L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	<i>Bu/cm</i> 695.80	1 PC	695.80	✓
2 FRONT BUMPER REINFORCEMENT	223.00	1 PC	<i>CM</i> 223.00	✓
3 FRONT BUMPER AIR DUCT	19.50	2 PC	<i>CM</i> 39.00	✓
4 FRT BUMPER TOW COVER	17.10	1 PC	<i>CM</i> 17.10	✓
5 FRONT BUMPER RH FOG LAMP COVER	29.00	1 PC	<i>CM</i> 29.00	✓
6 FRONT BUMPER SIDE RETAINER	11.20	2 PC	<i>CM</i> 22.40	✓
7 FRONT BUMPER CENTRE LOWER GRILLE	180.00	1 PC	<i>CM</i> 180.00	✓
8 FRONT BUMPER CENTRE GRILLE SIDE GARNISH (RH)	12.80	1 PC	<i>CM</i> 12.80	✓
9 FRONT BUMPER CLIP	3.90	5 PC	<i>CM</i> 19.50	✓
10 BONNET	551.40	1 PC	<i>Bu</i> 551.40	✓
11 BONNET HINGE	28.00	2 PC	<i>CM</i> 56.00	✓
12 BONNET INNER LOCK	85.60	1 PC	<i>CM</i> 85.60	✓
✓ 13 BONNET CABLE	18.00	1 PC	<i>CM</i> 18.00	✓
14 BONNET INSULATOR	90.00	1 PC	<i>CM</i> 90.00	✓
15 BONNET STAND FOLDER	4.30	1 PC	<i>CM</i> 4.30	✓
16 BONNET INNER CENTRE RUBBER	22.00	2 PC	<i>CM</i> 44.00	✓
17 BONNET INNER SIDE RUBBER	10.20	2 PC	<i>CM</i> 20.40	✓
✓ 18 BONNET RH SIDE GARNISH	24.70	1 PC	<i>CM</i> 24.70	✓
19 FRONT GRILLE HOUSING	254.30	1 PC	<i>CM</i> 254.30	✓
20 FRONT GRILLE TOP CHROME	224.10	1 PC	<i>CM</i> 224.10	✓
21 FRONT GRILLE LOGO	27.40	1 PC	<i>CM</i> 27.40	✓
22 FRONT GRILLE OUTER LOWER CHROME	202.80	1 PC	<i>CM</i> 202.80	✓
23 FRONT GRILLE INNER TOP GARNISH	15.40	1 PC	<i>CM</i> 15.40	✓
24 FRONT GRILLE INNER TOP GARNISH CLIP	3.80	2 PC	<i>CM</i> 7.60	✓
25 HEADLAMP	<i>o/s CM</i> 895.00	2 PC	<i>CM</i> 1,790.00	✓
26 HEADLAMP LOWER BRACKET	35.00	2 PC	<i>CM</i> 70.00	✓
27 FRONT FENDER	483.50	2 PC	<i>Bu</i> 967.00	✓
✗ 28 FRONT FENDER INNER SHIELD	71.50	2 PC	<i>CM</i> 143.00	✗
✗ 29 FRONT FENDER INNER SHIELD CLIP	3.80	12 PC	<i>CM</i> 45.60	✗
30 FRONT RH FENDER EXTENSION ARM	150.00	1 PC	<i>CM</i> 150.00	✓
31 FRONT FENDER TOP BRACKET	49.00	2 PC	<i>CM</i> 98.00	✓
32 FRT SUPPORT PANEL	455.00	1 PC	<i>Bu</i> 455.00	✓
33 FRONT SUPPORT PANEL LH AIR DUCT	39.50	1 PC	<i>CM</i> 39.50	✓
34 FRONT SUPPORT PANEL LOWER AIR DUCT	24.80	1 PC	<i>CM</i> 24.80	✓
35 AIR-CON CONDENSER	811.00	1 PC	<i>CM</i> 811.00	✓
✓ 36 AIR-CON CONDENSER LIQUID PIPE	175.00	1 PC	<i>CM</i> 175.00	✓
✓ 37 AIR-CON CONDENSER SUCTION HOSE	178.00	1 PC	<i>CM</i> 178.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 09/11/2020

TP Veh Reg No: SKT518M

Estimate No: ES2090908/AMK

Date: 12 Nov 2020

Policy No: 5114404657

Veh Reg No: SMN4099L

Make/Model: HONDA FIT 1.3 GF CVT
 A

Chassis No: GK33418264

Engine No: L13B3932754

Reg. Date: 07/08/2019

Estimate Repair Cost to Vehicle No :SMN4099L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
✓38 AIR-CON CONDENSER DISCHARGE HOSE	210.00	1 PC	210.00	✓
✓39 AIR-CON COMPRESSOR	1,780.50	1 PC	1,780.50	✓
40 RADIATOR	1,250.80	1 PC	1,250.80	✓
41 RADIATOR SPARE TANK	40.00	1 PC	40.00	✓
42 RADIATOR FAN COWLING	125.00	1 PC	125.00	✓
✓43 RADIATOR FAN MOTOR	326.00	1 PC	326.00	✓
✓44 RADIATOR FAN BLADE	78.00	1 PC	78.00	✓
45 RADIATOR RH SIDE GARNISH	17.50	1 PC	17.50	✓
✓46 AIR FILTER HOUSING ASSY	227.00	1 PC	227.00	✓
✗47 AIR RESONATOR TUBE	40.60	1 PC	40.60	✗
✗48 FRONT RH ENGINE MOUNTING	170.80	1 PC	170.80	✗
✗49 FRONT LH ENGINE MOUNTING	260.00	1 PC	260.00	✗
✓50 ENGINE INTAKE MANIFOLD	389.40	1 PC	389.40	✓
51 DASHBOARD ASSY	718.50	1 PC	718.50	✓
52 PASSENGER FRT AIR BAG	2,236.80	1 PC	2,236.80	✓
53 STEERING AIRBAG	1,605.80	1 PC	1,605.80	✓
54 STEERING SPIRAL CABLE	289.30	1 PC	289.30	✓
55 AIR BAG ECU	846.70	1 PC	846.70	✓
56 FRONT RH AIRBAG SENSOR	157.10	1 PC	157.10	✓
57 FRONT SEAT BELT	486.00	2 PC	972.00	✓
58 FRONT SEAT BELT LOWER CENTRE GARNISH	60.50	2 PC	121.00	✓
59 WIPER WASHER TANK	75.00	1 PC	75.00	✓
✗60 WIPER WASHER NECK	19.00	1 PC	19.00	✗
61 REAR BUMPER	693.50	1 PC	693.50	✓
✗62 REAR BUMPER RH SIDE GARNISH	48.00	1 PC	48.00	✗
63 REAR BUMPER RH SIDE RETAINER	16.90	1 PC	16.90	✓
64 REAR BUMPER CLIP	3.90	5 PC	19.50	✓
65 RH TAILLAMP	244.60	1 PC	244.60	✓
✓66 TAILGATE INNER RUBBER	92.30	1 PC	92.30	✓
67 TAILGATE INNER LOCK	157.10	1 PC	157.10	✓
68 TAILGATE EMBLEM 'FIT'	35.00	1 PC	35.00	✓
69 TAILGATE WINDSCREEN GLASS MOULDING	108.10	1 SET	108.10	✓
70 REAR END PANEL	328.60	1 PC	328.60	✓
71 REAR END PANEL INNER TOP GARNISH	60.80	1 PC	60.80	✓
72 REAR TAILGATE	950.00	1 PC	950.00	✓
			22,522.70	
			Less 20%	4,504.54
				18,018.16

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 09/11/2020

TP Veh Reg No: SKT518M

Estimate No: ES2090908/AMK

Date: 12 Nov 2020

Policy No: 5114404657

Veh Reg No: SMN4099L

Make/Model: HONDA FIT 1.3 GF CVT
 A

Chassis No: GK33418264

Engine No: L13B3932754

Reg. Date: 07/08/2019

Estimate Repair Cost to Vehicle No :SMN4099L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Special Net				
73 FRONT NUMBER PLATE	35.00	1 PC	CM 35.00	25m
74 COOLANT	35.00	1 PC	na 35.00	✓
75 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	na 40.00	✓
76 REVERSE SENSOR	200.00	1 PC	per 200.00	✓
			310.00	310.00
Labour				
77 TOWING (FROM TRAFFIC POLICE COMPOUND TO AMK)	50.00	1 LA	50.00	✓
78 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
79 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,BONNET & ATTACHMENTS,HEADLAMPS,BOTH FENDERS;TO CUT,WELD & RENEW FRT SUPPORT PANEL;STRAIGHTEN,KNOCKING & REPAIR FRT CHASSIS FRAMES & REALIGN THE SAME	1,200.00	1 LA	1,200.00	1000
80 PUTTY & RESPRAY FRT BUMPER,BONNET,BOTH FENDERS,FENDER EXTENSION ARM,FRT SUPPORT PANEL,FRT CHASSIS FRAMES,FRT RH DOOR & ALL AFFECTED AREAS	1,100.00	1 LA	1,100.00	1000
81 REMOVE & REFIX FRT DASHBOARD TO FACILITATE REPAIR	250.00	1 LA	250.00	✓
82 REMOVE & REFIX AIRBAG ECU,FRT SEAT BELTS,STEERING & PASSENGER AIRBAG & RESET FAULT CODE	250.00	1 LA	250.00	✓
83 REMOVE & REFIX ENGINE ASSY,GEARBOX ASSY,ENGINE INTAKE MANIFOLD,ENGINE MOUNTINGS & REALIGN THE SAME	350.00	1 LA	350.00	600
84 REMOVE & REFIX REAR BUMPER & ATTACHMENTS,TAILGATE & ATTACHMENTS,TAILLAMP;TO CUT,WELD & RENEW REAR END PANEL;KNOCKING & REPAIR REAR RH FENDER & REALIGN THE SAME	800.00	1 LA	800.00	500-600 500
85 PUTTY & RESPRAY REAR BUMPER & PARKING SENSORS,TAILGATE,REAR END PANEL,REAR RH FENDER & ALL AFFECTED AREAS	700.00	1 LA	700.00	600
86 REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION	50.00	1 PC	50.00	✓
87 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
88 RUSTPROOFING	150.00	1 LA	150.00	✓
89 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	✓
			5,370.00	5,370.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 09/11/2020
TP Veh Reg No: SKT518M

Estimate No: ES2090908/AMK
Date: 12 Nov 2020
Policy No: 5114404657
Veh Reg No: SMN4099L
Make/Model: HONDA FIT 1.3 GF CVT
A
Chassis No: GK33418264
Engine No: L13B3932754
Reg. Date: 07/08/2019

Estimate Repair Cost to Vehicle No :SMN4099L

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			Total	S\$ 23,698.16
			Add GST @ 7%	1,658.87
			Total Amount Payable	<u>S\$ 25,357.03</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 09/11/2020
TP Veh Reg No: SKT518M

Estimate No: ES2090908/AMK
Date: 16 Nov 2020
Policy No: 5114404657
Veh Reg No: SMN4099L
Make/Model: HONDA FIT 1.3 GF CVT
A
Chassis No: GK33418264
Engine No: L13B3932754
Reg. Date: 07/08/2019

Estimate Repair Cost to Vehicle No :SMN4099L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 OIL COOLER	202.80	1 PC	202.80	✓
2 BATTERY TRAY	18.20	1 PC	18.20	✓
3 BATTERY COVER	14.00	1 PC	14.00	✓
			235.00	
		Less 20%	47.00	188.00
Special Net				
4 BATTERY	160.00	1 PC	160.00	✓
			160.00	160.00
Total				S\$ 348.00
GST Amount				S\$ 24.36
Total Amount Payable				S\$ 372.36

For Cheng Hoe Motor Pte Ltd

Dorlyn LA

AUTHORISED SIGNATURE