

Date: 10.11.2020  
Vehicle No: SLE4832X  
Model: TOYOTA AQUA HYBRID 1.5S  
Chassis: NHP102520159-2016  
Reg.Year: 2016

Third Party Insurer: MS FIRST CAP  
Third Party Veh No: SHB3137P  
Date of Accident: 08.11.2020

*Not Authorised*

*12 days Repair After Paint*

## ESTIMATE

| NO. | DESCRIPTION                             | QTY | UNIT S\$ | AMOUNT S\$      |        |
|-----|-----------------------------------------|-----|----------|-----------------|--------|
| 1   | FRONT BONNET                            | 1   |          | Bz \$760.20     | ✓      |
| 2   | FRONT BONNET INSULATOR                  | 1   |          | Sm \$241.30     | X      |
| 3   | FRONT BONNET INSULATOR CLIPS            | 5   | \$5.50   | Nm \$44.00      | ✓      |
| 4   | FRONT BONNET HINGE LH                   | 1   |          | R \$65.30       | X      |
| 5   | FRONT BONNET HINGE RH                   | 1   |          | Dir \$65.30     | ✓      |
| 6   | FRONT WIPER AIR GRILLE GARNISH COVER RH | 1   |          | Rm \$67.80      | X      |
| 7   | FRONT HEADLAMP RH                       | 1   |          | Bz \$1,374.30   | ✓      |
| 8   | FRONT BUMPER                            | 1   |          | CM \$936.50     | ✓      |
| 9   | FRONT BUMPER CLIPS                      | 8   | \$5.80   | Nm \$46.40      | ✓      |
| 10  | FRONT BUMPER SIDE BRACKET RH            | 1   |          | mi \$57.60      | ✓      |
| 11  | FRONT BUMPER FOG LAMP RH                | 1   |          | CM \$228.30     | ✓      |
| 12  | FRONT BUMPER FOG LAMP GARNISH COVER RH  | 1   |          | mi \$60.90      | ✓      |
| 13  | FRONT FENDER RH                         | 1   |          | Bz \$501.40     | ✓      |
| 14  | FRONT FENDER "HYBRID" EMBLEM RH         | 1   |          | Nm \$47.60      | ✓      |
| 15  | FRONT FENDER INNER SHIELD RH            | 1   |          | CM \$216.90     | ✓      |
| 16  | FRONT FENDER INNER SHIELD CLIPS RH      | 8   | \$5.80   | Nm \$46.40      | ✓      |
| 17  | FRONT QUARTER GLASS GARNISH COVER RH    | 1   |          | mi \$48.40      | ✓      |
| 18  | FRONT SUPPORT UPPER PANEL RH            | 1   |          | Bz \$69.30      | ✓      |
| 19  | SIDE FRAME INNER PANEL RH               | 1   |          | Dir \$76.80     | ✓      |
| 20  | SIDE FRAME OUTER PANEL RH               | 1   |          | Bz \$85.20      | ✓      |
| 21  | FRONT WIPER WASHER TANK                 | 1   |          | Nm \$219.30     | ✓      |
| 22  | FRONT FUSE BOX ASSY                     | 1   |          | \$468.70        | ?      |
| 23  | FRONT WHEEL CAP RH                      | 1   |          | Red/Gr \$180.30 | ✓      |
| 24  | FRONT LOWER ARM RH                      | 1   |          | \$457.80        | ?      |
| 25  | FRONT KNUCKLE ARM RH                    | 1   |          | \$594.60        | ?      |
| 26  | FRONT WHEEL BEARING RH                  | 1   |          | \$168.90        | ?      |
| 27  | FRONT ABSORBER RH                       | 1   |          | \$463.20        | ?      |
| 28  | FRONT TIE ROD END RH                    | 1   |          | \$154.70        | ?      |
| 29  | REAR TAILGATE                           | 1   |          | Bz \$1,131.90   | ✓      |
| 30  | REAR TAILGATE "AQUA" EMBLEM             | 1   |          | Nm \$78.20      | ✓      |
| 31  | REAR TAILGATE "HYBRID" EMBLEM           | 1   |          | Nm \$76.50      | ✓      |
| 32  | REAR TAILGATE LOGO EMBLEM               | 1   |          | Nm \$68.80      | ✓      |
| 33  | REAR TAILGATE INNER LOCK                | 1   |          | Nm \$467.10     | ✓      |
| 34  | REAR TAILGATE RUBBER                    | 1   |          | CA \$335.70     | 507.50 |
| 35  | REAR WINDSCREEN MOULDING                | 1   |          | na Nm \$185.70  | X      |
| 36  | REAR BUMPER                             | 1   |          | Bz \$848.70     | ✓      |

Head office  
5 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1213 | Fax: (+65) 6472 2112

Branch  
8A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 0010 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)  
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10.11.2020  
Vehicle No: SLE4832X  
Model: TOYOTA AQUA HYBRID 1.5S  
Chassis: NHP102520159-2016  
Reg.Year: 2016

Third Party Insurer: MS FIRST CAP  
Third Party Veh No: SHB3137P  
Date of Accident: 08.11.2020

|             |                                   |   |        |    |             |   |
|-------------|-----------------------------------|---|--------|----|-------------|---|
| 37          | REAR BUMPER CLIPS                 | 8 | \$5.80 | Ar | \$46.40     | ✓ |
| 38          | REAR BUMPER SIDE BRACKET LH       | 1 |        | Di | \$64.40     | ✓ |
| 39          | REAR BUMPER SIDE BRACKET RH       | 1 |        | Di | \$64.40     | ✓ |
| 40          | REAR BUMPER UNDER COVER           | 1 |        |    | \$189.60    | ? |
| 41          | REAR BUMPER REINFORCEMENT         | 1 |        | Ar | \$590.60    | ✓ |
| 42          | REAR END PANEL                    | 1 |        | Ar | \$650.30    | ✓ |
| 43          | REAR END PANEL UPPER COVERING     | 1 |        | Di | \$284.50    | ✓ |
| 44          | REAR SPARE TYRE PANEL             | 1 |        |    | \$698.40    | ? |
| 45          | REAR SPARE TYRE PANEL UPPER BOARD | 1 |        | Ar | \$245.80    | ✓ |
| 46          | FRONT DOOR RH                     | 1 |        |    | REPAIR      |   |
| SUB TOTAL   |                                   |   |        |    | \$13,774.40 |   |
| LESS 25%    |                                   |   |        |    | -\$3,443.60 |   |
| PARTS TOTAL |                                   |   |        |    | \$10,330.80 |   |

| NO. | SPECIAL NETT                 | QTY | UNIT S\$  | AMOUNT S\$    |
|-----|------------------------------|-----|-----------|---------------|
| 1   | REAR WINDSCREEN SEALANT      | 1   |           | Ar \$80.00    |
| 2   | REAR BUMPER REVERSE SENSOR   | 1   |           | Shan \$350.00 |
| 3   | REAR END PANEL JOINT SEALANT | 1   |           | Ar \$30.00    |
| 760 |                              |     |           |               |
|     |                              |     | S/N TOTAL | \$460.00      |

### LABOUR CHARGES:

|                                                                                                                                                                       |            |      |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------|
| LABOUR CHARGES TO REPAIR, REMOVE, REPLACE, REFIX & READJUST FRONT & REAR ACCIDENT AREAS & ETC.                                                                        | \$1,000.00 | ✓    |
| LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT DOOR RH, REAR TAILGATE, REAR BUMPER & ETC. | \$1,400.00 | ✓    |
| LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT ABSORBER RH, FRONT LOWER ARM RH, FRONT KNUCKLE ARM RH & ETC.                                                           | \$200.00   | ?    |
| TO WHEEL ALIGNMENT & BALANCING.                                                                                                                                       | \$60.00    | ✓    |
| LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCSCREEN SEALANT & ETC. TO EFFECT REPLACE OF REAR TAILGATE.                | \$150.00   | 120L |

Head office  
6 Kung Chong Road Singapore 150143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch  
9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 0010 | Fax: (+65) 6481 1003

Branch (Motor Insurance Claims)  
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6461 1522 | Fax: (+65) 6461 1011



Date: 10.11.2020  
Vehicle No: SLE4832X  
Model: TOYOTA AQUA HYBRID 1.5S  
Chassis: NHP102520159-2016  
Reg.Year: 2016

Third Party Insurer: MS FIRST CAP  
Third Party Veh No: SHB3137P  
Date of Accident: 08.11.2020

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR TAILGATE. \$120.00 601

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER. \$100.00 501

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$80.00 401

LABOUR TOTAL \$3,110.00

TingAn TOTAL \$13,900.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before any spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 0010 | Fax: (+65) 6481 1003

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 569047  
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011

