

Rasul (LKKAuto)

From: Francis Ong <daihaauto@gmail.com>
Sent: Tuesday, 17 November, 2020 11:37 AM
To: Rasul (LKKAuto)
Subject: Estimates for SGL8119T

Hi Rasul,

Per our whatsapp communication, do find estimates per above captioned. Thanks!

Accident Date: 03-Nov-2020

Accident Vehicle: SGL 8119 T

Estimates

S/no.	Description	Value (excl. GST)
01	Rear Bumper - x 01 pcs <i>de</i>	\$ 1,185.00
02	Rear Bumper - x 10 pcs <i>clips ne</i>	\$ 60.00
03	Bootlid - x 01 pcs <i>repair</i>	\$ 1,879.80 X
	Subtotal	\$ 3,124.80
04	Labour	\$ 480.00 <i>3.00</i>
05	Putty and Spraypaint	\$ 480.00 <i>4.00</i>
06	Check electrical	\$ 50.00 X
07	Tuff Kote	\$ 50.00 X
08	Remove and re-fit rear bumpers sensors	\$ 100.00 <i>60</i>
09	Rewire rear portion	\$ 50.00 X
10	Remove and refit bootlid components	\$ 100.00 <i>60</i>
11	Diagnose and reset code using diagnostic equipments	\$ 200.00 X

Overall \$ 4,634.80

Cheers!

BR
Francis Ong

大發汽車修理廠
DAIHA AUTO SERVICE
1004 Bukit Merah Lane 3
#01-27 Singapore 159720

Mobile: +65 9877 7225
Email: daihaauto@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
3 days
9/p
12/11/2020 @ 1610
Resurvey before paint