

Veron Chen (LKKAUTO)

From: Francis Ong <daihaauto@gmail.com>
Sent: Tuesday, 17 November 2020 11:37 AM
To: Rasul (LKKAUTO)
Subject: Estimates for SGL8119T

Hi Rasul,

Per our whatsapp communication, do find estimates per above captioned. Thanks!

Accident Date: 03-Nov-2020

Accident Vehicle: SGL 8119 T

Estimates

S/no.	Description	Value (excl. GST)
01	Rear Bumper - x 01 pcs	\$ 1,185.00
02	Rear Bumper - x 10 pcs	\$ 60.00
03	Bootlid - x 01 pcs	\$ 1,879.80
	Subtotal	\$ 3,124.80
04	Labour	\$ 480.00
05	Putty and Spraypaint	\$ 480.00
06	Check electrical	\$ 50.00
07	Tuff Kote	\$ 50.00
08	Remove and re-fit rear bumpers sensors	\$ 100.00
09	Rewire rear portion	\$ 50.00
10	Remove and refit bootlid components	\$ 100.00
11	Diagnose and reset code using diagnostic equipments	\$ 200.00
	Overall	\$ 4,634.80

Cheers!

BR
Francis Ong

大發汽車修理廠
DAIHA AUTO SERVICE
1004 Bukit Merah Lane 3
#01-27 Singapore 159720

Mobile: +65 9877 7225
Email: daihaauto@gmail.com