

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ABDUL HAMID BIN MOHAMED NOOR
BLK 123 PENDING ROAD
#02-52
S 670123

TP ConPac
GE 61164778

Vehicle No :SJQ 3845 B
Make/Model :HONDA FIT
Accident date :10.11.2020

Xiao Tony.

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear windscreen moulding <i>New</i>	1	\$ 79.50 ✓
2	Tailgate <i>Distorted</i>	1	\$ 966.00 845.
3	Tailgate dampers @ \$131.50 <i>new</i>	2	\$ 263.00 X
4	Tailgate hinges @ \$68.50 <i>new</i>	2	\$ 137.40 X
5	Tailgate inner trim board <i>crackd.</i>	1	\$ 254.50 ✓
6	Tailgate inner lock <i>Jammed.</i>	1	\$ 183.50 ✓
7	Tailgate inner catch <i>Norm</i>	1	\$ 42.60 X
8	Tailgate outer handle <i>at</i>	1	\$ 154.10 ✓
9	Tailgate H emblem <i>New</i>	1	\$ 45.00 ✓
10	Tailgate Fit emblem	1	\$ 48.50 ✓
11	Tailgate inner pull pocket <i>Dehd</i>	1	\$ 85.60 35.
12	Rear taillamp @ \$526.10 <i>crackd.</i>	2	\$ 1,052.20 570.
13	Rear taillamp panel @ \$438.00 <i>LH Distorted</i>	2	\$ 876.40 146.
14	Rear tailgate cable <i>new</i>	1	\$ 34.00 X
15	Rear end panel <i>Distorted</i>	1	\$ 553.40 356.70
16	Rear end panel inner garnish <i>Dehd</i>	1	\$ 213.40 116.20
17	Rear bumper <i>Distorted</i>	1	\$ 660.90 483.20
18	Rear bumper bracket @ \$32.70 <i>new</i>	2	\$ 65.40 ✓
19	Rear bumper clips (1 set) <i>new</i>	1	\$ 35.00 ✓
20	Rear bumper towing hook cover <i>Distorted</i>	1	\$ 38.50 ✓
21	Rear windscreen <i>shattered</i>	1	\$ 754.20 ✓
22	Rear wiper arm <i>at</i>	1	\$ 49.50 ✓
23	Rear wiper arm cover <i>crackd</i>	1	\$ 30.00 ✓
24	Rear wiper motor <i>Dryd</i>	1	\$ 261.80 ✓
25	Rear fender quarter glass rubber @ \$40.20 <i>LH new</i>	2	\$ 80.40 40.20
26	Rear fender @ \$717.70 <i>LH Buckleed</i>	2	\$ 1,435.40 717.70
27	Rear fender inner side garnish @ \$335.60 <i>Dehd.</i>	2	\$ 671.20 568.40
28	Rear fender inner side top garnish @ \$275.00 <i>Dehd</i>	2	\$ 550.00 390.
29	Rear spare tyre top board <i>Dehd</i>	1	\$ 290.40 ✓
30	Rear spare tyre well panel <i>Buckleed</i>	1	\$ 965.00 737.
31	Rear spare tyre well insulation @ \$209.80 <i>new</i>	3	\$ 629.40 X
32	Rear spare tyre sponge <i>Dehd</i>	1	\$ 242.50 ✓
33	Rear spare tyre side panel @ \$105.20 <i>tyr</i>	2	\$ 210.40 X
34	Rear RH chassis frame <i>Rejis</i>	1	\$ 165.00 X

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ABDUL HAMID BIN MOHAMED NOOR
BLK 123 PENDING ROAD
#02-52
S 670123

Vehicle No :SJQ 3845 B
Make/Model :HONDA FIT
Accident date :10.11.2020

No	DESCRIPTION	Qty	Amount (\$S)
35	Rear exhaust pipe <i>Bent</i>	1	\$ 1,800.00 <i>1250(SN)</i>
36	Rear exhaust pipe mounting @ \$32.40 <i>new</i>	2	\$ 64.80 <i>x</i>
37	Rear exhaust cover <i>cracked</i>	1	\$ 40.80 <i>✓</i>
38	Rear number plate lamp @ \$45.00 <i>new</i>	2	\$ 90.00
39	Front bonnet <i>cracked</i>	1	\$ 1,600.00 <i>1250(SN)</i>
40	Front bonnet hinges @ \$34.50 <i>new</i>	2	\$ 69.00 <i>+</i>
41	Front bonnet lock <i>new</i>	1	\$ 99.70 <i>x</i>
42	Front grille <i>cracked</i>	1	\$ 175.30 <i>✓</i>
43	Front grille emblem <i>new</i>	1	\$ 35.00 <i>✓</i>
44	Front grille clips (1 set) <i>new</i>	1	\$ 60.00 <i>20</i>
45	Front susport panel <i>Repair</i>	1	\$ 450.00 <i>x</i>
46	Front bumper <i>Distorted</i>	1	\$ 578.00 <i>✓</i>
47	Front bumper side holder @ \$23.70 <i>new</i>	2	\$ 47.40 <i>✓</i>
48	Front bumper lower centre grille <i>Del'd</i>	1	\$ 114.80 <i>✓</i>
49	Front bumper towing hook cover <i>Missing</i>	1	\$ 30.00 <i>✓</i>
50	Front bumper reinforcement <i>Bent</i>	1	\$ 280.00 <i>✓</i>
51	Front bumper bracket @ \$30.40 <i>new</i>	2	\$ 60.80 <i>+</i>
52	Front bumper clips (1 set) <i>new</i>	1	\$ 60.00 <i>30</i>
53	Front headlamp @ \$643.50 <i>cracked</i>	2	\$ 1,287.00 <i>✓</i>
54	Front headlamp lower bracket @ \$30.50 <i>cracked</i>	2	\$ 61.00 <i>✓</i>
55	Aircond condenser <i>Bent</i>	1	\$ 846.00 <i>✓</i>
56	Radiator <i>new</i>	1	\$ 1,525.00 <i>x</i>
			\$ 21,498.70
		Less 20% Disc	\$ 4,299.74
		Total	\$ 17,198.96

11083-10

8866-48

S N 2500

Special Nett Items

1	Front number plate <i>Bent</i>	\$ 50.00 <i>30</i>
2	Front number plate holder <i>Del'd</i>	\$ 50.00 <i>30</i>
3	Rear number plate <i>Bent</i>	\$ 50.00 <i>30</i>
4	Rear number plate holder <i>del'd</i>	\$ 50.00 <i>30</i>
5	Rear bumper sensor (1 set) <i>Damaged</i>	\$ 380.00 <i>2w</i>
	Total	\$ 580.00

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ABDUL HAMID BIN MOHAMED NOOR
BLK 123 PENDING ROAD
#02-52
S 670123

Vehicle No :SJQ 3845 B
Make/Model :HONDA FIT
Accident date :10.11.2020

No	Description	Qty	Amount (\$\$)
Labour Cost			
1	To supply rear end panel sealant		\$ 200.00 ⁶⁰
2	To supply rear windscreen sealant		\$ 100.00 ⁶⁰
3	Remove & reinstall rear windscreen & quarter glass		\$ 300.00 ¹⁶⁰
4	Remove & reinstall roof lining & cushion		\$ 300.00 ²⁰⁰
5	Remove & reinstall reverse sensor		\$ 150.00 ⁵⁰
6	Remove & reinstall petrol tank		\$ 150.00 ⁸⁰
7	Remove & reinstall air con fill in gas		\$ 150.00 ¹²⁰
8	Remove, replace & repair consistent to the accident	4580	\$ 2,200.00 ²⁰⁰⁰
9	Respray painting		\$ 1,800.00 ✓
10	Tuff kote		\$ 50.00 ✓
	Total		\$ 5,400.00
	Grand Total		\$ 23,178.96

Total: 16266.48
L/s: 13k

17 Days.

13k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: