

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20012420/AGA3Q2
Date: 13/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900018567
Claimant Vehicle No :	SMS4512J	Insured Vehicle No :	SDV8298S
Date of Loss:	10/11/2020	Nature of Claim:	TP
		Claim No:	3691547178SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS4512J	Engine No:	G4FGKU471568
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Chassis No:	KMHD841CMLU008570
Reg. Date:	27/02/2020 (Man. Year: 2019)	Odometer:	13473 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,146.64	8,755.52	6,391.12	42.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,299.20	2,840.00	3,459.20	54.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,445.84	11,595.52	9,850.32	45.93
Approved Total (Overridden) (S\$)		9,200.00		

Adjuster Report

	(S\$)	21,445.84	9,200.00	12,245.84	57.10
	+ GST 7.00/7.00% (S\$)	1,501.21	644.00	857.21	57.10
	Nett Amount (S\$)	22,947.05	9,844.00	13,103.05	57.10
	+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
	+ Doc/Search Fee (S\$)		7.45		
	Nett Liability (S\$)		10,851.45		

INSPECTION

Date of Assignment: 12/11/2020

Date Inspected: 12/11/2020

Inspected At:

Cas Garage Pte Ltd (HQ)
 No.1, Kaki Bukit Ave 6, #02-22 Autobay
 Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Distorted	1,853.60 FL	*1,853.60 FL
2	1		*REAR BOOTLID INNER LOCK	Jammed	185.70 FL	*185.70 FL
3	1		*REAR BOOTLID SMARTKEY ANTENNA	Not Necessary	197.50 FL	*- FL
4	1		*REAR BOOTLID INNER TRIM	Deformed	235.40 FL	*235.40 FL
5	1		*REAR BOOTLID LATCH	Bent	38.50 FL	*38.50 FL
6	1		*REAR BOOTLID LOGO	Necessary	93.60 FL	*93.60 FL
7	1		*REAR BOOTLID AVANTE EMBLEM	Necessary	98.70 FL	*98.70 FL
8	2		*REAR NUMBER PLATE LAMPS	Damaged (1 PCS ONLY)	197.40 FL	*98.70 FL
9	2		*REAR BOOTLID LAMPS	Cut	997.40 FL	*997.40 FL
10	1		*REAR BOOTLID WEATHERSTRIP	Cut	165.30 FL	*165.30 FL
11	1		*END PANEL	Distorted	657.80 FL	*657.80 FL
12	1		*END PANEL TOP GARNISH	Deformed	175.90 FL	*175.90 FL
13	1		*END PANEL BOOT REFLEASE ANTENNA	Not Necessary	185.90 FL	*- FL
14	2		*TAILAMPS	Cracked	1,516.40 FL	*1,516.40 FL
15	2		*TAILAMPS PANEL	Buckled	491.20 FL	*491.20 FL
16	1		*REAR BUMPER	Distorted	675.10 FL	*459.00 FL
17	1		*REAR BUMPER NUMBER PLATE GARNISH	Missing	98.50 FL	*98.50 FL
18	1		*REAR BUMPER LOWER	Distorted	496.30 FL	*496.30 FL
19	1		*REAR BUMPER LOWER COVER LH	Not Necessary	197.80 FL	*- FL
20	1		*REAR BUMPER LOWER COVER RH	Not Necessary	185.20 FL	*- FL
21	2		*REAR BUMPER RETAINERS	Necessary	171.80 FL	*171.80 FL
22	2		*REAR BUMPER REFLECTOR	Cut	513.60 FL	*513.60 FL
23	1		*REAR BUMPER REINFORCEMENT	Distorted	398.70 FL	*295.00 FL
24	1		*REAR REVERSE SENSORS HARDNESS	Not Necessary	198.60 FL	*- FL
25	3		*REINFORCEMENT BRACKET (BOTTOM)	Damaged	257.70 FL	*60.00 FL
26	2		*REINFORCEMENT BRACKET (TOP)	Damaged	164.80 FL	*40.00 FL
27	2		*REINFORCEMENT BRACKETS METAL	Bent	453.00 FL	*453.00 FL
28	2		*REAR FENDER	Repair	3,571.80 FL	*- FL
29	2		*REAR FENDER INNER TRIM	Not Necessary	579.20 FL	*- FL
30	2		*REAR FENDER INNER COWLING	Not Necessary	370.20 FL	*- FL
31	2		*REAR FENDER AIR DUCTS	Not Necessary	197.00 FL	*- FL
32	1		*REAR SILENCER BOX	Bent	785.90 FL	*688.00 FL
33	2		*REAR SILENCER BOX MOUNTING	Not Necessary	156.40 FL	*- FL
34	1		*SPARE TYRE TOP BOARD	Deformed	397.80 FL	*286.00 FL
35	1		*SPARE TYRE PANEL	Repair	798.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET REVERSE SENSORS	Damaged	250.00 FS	*200.00 FS
37	1		*SET REAR NUMBER PLATE WITH CASING	Distorted	50.00 FS	*50.00 FS
38	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
39	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
40	1		*SET REAR BOOTLID INNER TRIM CLIPS	Necessary	30.00 FS	*30.00 FS
41	2		*END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
42	2		*SET REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*60.00 FS
43	2		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
44	1		*SET REAR BUMPER LOWER COVER CLIPS	Necessary	30.00 FS	*30.00 FS
45	1		*REAR EMERGENCY BREAK DOWN SIGN	Cracked	200.00 FS	*100.00 FS
46	2		*SET TAILLAMPS CLIPS	Necessary	60.00 FS	*20.00 FS
47	2		*SET BOOTLID LAMP CLIPS	Necessary	60.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,698.30	10,789.40
- List Item Discount on L Items 20.00/20.00% (\$)	3,551.66	2,033.88
Total Parts (\$)	15,146.64	8,755.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT,WELD ,REALIGN AND ALIGNE ALL PARTS	New	2,200.00	1,200.00
2	TO RESPRAY AFFECTED AREAS	New	2,200.00	1,000.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	60.00
4	TO CONDUCT WIRING CHECK ON THE REAR TAILAMPS	New	120.00	30.00
5	TO REMOVE /REFIT /REPLACE BOOTLID REVERSE CAMERA	New	180.00	50.00
6	TO REMOVE /REFIT & REPLACE REAR SENSORS AND DISTANCE SETTLING	New	180.00	50.00
7	TO REMOVE /REFIT REAR INTERIOR UPHOLSTERY	New	180.00	80.00
8	TO CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
9	TO REMOVE /REFIT AND REPLACE REAR SILENCER	New	150.00	80.00
10	TO APPLY UNDERCOATING TO THE AFFECTED AREAS	New	180.00	80.00
11	TO REMOVE AND REPLACE BOOTLID MECHANISM	New	150.00	60.00
12	TO APPLY KLARCODE COATING TO ONE EXTERIOR	New	439.20	150.00
Gross Labour Cost (S\$)			6,299.20	2,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >