



Address : 1, Kaki Bukit Avenue 6 #02-22/20 Autobay S(417883)
 Reg: 201828067M

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: 78, SHENTON WAY, #07-16
 S(079120)

Cecilia

Telephone: 64193000 Fax: 68357416 Email assignments@lkkauto.com

Make/ Model : HYUNDAI AVANTE ELITE Date: 11.11.2020

Chassis No : KMHD841CMLU008570 Vehicle No: SMS4512J

Date/Time of Accide 10.11.2020/ 1810 Date of Reg: 27.02.2020

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	REAR BOOTLID <i>Dishled</i>	1	\$ 1,853.60		\$ ✓ 1,853.60
2	REAR BOOTLID INNER LOCK <i>Jamud</i>	1	\$ 185.70		\$ ✓ 185.70
3	REAR BOOTLID SMARTKEY ANTENNA <i>in</i>	1	\$ 197.50		\$ + 197.50
4	REAR BOOTLID INNER TRIM <i>shd</i>	1	\$ 235.40		\$ ✓ 235.40
5	REAR BOOTLID LATCH <i>Best</i>	1	\$ 38.50		\$ ✓ 38.50
6	REAR BOOTLID LOGO <i>ne</i>	1	\$ 93.60		\$ ✓ 93.60
7	REAR BOOTLID "AVANTE " EMBLEM <i>ne</i>	1	\$ 98.70		\$ ✓ 98.70
8	REAR NUMBER PLATE LAMPS <i>ipian dnd</i>	2	\$ 98.70		\$ 98.70 197.40
9	REAR BOOTLID LAMPS <i>cut</i>	2	\$ 498.70		\$ ✓ 997.40
10	REAR BOOTLID WEATHERSTRIP <i>cut</i>	1	\$ 165.30		\$ ✓ 165.30
11	END PANEL <i>Dishled</i>	1	\$ 657.80		\$ ✓ 657.80
12	END PANEL TOP GARNISH <i>del</i>	1	\$ 175.90		\$ ✓ 175.90
13	END PANEL BOOT RELEASE ANTENNA <i>ne</i>	1	\$ 185.90		\$ + 185.90
14	TAILAMPS <i>cut</i>	2	\$ 758.20		\$ ✓ 1,516.40
15	TAILAMPS PANEL <i>Brakled</i>	2	\$ 245.60		\$ ✓ 491.20
16	REAR BUMPER <i>Dishled</i>	1	\$ 675.10	<i>450</i>	\$ ✓ 675.10
17	REAR BUMPER NUMBER PLATE GARNISH <i>missing</i>	1	\$ 98.50		\$ ✓ 98.50
18	REAR BUMPER LOWER <i>Dishled</i>	1	\$ 496.30		\$ ✓ 496.30
19	REAR BUMPER LOWER COVER LH <i>3rd</i>	1	\$ 197.80		\$ x 197.80
20	REAR BUMPER LOWER COVER RH <i>3rd</i>	1	\$ 185.20		\$ + 185.20
21	REAR BUMPER RETAINERS <i>ne</i>	2	\$ 85.90		\$ ✓ 171.80
22	REAR BUMPER REFLECTOR <i>cut</i>	2	\$ 256.80		\$ ✓ 513.60
23	REAR BUMPER REINFORCEMENT <i>Dishled</i>	1	\$ 398.70	<i>295</i>	\$ ✓ 398.70
24	REAR REVERSE SENSORS HARDNESS <i>ne</i>	1	\$ 198.60		\$ + 198.60
25	REINFORCEMENT BRACKETS(BOTTOM) <i>2nd</i>	3	\$ 85.90		\$ 60 257.70
26	REINFORCEMENT BRACKETS(TOP) <i>2nd</i>	2	\$ 82.40		\$ 40 164.80
27	REINFORCEMENT BRACKETS METAL <i>Best</i>	2	\$ 226.50		\$ ✓ 453.00
28	REAR FENDER <i>Rep</i>	2	\$ 1,785.90		\$ + 3,571.80
29	REAR FENDER INNER TRIM <i>Not ne</i>	2	\$ 289.60		\$ x 579.20
30	REAR FENDER INNER COWLING <i>ne</i>	2	\$ 185.10		\$ + 370.20
31	REAR FENDER AIR DUCTS <i>ne</i>	2	\$ 98.50		\$ + 197.00

32	REAR SILENCER BOX <i>Best</i>	1	\$ 785.90	<i>688</i>	\$ <input checked="" type="checkbox"/> 785.90
33	REAR SILENCER BOX MOUNTING <i>per</i>	2	\$ 78.20		\$ <input checked="" type="checkbox"/> 156.40
34	SPARE TYRE TOP BOARD <i>2nd</i>	1	\$ 397.80	<i>286</i>	\$ <input checked="" type="checkbox"/> 397.80
35	SPARE TYRE PANEL <i>per</i>	1	\$ 798.60		\$ <input checked="" type="checkbox"/> 798.60
Total List Price Cost					\$ 17,758.30
					\$ 14,206.64

10/6940
8135-52

PARTS DISCOUNT 20%

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REVERSE SENSORS <i>2nd</i>	1 SET	\$ 250.00		\$ <i>250</i> 250.00
2	REAR NUMBER PLATE WITH CASING <i>assembled</i>	1 SET	\$ 50.00		\$ <input checked="" type="checkbox"/> 50.00
3	REAR BUMPER CLIPS <i>per</i>	1 SET	\$ 30.00		\$ <input checked="" type="checkbox"/> 30.00
4	END PANEL TOP GARNISH CLIPS <i>per</i>	1 SET	\$ 30.00		\$ <i>20</i> 30.00
5	REAR BOOTLID INNER TRIM CLIPS <i>per</i>	1 SET	\$ 30.00		\$ <input checked="" type="checkbox"/> 30.00
6	END PANEL SEALANT <i>per</i>	2	\$ 80.00		\$ <i>60</i> 80.00
7	REAR FENDER INNER TRIM CLIPS <i>per</i>	2 SET	\$ 60.00		\$ <input checked="" type="checkbox"/> 60.00
8	REAR FENDER INNER COWLING CLIPS <i>per</i>	2 SET	\$ 60.00		\$ <input checked="" type="checkbox"/> 60.00
9	REAR BUMPER LOWER COVER CLIPS <i>per</i>	1 SET	\$ 30.00		\$ <input checked="" type="checkbox"/> 30.00
10	REAR EMERGENCY BREAK DOWN SIGN <i>cut</i>	1	\$ 200.00		\$ <i>100</i> 200.00
11	TAILAMPS CLIPS <i>per</i>	2 SET	\$ 30.00		\$ <i>20</i> 60.00
12	BOOTLID LAMP CLIPS <i>per</i>	2 SET	\$ 30.00		\$ <i>20</i> 60.00
Total Special Nett Items					\$ 620.00

620

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 2,200.00
<i>1,200</i>	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,200.00
<i>1000</i>	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 60 200.00
TO CONDUCT WIRING CHECK ON THE REAR TAILAMPS	\$ 30 120.00
TO REMOVE / REFIT / REPLACE BOOTLID REVERSE CAMERA	\$ 50 180.00
TO REMOVE/ REFIT & REPLACE REAR SENSORS AND DISTANCE SETTLING	\$ 50 180.00
TO REMOVE/ REFIT REAR INTERIOR UPHOLSTERY	\$ 80 180.00
TO CONDUCT WATER LEAKAGE TEST	\$ X 120.00
TO REMOVE /REFIT AND REPLACE REAR SILENCER	\$ 80 150.00
TO APPLY UNDERCOATING TO THE AFFECTED AREAS	\$ 80 180.00
TO REMOVE AND REPLACE BOOTLID MECHANISM	\$ 60 150.00
TO APPLY KLARCODE COATING TO ONE EXTERIOR	\$ 150 439.20
Total Others Cost	\$ 1,899.20
GRAND TOTAL	\$ 21,125.84

2840

Adrian Lij

1/s 12/11/20


08 Days

total: 11595.52

1/s: 9.2K

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allan@casgarage.sg
 Fax: +65 6509 9501



P2W Services Pte Ltd (201410570W)
 48 Toh Guan Road East #02-124 Enterprise Hub
 Singapore 608586
 Phone: 66356703

Bill To: Frank Ng
 Singapore

Invoice: P2W:3239

Date: 17-Mar-2020

Amount: SGD 439.20

Model: Hyundai Avante

Colour: Grey

Plate: SMS 4512 J

Product/Service	Description	Unit Cost	Quantity	Discount	Price
KlarCoat Performance		488.00	1.00	48.80	439.20
Klarspa	complimentary voucher	90.00	1.00	90.00	0.00
KlarWindscreen Coats	Windscreen Coats	88.00	1.00	88.00	0.00

Subtotal: 439.20

Net Balance (SGD): 439.20

Total Paid: 50.00

Outstanding (SGD): **389.20**

Terms & Conditions

P2W Services Pte Ltd shall not be liable to any loss, defects and damages that has occurred upon departure of or after customer's acceptance of vehicle.