

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 12-Nov-20

INSURANCE: ALG.

MODEL: HYUNDAI I40

VEHICLE NO.: SHC 8832 C

CC4|AIG20012426|Dga³

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BOOTLID <i>Dented</i>	1	\$2,174.90	\$2,174.90
BOOTLID RUBBER <i>deformed</i>	1	\$96.50	\$96.50
BOOTLID HINGE (LH/RH) <i>2/S 4 4/S 4H 0/S rep</i>	2	\$284.60	\$569.20
BOOTLID LOCK UPPER <i>Dent</i>	1	\$114.90	\$114.90
BOOTLID LOCK LOWER <i>1mm</i>	1	\$23.20	\$23.20
BOOTLID KEY LOCK <i>4H</i>	1	\$68.00	\$68.00
BOOTLID I40 EMBLEM (I40) <i>4cc</i>	1	\$67.90	\$67.90
BOOTLID 'H' EMBLEM <i>4cc</i>	1	\$63.10	\$63.10
BOOTLID CRDI PLATE <i>4cc</i>	1	\$52.40	\$52.40
BOOTLID LAMP (LH/RH) <i>broken / crack 565 60 X 2</i>	2	<u>\$1,131.20</u>	<u>\$2,262.40</u>
LICENSE LAMP (LH/RH) <i>4H</i>	2	\$56.10	\$112.20
BOOTLID TRIMBOARD <i>4H torn</i>	1	\$343.90	\$343.90
BOOTLID TRIMBOARD CLIPS (11 PCS) <i>4H 4cc</i>	1	\$11.00	\$11.00
BOOTLID MOULDING (I40) <i>mostly crack</i>	1	\$385.30	\$385.30
BOOTLID LOWER GARNISH CHROME (I40) <i>4cc 85.00</i>	1	\$227.90	\$227.90
REAR BUMPER <i>Dented 553.00</i>	1	\$1,106.00	\$1,106.00
REAR BUMPER REINFORCEMENT BRACKET <i>0/S 4H</i>	1	\$160.60	\$160.60
REAR BUMPER REINFORCEMENT <i>broken</i>	1	\$428.40	\$428.40
REAR BUMPER CLIP <i>4cc</i>	1	\$19.00	\$19.00
REAR BUMPER SPONGE <i>torn</i>	1	\$119.50	\$119.50
REAR BUMPER UNDER COVER <i>distrub</i>	1	\$228.00	\$228.00
REAR BUMPER REFLECTOR LAMP (I40) <i>0/S broken</i>	1	\$32.00	\$32.00
TAIL LAMP (LH/RH) <i>broken / crack</i>	2	\$697.80	\$1,395.60
TAIL LAMP QUARTER PANEL (LH) <i>Dented 226.50</i>	1	\$453.00	\$453.00
REAR PANEL <i>Dented</i>	1	\$526.70	\$526.70
REAR PANEL LOWER <i>Dented</i>	1	\$367.20	\$367.20
REAR PANEL GARNISH <i>mostly broken</i>	1	\$57.70	\$57.70
PANEL ASSY-REAR FLOOR SIDE (LH) <i>4H</i>	1	\$177.00	\$177.00
SPARE TYRE HOLDER <i>4H</i>	1	\$223.10	\$223.10
SPARE WHEEL LOCK NUT <i>4H</i>	1	\$41.80	\$41.80
SPARE TYRE PANEL <i>4H</i>	1	\$852.80	\$852.80
SPARE TYRE PANEL CUSHION <i>4H</i>	1	\$223.10	\$223.10
MEMBER-ASSY-REAR FLOOR CENTRE <i>4H</i>	1	\$570.40	\$570.40
REAR TOWING HOOK <i>4H</i>	1	\$194.60	\$194.60
EXHAUST PIPE INSULATOR (LH) <i>4H</i>	1	\$117.10	\$117.10
EXHAUST SILENCER (LH) <i>2 4H 967.70</i>	1	\$1,935.40	\$1,935.40
EXHAUST PIPE HANGER <i>4H</i>	1	\$117.10	\$117.10
REAR FENDER <i>Dented</i>	1	\$2,171.40	\$2,171.40
REAR FENDER UNDER SHIELD (LH) <i>4H</i>	1	\$338.60	\$338.60
REAR TRAY LUGGS SIDE (LH) <i>4H</i>	1	\$232.60	\$232.60
REAR FENDER AIR-DUCT (LH) <i>deformed</i>	1	\$51.60	\$51.60
REAR FENDER TRIM BOARD (LH) <i>4H 1 torn</i>	1	\$688.75	\$688.75
REAR WINDSCREEN MOULDING <i>4cc</i>	1	\$51.80	\$51.80

	12571.55			
SUB TOTAL				\$19,453.65
LESS 20%	10057.24			\$3,890.73
DISCOUNTED TOTAL				\$15,562.92
BOOTLID COMFORT LOGO & TEL NO. STICKER <i>Hec</i> SN	1	\$17.00	\$17.00	✓
BOOTLID ADVERTISEMENT LOGO <i>Hec</i> SN	1	\$100.00	\$100.00	✓
REAR BUMPER RESERVE SENSOR <i>Dew</i> SN	1	\$118.00	\$118.00	✓
REAR BUMPER ADVERTISEMENT LOGO <i>Hec</i> SN	1	\$50.00	\$50.00	✓
REAR BUMPER RUBBER MAT / I40 PLATE <i>defina</i> SN	1	\$50.00	\$50.00	✓
REAR FENDER ADVERTISEMENT LOGO (LH) <i>Hec</i> SN	1	\$100.00	\$100.00	✓
REAR WINDSCREEN SEALANT <i>Hec</i> SN	1	\$46.00	\$46.00	✓
SUB TOTAL				\$481.00
	481.00			
Labour Charge				
Panel Beating	1	\$1,600.00	\$1,600.00	900/-
Spray Painting Charge	1	\$1,400.00	\$1,400.00	800/-
Wiring Charge	1	\$160.00	\$160.00	30/-
Tuff Kote	1	\$180.00	\$180.00	40/-
Towing Charge	1	\$80.00	\$80.00	20/-
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00	80/-
Remove/Refix Rear Windscreen Glass	1	\$120.00	\$120.00	80/-
Remove/Refix Reverse Sensor <i>2030-00</i>	1	\$120.00	\$120.00	40/-
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00	60/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	24
TOTAL LABOUR				\$4,440.00
ESTIMATE TOTAL				\$ 20,483.92
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

13/11/2020 e 0915h

Not Androm
2/5mm 8 days.

[Signature]

2kk Auto

[Signature]

Check P&A prices.

12568.24

1/5 10,000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: