

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 16 Nov 2020

Preliminary Advice

Vehicle No	: SME2403C	Accident Date	: 12/11/2020
Make	: SUBARU FORESTER	Policy No.	: 1800113328
Assignment Date	: 12/11/2020	Excess	: S\$400.00
Date of Inspection	: 13/11/2020	Est. Duration of Repair	: 9
Inspection At	: MOTOR IMAGE ENTERPRISES PTE LTD (TOA PAYOH) 19 LORONG 8 TOA PAYOH SINGAPORE 319255		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,957.10
Revised Amount	:S\$	13,162.70
Check Items (Estimated)	:S\$	1,251.40
Total	:S\$	14,414.10

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	35,371.00
Salvage Value	:S\$	
Margin for Repair	:S\$	46,629.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :