

MotorImage

19 Lorong 8 Toa Payoh
Singapore 310288



ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SME2403C	MODEL : FORESTER 2.0I-L AWD CVT
REF: INS/IC/CHI/0215/2020	YEAR: 24-SEP-2018
ENGINE NO: FB20YE53786	CHASSIS NO: JF1SJ5KC5JG112768
DOA: 12 / 11 / 2020	TOA: 0810 HRS
TYPE OF CLAIM: OD	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, RIGHT FENDER, LEFT FENDER, LEFT DOOR & RIGHT DOOR ²⁵⁰	\$ 2250.00 1500
2.	RESPRAY FRT BUMPER, FRT BONNET, FRT SUPPORT PANEL, RIGHT FENDER, LEFT FENDER, LEFT DOOR & RIGHT DOOR ²⁰⁰	\$ 1600.00 1200
3.	REMOVE & REFIX AIR CON CONDENSOR & RADIATOR TO FACILITATE REPAIRS	\$ 171.00 ✓
4.	MECHANICAL REPAIRS - ALTERNATOR, COMPRESSOR, STEERING PUMP	\$ 171.00 ✓
5.	REMOVE & REFIX WIRE HARNESS	\$ 228.00 ✓
6.	FAULT DIAGNOSTIC AND RESET SYSTEMS	\$ 235.00 ✓
7.	COOLING SYSTEM PRESSURE TEST	\$ 85.00 ✓
8.	TO CONDUCT FRONT LIGHTING TEST	\$ 28.00 ✓
9.	SUNDRIES	\$ 100.00 20
10.	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING	\$ 125.00 ✓
Total Labour		\$ 4993.00

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Guo Qiang - 82880282
HP / EMAIL:	Guo Qiang / kfk auto. com
BEFORE PAINT:	before paint photos.
DAYS GIVEN:	10 Days.

10 Not Authorised.

13 / 11 / 2020.

Estimate

Date 11 / 12 / 2020

601 / 003

Name	QUOTATION FOR SME2403C	Tel. Home	
Address	SPORT BUMPER	Tel. Office	
E-Mail		Tel. Portable	
		Fax	
		Model Name	513
		Body Model	SJ5EK7C
		Vin Code	JF15J5K05JG112768

Part Number	Part Code Name	Part Code	Qty	Price
57709SG011	BUMPER FACE-FRONT / <i>re</i>	FIG-590 57704	1	594.00
57711SG0009P	BACK BEAM COMPLETE-FRONT / <i>BT</i>	FIG-590 57711	1	288.00
57722SG020	ENERGY ABSORBER-FRONT BUMPER / <i>BT</i>	FIG-590 57705	1	126.00
57731SG070	COVER-FRONT BUMPER / <i>scr</i>	FIG-590 57731	1	5.40
57780SG010	PACKING-BUMPER, RIGHT / <i>ngc</i>	FIG-590 57780B	1	9.00
57780SG020	PACKING-BUMPER, LEFT / <i>ngc</i>	FIG-590 57780C	1	9.00
57707SG000	BRACKET-FRONT BUMPER CORNER, RI GHT / <i>re</i>	FIG-590 57707AF	1	36.00
57707SG010	BRACKET-FRONT BUMPER CORNER, LE FT / <i>re</i>	FIG-590 57707AG	1	36.00
57707SG020	BRACKET-FRONT BUMPER SIDE, RIGH T / <i>photo</i>	FIG-590 57707F	1	12.60
57707SG030	BRACKET-FRONT BUMPER SIDE, LEFT / <i>photo</i>	FIG-590 57707G	1	12.60
57731SG080	FRH FOG LAMP COVER / <i>X</i>	FIG-845 84927N	1	43.20
57731SG090	FLH FOG LAMP COVER / <i>X</i>	FIG-845 84927O	1	43.20
53029SG0019P	PANEL COMPLETE-RADIATOR / <i>buc</i>	FIG-505 53010	1	360.00
57731SG120	FRH BUMPER SD COVER / <i>X</i>	FIG-590 57708D	1	12.60
57731SG130	FLH BUMPER SD COVER / <i>X</i>	FIG-590 57708E	1	12.60
TCS-FJ8-FL-002	FRT BUMPER UNDER SPOILER / <i>Cut.</i>	FIG-590 57711	1	1,398.00
Page-Total				2,998.20

Memo

Grand Total
10,919.10

--

Tel

Estimate

Date 11 / 12 / 2020

002 / 003

Name	QUOTATION FOR SME2403C	Tel (Home)	
Address	SPORT BUMPER	Tel (Office)	
E-Mail		Tel (Portable)	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin Code	JF1SJ5K05JG112768

Part Number	Part Code Name	Part Code	Q'ty	Price
91121SG280A	FRONT GRILLE ASSEMBLY, LOWER / <i>CRA</i>	FIG-911 91121F	1	316.80
91121SG240A	FRONT GRILLE ASSEMBLY, CENTER / <i>CRA</i>	FIG-911 91121G	1	180.00
91121SG210A	FRONT GRILLE ASSEMBLY, UPPER / <i>CRA</i>	FIG-911 91121E	1	150.90
91165SG000	BRACKET-GRILL LOWER ✓ <i>RE</i>	FIG-911 91165JA	1	21.60
84002SG222	LAMP ASSEMBLY-HEAD RIGHT / <i>CRA</i>	FIG-840 84001A	1	2,380.00
84002SG232	LAMP ASSEMBLY-HEAD LEFT / <i>CRA</i>	FIG-840 84001B	1	2,380.00
84501AJ060	FOG LIGHT ASSEMBLY-FRONT X <i>NN</i>	FIG-845 84501B	2	544.00
57229SG0009P	HOOD COMPLETE-FRONT / <i>Buc</i>	FIG-550 57220	1	882.00
57310SG020	LOCK ASSEMBLY-FRONT HOOD / <i>BT</i>	FIG-550 57310	1	72.00
57311AG010	STRIKER-FRONT HOOD / <i>BT</i>	FIG-550 57311	1	36.00
57260SG0009P	HINGE COMPLETE-FRONT HOOD, RIGHT / <i>BT</i>	FIG-550 57260	1	43.20
57260SG0109P	HINGE COMPLETE-FRONT HOOD, LEFT / <i>BT</i>	FIG-550 57260A	1	43.20
57256SG020	COVER-FRONT FENDER, RIGHT <i>CRA</i> X <i>NN</i>	FIG-550 57256H	1	18.00
57256SG030	COVER-FRONT FENDER, LEFT X <i>NN</i>	FIG-550 57256I	1	18.00
90815SG051	INSULATOR-FRONT HOOD / <i>CRAmp</i>	FIG-956 90815B	1	79.20
57120SG0209P	FENDER COMPLETE-FRONT, RIGHT / <i>Buc</i>	FIG-540 57110	1	270.00
Page-Total				7,434.90

Memo

Grand Total

10,919.10

Tel

Estimate

Date 11 / 12 / 2020

003 / 003

Name	QUOTATION FOR SME2403C	Tel Home	
Address	SPORT BUMPER	Tel Office	
E-Mail		Tel Portable	
		Fax	
		Model Name	S13
		Body Model	SJ5EK7C
		Vin-Code	JF1SJ5K05JG112768

Part Number	Part Code Name	Part Code	Q ty	Price
57120SG0309P	FENDER COMPLETE-FRONT LEFT / huc	FIG-540 57110A	1	270.00
59110SG021	MUD GUARD, FRONT RIGHT X	FIG-541 59110B	1	108.00
59110SG031	MUD GUARD, FRONT LEFT X } WV	FIG-541 59110C	1	108.00
WMOOI (SUPP)	FRT NO PLATE \$45 (NET) / GA	Page-Total		486.00
		Sub-Total		10,919.10
		Total		10,919.10
		Tax		0.00
		Grand Total		10,919.10

Memo

Grand Total

~~10,919.10~~

16,673.20

Tel



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO S9E-2403-C

Surveyor: _____

DESCRIPTION

PART NO

AMOUNT

→1	PACZING RAD. LHS / RL	45167SG010	\$18.00/
→2	BRACKET. GRILL. UPR / RL	91165SG020	\$10.50/
→3	RADIATOR. LOWER. PANEL / BT	51231AG0009-P	\$112.00/
→4	COVER. PANEL SIDE. LEFT / BR	91423SG010	\$7.20/
→5	PACZING RADIATOR. RHS / RL	45167SG020	\$118.00/
6			
→7	Condenser ASSY / GA	73210SG011	\$579.30/
→8	Seal O ring / MSL	73039 TA040 X	\$3.60/
→9	Seal O ring	73039 TA030 X	\$3.60/
→10	Bracket - Radiator, Upper / BT	45124SG000	\$14.40/
→11	Reserve tank Assembly - Radiator / RL	45150SG001	\$61.00/
12			
→13	Hose-radiator inlet / Cut	45161SG010	\$36.00/
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			

Sumo Qiang
24/11/2020