

(08/11/13) .wef

ASS. REC. BY: *marcus*

REF:

*cc 6 / A1620012433/Upa3***ASSIGNMENT**

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

have G.I.A
coe 8-3-2022 NO BI involved
Rep 15k. NOT 5982
24/11/20 d/s \$3600 confirmed with Alan.

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

KKK HSIANTONG

not Authorized
date
14/1/20
2/s + 3600 / 2 hrs.

VEHICLE No: SKF 8499E

1PC	FRONT BUMPER	1704.10
1SET	FRONT BUMPER RIVET	
1PC	FRONT BUMPER REINFORCEMENT	608.00
2PCS	FRONT BUMPER CHROME MOULDINGS @161.00	
1PC	FRONT BUMPER DAY LIGHT LAMP O/S	
1PC	FRONT BUMPER DAY LIGHT LAMP GRILLE O/S	
1PC	FRONT BUMPER DAY LIGHT LAMP CHROME O/S	
1PC	FRONT BUMPER PDC SENSOR O/S	212.05
1PC	HEADLAMP ASSY O/S	1281.74
1PC	FRONT FENDER O/S	

Deep cut	\$2,108.33	✓
1M	\$60.00	✓
DO	\$788.10	✓
scr / 1M	\$322.00	✓
11	\$285.20	X
11	\$145.00	X
scr	\$109.30	✓
shut	\$245.00	✓
scr / 1M	\$4,550.22	✓
1	\$1,071.20	X
	\$9,684.35	

(102)

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO DISMANTLE & REPLACED PDC SENSOR
TO RESET & REPROGRAMME FAULT CODE
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00	20
11	\$50.00	X
	\$80.00	40
	\$100.00	50
	\$450.00	250
	\$600.00	300
TOTAL	\$11,014.35	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p- 4297.19
100
3867.47
4527.47
100
3621

Dear Owner of,

SXF8499E



I'm sorry that I accidentally dented
your car on the left hand corner.
Please contact me at 97310770
for all matters.

For Chue Jang
SU 94499 (SF 47310770)