

REPAIR ESTIMATE*

11/11/20

MAKE

MODEL HYU-140

CHING / *ALC*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

5feri CLKK)

ml Al

3 days

L15

13/11/20, 11.00a

My AC my

- by the Insurance company.
- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

FORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Hill Road Singapore 107643

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768731

Date/Time: 12.11.2020 16:36

Page : 1

Number of COMFORTDELGRO

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.:305433386

OMER

S

OMER NO

ESS

(R)

(P)

OUNT CARD NO.

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

REGN NO: SHA3797P

MAKE: HYUNDAI

MODEL I-40

YR OF MANU 17.03.2016

CHASSIS CODE KMHLEB41UMGU085621

MILEAGE

FUEL

DATE/TIME IN 12.11.2020 13:45

TARGET DATE

COMPLETION DATE/TIME:


Accident Date: 12.11.2020
NATURE: 3P 12.11.2020

S/NO

LABOR CODE

JOB DESCRIPTION

DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

No.:

SHA3797P

CHIANG

Exit Pass

Vehicle No.:

SHA3797P

of Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard