

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SMR5668S	MODEL : XV 2.0I-S EYESIGHT AWD CVT
REF NO: INS/IC/CHI/0214/2020	YEAR: 14-JAN-2020
ENGINE NO: FB20CF35583	CHASSIS NO: JF1GT7KL5KG069612
DOA: 10/11/2020	TOA: 1810HRS
TYPE OF CLAIM: OD	INS COMPANY: AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRT BUMPER, RH FRT FENDER, FRT PANEL & PANEL	\$1500.00 1125
2.	RESPRAY FRT BUMPER, RH FRT FENDER, FRT PANEL & PANEL	\$1200.00 1000
3.	REMOVE & REFIX AIRCON CONDENSER & RADIATOR TO FACILITATE REPAIR	\$171.00 ✓
4.	TRANSFER DOOR RH FRT MECHANISM	\$142.00 X
5.	MECHANICAL REPAIRS - ALTERNATOR, COMPRESSOR, STEERING PUMP	\$171.00 X
6.	FAULT DIAGNOSTIC	\$235.00 ✓
7.	TO CONDUCT FRONT LIGHTING TEST (LH FRT)	\$28.00 ✓
8.	TO CONDUCT PROTECTANT COATING	\$250.00 X
9.	TO CONDUCT ANTI RUST COATING	\$290.00 ?
10.	SUNDRIES	\$100.00 20
11.	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING	\$125.00 ✓
	Total Labour	

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Guo Qiang (LKK)
HP / EMAIL:	8288 0282 Guo Qiang @lkk auto.com
BEFORE PAINT:	before paint photos.
DAYS GIVEN:	

7 Days
13/11/2020

Not Authorised.

Estimate

Date 11 / 11 / 2020

001 / 004

Invoice Number	SMR5668S	Tel(Home)	
Registration Number		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	G24
		Body Model	GT7CKVL
		Vin-Code	JF1GT7KL5KG069612

Part Number	Part Code Name	Part Code	Q'ty	Price
57731FL110	COVER-INTAKE,FRONT <i>X NN</i>	FIG-590 57731M	1	51.70
57731FL130	COVER-FRONT BUMPER <i>/ DISMIS</i>	FIG-590 57731	1	4.90
57702FL310	BUMPER FACE-FRONT <i>/ D's</i>	FIG-590 57704	1	446.40
57731FL082	COVER-FOG LIGHT,RIGHT <i>/ M's</i>	FIG-590 84953N	1	46.30
57731FL092	COVER-FOG LIGHT,LEFT <i>/ M's</i>	FIG-590 84953O	1	46.30
57711FL0109P	BACK BEAM COMPLETE-FRONT <i>/ BT</i>	FIG-590 57711	1	346.00
57705FL040	ENERGY ABSORBER-FRONT BUMPER <i>/ CPA</i>	FIG-590 57705	1	59.90
57707FL060	BRACKET-BUMPER,FRONT LOWER <i>/ BR</i>	FIG-590 57707AE	1	36.00
57705FL080	ENERGY ABSORBER-LOWER <i>X</i>	FIG-590 57705C	1	38.00
57731FL150	COVER-UPPER <i>X</i>	FIG-590 57730	1	22.70
57707FL000	BRACKET-FRONT BUMPER CORNER,RI GHT <i>/ CA</i>	FIG-590 57707AF	1	36.00
57707FL010	BRACKET-FRONT BUMPER CORNER,LE FT <i>/ CA</i>	FIG-590 57707AG	1	36.00
57705FL001	ENERGY ABSORBER-UPPER <i>/ BT</i>	FIG-590 57705B	1	65.90
57735FL000	SEAL-FRONT BUMPER <i>/ CA</i>	FIG-590 57735A	1	21.60
57722FL100	PLATE-BUMPER,FRONT <i>/ CA</i>	FIG-590 57751F	1	28.80
57310FL050	LOCK ASSEMBLY-FRONT HOOD <i>/ BT</i>	FIG-550 57310	1	72.70
Page-Total				1,359.20

Memo

Grand Total
10,780.20

--

Tel

Estimate

Date 11 / 11 / 2020

002 / 004

Invoice Number	SMR5668S	Tel(Home)	
Registration Number		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	G24
		Body Model	GT7CKVL
		Vin-Code	JF1GT7KL5KG069612

Part Number	Part Code Name	Part Code	Q'ty	Price
57311FL010	STRIKER-FRONT HOOD / BT	FIG-550 57311	1	28.80
57229FL0109P	HOOD COMPLETE-FRONT / BT	FIG-550 57220	1	1,072.80
57260FL0209P	HINGE COMPLETE-FRONT HOOD, RIGHT	FIG-550 57260	1	37.90
57260FL0309P	HINGE COMPLETE-FRONT HOOD, LEFT	FIG-550 57260A	1	37.90
57256FL000	COVER-FRONT FENDER, RIGHT / ee	FIG-550 57256H	1	18.00
57256FL010	COVER-FRONT FENDER, LEFT	FIG-550 57256I	1	18.00
53029FL0819P	PANEL COMPLETE-RADIATOR	FIG-505 53010	1	376.70
51231FL0209P	FRAME COMPLETE-RADIATOR, LOWER	FIG-505 51231G	1	92.20
51609FL0409P	WHEEL APRON SUB COMPLETE-RIGHT	FIG-505 51610F	1	540.00
51609FL0509P	WHEEL APRON SUB COMPLETE-LEFT	FIG-505 51610G	1	540.00
91123FL170	MOLDING-FRONT GRILLER / CRA	FIG-911 91123F	1	129.60
91123FL140	MOLDING-FRONT GRILLE LEFT / XNN	FIG-911 91123D	1	111.90
91123FL130	MOLDING-FRONT GRILLE RIGHT /	FIG-911 91123C	1	111.90
91123FL100	MOLDING-FRONT GRILLEBAR / {scr	FIG-911 91123E	1	86.10
91122FL100	FRONT GRILLE-BASE / CRA	FIG-911 91122B	1	172.20
93013VA090	ORNAMENT / na	FIG-919 91174	1	64.80
Page-Total				3,438.80

Memo

Grand Total
10,780.20

Tel

Estimate

Invoice Number	SMR566B5	Date	11 / 11 / 2020	003 / 004
Registration Number		Tel(Home)		
		Tel(Office)		
		Tel(Portable)		
		Fax		
E-Mail		Model Name	G24	
		Body Model	GT7CKVL	
		Vin-Code	JF1GT7KL5KG069612	

Part Number	Part Code Name	Part Code	Q'ty	Price
84002FL110	LAMP ASSEMBLY-HEAD LEFT <i>8 MN</i>	FIG-840 84001B	1	2,520.00
84501AJ060	FOG LIGHT ASSEMBLY-FRONT <i>44X MN</i>	FIG-845 84501B	2	544.00
86636FL040EN	COVER ASSEMBLY-LAMP WASHER NOZ ZLE,RIGHT <i>mis</i>	FIG-877 86636NA	1	54.00
86636FL050EN	COVER ASSEMBLY-LAMP WASHER NOZ ZLE,LEFT <i>mis</i>	FIG-877 86636OA	1	54.00
86636FL000	NOZZLE-LAMP WASHER,RIGHT <i>mis</i>	FIG-877 86636N	1	82.10
86636FL010	NOZZLE-LAMP WASHER,LEFT <i>mis</i>	FIG-877 86636O	1	82.10
57120FL0609P	FENDER COMPLETE-FRONT,RIGHT <i>bux</i>	FIG-540 57110	1	207.50
59110FL040	MUD GUARD,FRONT RIGHT <i>W</i>	FIG-541 59110B	1	108.00
60009FL0409P	PANEL ASSEMBLY-FRONT DOOR,RIGHT <i>Repair X</i>	FIG-605 60010	1	920.00
61280FL020	WEATHER STRIP-DOOR,OUT RH <i>X</i>	FIG-605 61280	1	107.60
61160FL042WW	HANDLE-DOOR,OUTER <i>X</i>	FIG-607 61160E	1	252.00
61032FL021	LATCH & ACTUATOR ASSEMBLY-FRONT,RIGHT <i>X</i>	FIG-607 61176F	1	216.00
90422FL000	TAPE-FRONT DOOR,RIGHT <i>X</i>	FIG-905 90422X	1	10.80
90422FL020	TAPE-FRONT DOOR SASH RIGHT <i>X</i>	FIG-905 90422A	1	10.80
63563FL360	COVER ASSEMBLY-B PILLAR,RIGHT <i>X</i>	FIG-901 63563	1	25.20
63563FL200	COVER-SASH,FRONT RIGHT <i>X</i>	FIG-901 63563M	1	10.80
Page-Total				5,204.90

Memo

Grand Total
10,780.20

--

Tel

Estimate

Invoice Number	SMR56683	Date	11 / 11 / 2020	004 / 004
Registration Number		Tell Home		
E-Mail		Tell Office		
		Tell Portable		
		Fav		
		Model Name	G24	
		Body Model	GT7CKVL	
		Vin-Code	JF1GT7KL5K/G069612	

Part Number	Part Code Name	Part Code	Qty	Price
45111FL001	RADIATOR ASSEMBLY	FIG-450 45111	1	576 00
45161FL000	HOSE-RADIATOR INLET	FIG-450 45162G	1	32 80
45161FL040	HOSE-RADIATOR OUTLET	FIG-450 45162H	1	28 80
91112FL120	GARNISH-FRONT FENDER,RIGHT	FIG-914 91111	1	139 90
WMOOI	PRT NO DATE \$45 (NETT) / cut	Page-Total		777 30
		Sub-Total		10,780 20
	HEADLAMP RIGHT / CRA	Total		10,780 20
		Tax		0 00
		Grand Total		10,780 20

Memo

Grand Total
10,780.20

Tel



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SMD 5668S

Surveyor: _____

LABOUR DESCRIPTION

AMOUNT

1	remove & retix wire harness	\$ 228.00 ✓
2	cooling system pressure test	\$ 85.00 ✓
3		
4	Caro Qianf.	
5	24/11/2020	
6		
7		
8		
9		
10		
11		
12		



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SMP 5668 S

Surveyor: _____

DESCRIPTION

PART NO

AMOUNT

1	COVER INTAKE FRONT / BR	57731FL110	\$51,70
2	AIR GUIDE / CFA	73233FL000	\$18,00
3	FRANGE ASSEMBLY ACTIVE LITZUK /	52811T-L050	\$140,00
4	BR		
5			
6			
7			
8	Goodland 24/11/2020.		
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			