

ESTIMATE / QUOTATION COST OF ACCIDENT REPAIR

REG NO: SMR5668S	MODEL : XV 2.0I-S EYESIGHT AWD CVT
REF NO:INS/IC/CHI/0214/2020	YEAR: 14-JAN-2020
ENGINE NO: FB20CF35583	CHASSIS NO: JF1GT7KL5KG069612
DOA: 10/11/2020	TOA: 1810HRS
TYPE OF CLAIM: OD	INS COMPANY:AIG

S/N	NATURE OF JOB	AMOUNT
1.	REPAIR/REPLACE FRT BUMPER,RH FRT FENDER,FRT PANEL & PANEL	\$1500.00 1125
2.	RESPRAY FRT BUMPER,RH FRT FENDER,FRT PANEL & PANEL	\$1200.00 1000
3.	REMOVE & REFIX AIRCON CONDENSER & RADIATOR TO FACILITATE REPAIR	\$171.00
4.	TRANSFER DOOR RH FRT MECHANISM	\$142.00 X
5.	MECHANICAL REPAIRS - ALTERNATOR, COMPRESSOR, STEERING PUMP	\$171.00 ?
6.	FAULT DIAGNOSTIC	\$235.00
7.	TO CONDUCT FRONT LIGHTING TEST (LH FRT)	\$28.00
8.	TO CONDUCT PROTECTANT COATING	\$250.00 X
9.	TO CONDUCT ANTI RUST COATING	\$290.00 ?
10.	SUNDRIES	\$100.00 20
11.	REMOVE/REFIX FRT HEADLAMP WASHER & PIPING	\$125.00
Total Labour		

DATE APPROVAL:	
TIME APPROVAL:	
SURVEY BY:	Guo Qiang (Ukk)
HP / EMAIL:	8288 0282, Guo Qiang @lkkauto.com
BEFORE PAINT:	before paint photos.
DAYS GIVEN:	

7 Days
13/11/2020

Not Authorised.

Estimate

Date 11 / 11 / 2020

001 / 004

Invoice Number	SMR5668S	Tel(Home)	
Registration Number		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	G24
		Body Model	GT7CKVL
		Vin-Code	JF1GT7KL5KG069612

Part Number	Part Code Name	Part Code	Q'ty	Price
57731FL110	COVER-INTAKE,FRONT X	FIG-590 57731M	1	51.70
✓ 57731FL130	COVER-FRONT BUMPER / DISMIS	FIG-590 57731	1	4.90 /
✓ 57702FL310	BUMPER FACE-FRONT / D's	FIG-590 57704	1	446.40 /
✓ 57731FL082	COVER-FOG LIGHT,RIGHT / m's	FIG-590 84953N	1	46.30 /
✓ 57731FL092	COVER-FOG LIGHT,LEFT / m's	FIG-590 84953O	1	46.30 /
✓ 57711FL0109P	BACK BEAM COMPLETE-FRONT / BT	FIG-590 57711	1	346.00 /
✓ 57705FL040	ENERGY ABSORBER-FRONT BUMPER / CRA	FIG-590 57705	1	59.90 /
✓ 57707FL060	BRACKET-BUMPER,FRONT LOWER / BR	FIG-590 57707AE	1	36.00 /
57705FL080	ENERGY ABSORBER-LOWER X	FIG-590 57705C	1	38.00
57731FL150	COVER-UPPER X	FIG-590 57730	1	22.70
✓ 57707FL000	BRACKET-FRONT BUMPER CORNER,RI GHT / CA	FIG-590 57707AF	1	36.00 /
✓ 57707FL010	BRACKET-FRONT BUMPER CORNER,LE FT / CA	FIG-590 57707AG	1	36.00 /
→ 57705FL001	ENERGY ABSORBER-UPPER / BT	FIG-590 57705B	1	65.90 /
→ 57735FL000	SEAL-FRONT BUMPER / CA	FIG-590 57735A	1	21.60 /
✓ 57722FL100	PLATE-BUMPER,FRONT / CA	FIG-590 57751F	1	28.80 /
✓ 57310FL050	LOCK ASSEMBLY-FRONT HOOD / BT	FIG-550 57310	1	72.70 /
		Page-Total		1,359.20

Memo

Grand Total
10,780.20

--

Tel

Estimate

Date

11 / 11 / 2020

002 / 004

Invoice Number	SMR5668S	Tel(Home)	
Registration Number		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	G24
		Body Model	GT7CKVL
		Vin-Code	JF1GT7KL5KG069612

Part Number	Part Code Name	Part Code	Q'ty	Price
✓ 57311FL010	STRIKER-FRONT HOOD / BT	FIG-550 57311	1	28.80 ✓
✓ 57229FL0109P	HOOD COMPLETE-FRONT / BT	FIG-550 57220	1	1,072.80 ✓
57260FL0209P	HINGE COMPLETE-FRONT HOOD, RIGH	FIG-550 57260	1	37.90
57260FL0309P	HINGE COMPLETE-FRONT HOOD, LEFT	FIG-550 57260A	1	37.90
✓ 57256FL000	COVER-FRONT FENDER, RIGHT / ee	FIG-550 57256H	1	18.00 ✓
57256FL010	COVER-FRONT FENDER, LEFT	FIG-550 57256I	1	18.00
12 53029FL0819P	PANEL COMPLETE-RADIATOR / BT Repair R	FIG-505 53010	1	376.70 R
51231FL0209P	FRAME COMPLETE-RADIATOR, LOWER	FIG-505 51231G	1	92.20
51609FL0409P	WHEEL APRON SUB COMPLETE-RIGHT	FIG-505 51610F	1	540.00
51609FL0509P	WHEEL APRON SUB COMPLETE-LEFT	FIG-505 51610G	1	540.00
✓ 91123FL170	MOLDING-FRONT GRILLER /	FIG-911 91123F	1	129.60 ✓
91123FL140	MOLDING-FRONT GRILLE LEFT	FIG-911 91123D	1	111.90
✓ 91123FL130	MOLDING-FRONT GRILLE RIGHT /	FIG-911 91123C	1	111.90 ✓
✓ 91123FL100	MOLDING-FRONT GRILLEBAR /	FIG-911 91123E	1	86.10 ✓
✓ 91122FL100	FRONT GRILLE-BASE /	FIG-911 91122B	1	172.20 ✓
✓ 93013VA090	ORNAMENT /	FIG-919 91174	1	64.80 ✓
Page-Total				3,438.80

Memo

Grand Total
10,780.20

--

Tel

Estimate

Date _____

11 / 11 / 2020

003 / 004

Invoice Number	SMR5668S	Tel(Home)	
		Tel(Office)	
Registration Number		Tel(Portable)	
		Fax	
		Model Name	G24
E-Mail		Body Model	GT7CKVL
		Vin-Code	JF1GT7KL5KG069612

Part Number	Part Code Name	Part Code	Q'ty	Price
84002FL110	LAMP ASSEMBLY-HEAD LEFT ?	FIG-840 84001B	1	2,520.00
84501AJ060	FOG LIGHT ASSEMBLY-FRONT 44X alt / scr	FIG-845 84501B	2 1	544.00
86636FL040EN	COVER ASSEMBLY-LAMP WASHER NOZ ZLE,RIGHT / mis	FIG-877 86636NA	1	54.00
86636FL050EN	COVER ASSEMBLY-LAMP WASHER NOZ ZLE,LEFT / mis	FIG-877 86636OA	1	54.00
86636FL000	NOZZLE-LAMP WASHER,RIGHT / } mis	FIG-877 86636N	1	82.10
86636FL010	NOZZLE-LAMP WASHER,LEFT / }	FIG-877 86636O	1	82.10
57120FL0609P	FENDER COMPLETE-FRONT,RIGHT / buc	FIG-540 57110	1	207.50
59110FL040	MUD GUARD,FRONT RIGHT / TW	FIG-541 59110B	1	108.00
60009FL0409P	PANEL ASSEMBLY-FRONT DOOR,RIGHT T mis X	FIG-605 60010	1	920.00
61280FL020	WEATHER STRIP-DOOR,OUT RH X	FIG-605 61280	1	107.60
61160FL042WW	HANDLE-DOOR,OUTER X	FIG-607 61160E	1	252.00
61032FL021	LATCH & ACTUATOR ASSEMBLY-FRONT, RIGHT X	FIG-607 61176F	1	216.00
90422FL000	TAPE-FRONT DOOR,RIGHT X	FIG-905 90422X	1	10.80
90422FL020	TAPE-FRONT DOOR SASH RIGHT X	FIG-905 90422A	1	10.80
63563FL360	COVER ASSEMBLY-B PILLAR,RIGHT X	FIG-901 63563	1	25.20
63563FL200	COVER-SASH,FRONT RIGHT X	FIG-901 63563M	1	10.80
		Page-Total		5,204.90

Memo

Grand Total
10,780.20

--

Tel _____

Estimate

Date 11 / 11 / 2020

004 / 004

Invoice Number	SMR5668S	Tel(Home)	
Registration Number		Tel(Office)	
E-Mail		Tel(Portable)	
		Fax	
		Model Name	G24
		Body Model	GT7CKVL
		Vin-Code	JF1GT7KL5KG069612

Part Number	Part Code Name	Part Code	Q'ty	Price
45111FL001	RADIATOR ASSEMBLY X	FIG-450 45111	1	576.00
45161FL000	HOSE-RADIATOR INLET X	FIG-450 45162G	1	32.60
45161FL040	HOSE-RADIATOR OUTLET X	FIG-450 45162H	1	28.80
✓ 91112FL120	GARNISH-FRONT FENDER,RIGHT / re.	FIG-914 91111	1	139.90 ✓
(Supp) ✓ WMOOI	PRT NO DATE \$45 (NETT) / CA	Page-Total		777.30
		Sub-Total		10,780.20
(Supp) → 840027L100	HEADLAMP RIGHT / \$2,520, CRA	Total		10,780.20
		Tax		0.00
		Grand Total		10,780.20

Memo

Grand Total
10,780.20

--

Tel



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO SMD 56688

Surveyor: _____

LABOUR DESCRIPTION

AMOUNT

Repair

Repair

1 remove & refix wire harness

\$ 228.00 ✓

2 cooling system pressure test

\$ 85.00 ✓

3 _____

4 Sumo Qionf.

5 24/11/2020

6 _____

7 _____

8 _____

9 _____

10 _____

11 _____

12 _____



Motor Image Enterprises Pte Ltd
19 Lorong 8 Toa Payoh
Singapore 319255
Tel: (65) 6703 8101/8102
Fax: (65) 6253 5535
www.motorimage.net
Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SMR 5668 S

Surveyor: _____

DESCRIPTION

PART NO

AMOUNT

1	COVER INTAKE TRACT / PR	57731FL110 /	\$51,70 /
2	AIR GUIDE / CPA	73233FL000 /	\$18,00 /
3	FRANGE ASSEMBLY ACTIVE GRILL /	52811TL050 /	\$140,20 /
4	BR		
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			

Guo Qian
24/11/2020