

All diagnosis code

TEL:

FAX:

Employee. in charge:

E-mail:

Date and time: 27/11/2020 4:31:34 pm

Vehicle: Impreza / XV

VIN: JF1GT7KL5KG069612

Model: 19MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			01018	385500	Current		
Past	C1424	ECM	00993	1300	ommo		**

<Tire Pressure Monitor : 0 piece>

<Body Control : 0 piece>

<Airbag : 0 piece>

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			01018	385500	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					

<Keyless Access with Push Button Start : 0 piece>

<EyeSight : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			01018	385500	Current		
Past	B2806	ECM Abnormal	00993	5000	ommo		**

<Automatic Light and Wiper : 0 piece>

<Combination Meter : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			01018	385500	Current		
Past	U0156	Lost Communication With Information Center "A"	00049	800	ommo		

<Multi-function Display : 0 piece>

<Headlight / Foglight : 4 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			01018	385500	Current		
Past	B2904	LED Headlight Circuit RH	00988	2400	ommo		**
Past	B2905	LED Head Light Circuit LH	00989	2400	ommo		
Past	B2910	Steering Responsive Headlight Communication RH	00989	5000	ommo		
Past	B2911	Steering Responsive Headlight Communication LH	00989	5000	ommo		

<Subaru Rear Vehicle Detection(RH) : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count [count]	Time [msec]	Group		
			01018	385500	Current		
Past	B2301	Rear RADAR Circuit High	01009	700	ommo		

<Subaru Rear Vehicle Detection(LH) : 0 piece>

<Power Window (Driver) : 0 piece>

<Power Window (Passenger) : 0 piece>

<Power Window (Switch) : 0 piece>

<Reverse Automatic Braking : 0 piece>

All diagnosis code

TEL:

FAX:

Employee. in charge:

E-mail:

Date and time: 27/11/2020 4:34:46 pm

Vehicle: Impreza / XV

VIN: JF1GT7KL5KG069612

Model: 19MY > SSM4

[Diagnostic comments]

[Diagnostic result details]

Data name:

Memo:

<Engine : 0 piece>

<Transmission : 0 piece>

<Brake Control : 0 piece>

<Tire Pressure Monitor : 0 piece>

<Body Control : 0 piece>

<Airbag : 0 piece>

<Power Steering : 0 piece>

<Air Conditioner : 1 piece>

Status	Code	Description & trouble part	Time stamp			IG counter	FFD
			Trip Count (count)	Time [msec]	Group		
			01019	20900	Current		
Current	B14A1	Sunload Sensor Circuit Low/Open					

<Keyless Access with Push Button Start : 0 piece>

<EyeSight : 0 piece>

<Automatic Light and Wiper : 0 piece>

<Combination Meter : 0 piece>

<Multi-function Display : 0 piece>

<Headlight / Foglight : 0 piece>

<Subaru Rear Vehicle Detection(RH) : 0 piece>

<Subaru Rear Vehicle Detection(LH) : 0 piece>

<Power Window (Driver) : 0 piece>

<Power Window (Passenger) : 0 piece>

<Power Window (Switch) : 0 piece>

<Reverse Automatic Braking : 0 piece>