

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

11-Nov-20

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHC 6517 B

1 pc	Front n/s door	X R	\$	1,723.60
1 pc	Support panel	X	\$	1,243.60
1 pc	Delta garnish front o/s	/ MC	\$	15.30
1 pc	Mud guard front o/s	X	\$	47.48
1 pc	Front o/s fender signal light @ \$32.10	/ MT	\$	32.10
1 pc	Washer tank motor	X	\$	75.00
1 pc	Washer tank	X	\$	51.40
1 pc	Front bumper o/s upper bracket	X	\$	92.60
1 pc	Front bumper o/s support bracket	X	\$	37.01
1 pc	Front o/s fog lamp cover	X	\$	25.00
1 pc	Front o/s head lamp	X	\$	1,531.57
1 pc	Front bumper	X R	\$	811.11
1 pc	Front bumper emblem	X	\$	27.80
1 pc	Front bumper o/s side bracket	X	\$	32.51
1 pc	Front o/s fender	/ DD	\$	514.02
1 pc	Front o/s rim	X	\$	246.00
1 pc	Front o/s lower arm	X	\$	811.34
1 pc	Front o/s shock absorber	X	\$	611.56
1 pc	Front o/s tie rod end	X	\$	72.50
1 pc	Front o/s ball joint	X	\$	91.90
1 pc	Front o/s knuckle bearing	X	\$	349.60
1 pc	Front o/s stabilizer link	X	\$	88.50
1 pc	o/s mirror Assy	X	\$	749.49
1 pc	Front o/s fender inner shield	X	\$	176.72
			\$	6,427.73
		Less 20%	\$	1,285.55
			\$	5,142.18

11-Nov-20

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHC 6517 B

S/NETT

1 set	Front bumper clips	X	\$	48 00
1 pc	Front o/s fender sticker	X	\$	30 00
1 set	o/s door sticker	✓ ML	\$	100 00
1 pc	Tyre front o/s	X	\$	200 00
1 set	Front o/s fender inner shield clips	X	\$	28 00
Sundry				\$ 50 00 30
Towing Fee				\$ 50 00 ✓
To check wheel alignment				\$ 80 00 60
To focus/check front n/s & o/s head lamps				\$ 60 00 X
To dismantle and refit the inner components of the front n/s door into new shell door				\$ 150 00 X
To dismantle and replace the front o/s undercarriage				\$ 250 00 X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.				\$ 180 00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front o/s door etc				\$ 1,000.00 300
To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s wheel house, rear o/s door, o/s rocker panel				900 \$ 1,200.00
To apply rustproofing on the repaired and replaced panels.				\$ 150 00 30
				<u>\$ 8,718.18</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Steve (LKK) ML AL
11/11/20, 3.00pm
4 hrs
L/S
My AL 20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: