

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte Ltd (159-f&L)
 45 Leng Kee Road

Singapore 159103

GST Reg.No:M28920628X

Inv.No. . . : B&P 0 Page 1

Inv.date. . : 12/11/2020

WIP No. . . : 49515

Veh.In/Out:

*Tel.No. . . :

Reg.No. . . : SMK5508H

Reg.date . . : 29/08/2016

Mileage . . . : 0

Chassis No: JN18CAV37Z0480782

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER, FRT RH HEADLAMP, FOG LAMP, SIGNAL LAMP, MESH GRILLE, RH FRT FENDER, SENSORS, ETC	0	2700.00	0		2,700.00 S 1800	
800	TO SPRAYPAINT ON FRT BUMPER, FRT RH FENDER	0	2400.00	0		2,400.00 S 1600	
280	TO FOCUS HEADLAMP	0	175.00	0		175.00 S ?	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	525.00	0		525.00 S	
	BRACKET-BUMPER FRT R <i>new</i>	1.0 EA	21.40			21.40 S 19.26	
	CLIP <i>new</i>	1.0 EA	54.60			54.60 S 49.14	
	CLIP <i>new</i>	1.0 EA	54.60			54.60 S 49.14	
	BRACKET-BUMPER FRT L <i>X new</i>	1.0 EA	15.20			15.20 S	
	BRACKET-BUMPER FRT R <i>new</i>	1.0 EA	15.20			15.20 S 13.68	
	BUMPER FRT RETAINER <i>? x svl</i>	1.0 EA	60.70			60.70 S	
	BUMPER FRT RETAINER <i>X svl</i>	1.0 EA	60.70			60.70 S	

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte Ltd (159-f&L)
 45 Leng Kee Road

Singapore 159103

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Wearnes Automotive P

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2
 Inv.date. : 12/11/2020
 WIP No. . : 49515
 Veh.In/Out:
 *Tel.No. . :
 Reg.No. . : SMK5508H
 Reg.date. : 29/08/2016
 Mileage . : 0
 Chassis No: JN1BCAV37Z0480782

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	REINFORCEMENT-BUMPER <i>X SVL</i>	1.0 EA	520.50			520.50	S
	BUMPER FRT BASE SPOIL <i>X SVL</i>	1.0 EA	121.20			121.20	S
	ENERGY ABSORBER FOAM <i>X SVL</i>	1.0 EA	182.30			182.30	S
	TOW COVER BUMPER FRT <i>X SVL</i>	1.0 EA	21.60			21.60	S
	BRKT LICENS PLA <i>X SVL</i>	1.0 EA	127.00			127.00	S
	BUMPER SPORTS-FR <i>Q5 tom</i>	1.0 EA	583.00			583.00	S 524.70
	FOG LAMP GRILLE RH S <i>com</i>	1.0 EA	83.40			83.40	S 75.06
	HEADLAMP ASSY-RH Q50 <i>? com</i>	1.0 EA	3615.60			3,615.60	S 3254.04
	LAMP ASSY-FR TU <i>? com</i>	1.0 EA	106.20			106.20	S 97.58
	FOG LAMP RH FRT Q50 <i>com</i>	1.0 EA	472.40			472.40	S 425.16
	BUMPER INNER PANEL Q <i>? X SVL</i>	1.0 EA	636.90			636.90	S
	SUPPORT-RADIATO <i>? X SVL</i>	1.0 EA	54.60			54.60	S
	BRACKET LOWER FENDER <i>X SVL</i>	1.0 EA	83.40			83.40	S
	FENDER-FRONT RH Q50 <i>repair</i>	1.0 EA	764.00			764.00	S
	WHEEL ARCH OUTER FRT <i>com</i>	1.0 EA	47.10			47.10	S 42.39
	BUMPER GRILLE LOWER <i>? com</i>	1.0 EA	214.50			214.50	S 193.05
	ADHESIVE SEALER FL2 <i>X AN</i>	1.0 EA	709.60			709.60	S

SERVICE ESTIMATE

63413 - C00001 SL: SERVICE SALES - PC
 Wearnes Automotive Pte Ltd (159-f&L)
 45 Leng Kee Road

GST Reg.No: M28920628X

Inv.No. : B&P 0 Page 3
 Inv.date. : 12/11/2020
 WIP No. : 49515
 Veh.In/Out:
 *Tel.No. :
 Reg.No. : SMK5508H
 Reg.date. : 29/08/2016
 Mileage : 0
 Chassis No: JN18CAV37Z0480782

Singapore 159103

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Wearnes Automotive P

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BODY PANEL SEALANT X <i>Ann</i>	1.0 EA	955.20			955.20	S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Paul
Hp 90010068
4 days
12/11/2020 @ 1540
Resurvey before paint

Gross Total.	15,380.90
Net.....	15,380.90
GST @ 7.0%	1,076.66
Total.....	16,457.55
Paid.....	0.00
Please Pay..	16,457.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated