

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
 2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 86872100

TP Chinn.
Denise.

ESTIMATE

Repair Code : CLM16542

Date in : 12/11/2020

Vehicle Num. : SLS3071H

Model : TOYOTA PRIUS ALPHA 1.8S CVT

Chassis/Eng# : ZVW400025607/2ZR1969857

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Deformed</i>	1	523.90	✓ 523.90
REAR BUMPER END SEAL COVER LH <i>new</i>	1	92.30	+ 92.30
REAR BUMPER REFLECTOR L/R <i>LH could</i>	2	58.00	58 116.00
REAR BUMPER SIDE RETAINER L/R <i>LH could</i>	2	98.00	98 196.00
REAR END PANEL <i>Repair</i>	1	781.45	+ 781.45
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	465.00	+ 465.00
REAR END PANEL INNER TOP GARNISH <i>Deformed</i>	1	287.90	✓ 287.90
REAR FENDER INNER TRIM BOARD L/R <i>new</i>	2	656.00	+ 1,312.00
REAR FLOOR SPONGE COMPARTMENT TRAY <i>new</i>	1	459.70	+ 459.70
REAR FLOOR SPONGE COMPARTMENT TRAY TOP BOARD COVER <i>new</i>	1	655.00	+ 655.00
REAR LH TAILLAMP <i>could</i>	1	630.00	✓ 630.00
REAR LH TAILLAMP INNER BLACK GASKET <i>new</i>	1	69.50	20/30 69.50
REAR LH TAILLAMP LOWER BRACKET <i>could</i>	1	68.00	✓ 68.00
REAR TAILGATE <i>Dented</i>	1	929.60	✓ 929.60
REAR TAILGATE 'HYBRID' EMBLEM <i>new</i>	1	50.00	✓ 50.00
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	61.10	+ 61.10
REAR TAILGATE 'PRIUS' EMBLEM <i>new</i>	1	52.30	✓ 52.30
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>new</i>	2	29.00	+ 58.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 86872100

ESTIMATE

Repair Code : CLM16542
Date in : 12/11/2020
Vehicle Num. : SLS3071H
Model : TOYOTA PRIUS ALPHA 1.8S CVT
Chassis/Eng# : ZVW400025607/2ZR1969857

REAR TAILGATE INNER TRIM BOARD <i>Del</i>	1	578.00	✓	578.00
REAR TAILGATE LOCK STRIKER <i>3 new</i>	1	45.00	✗	45.00
REAR TAILGATE MECHANISM LOCK	1	425.00	+	425.00
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	360.70	✓	360.70
REAR TAILGATE WINDSCREEN LOWER SEAL <i>3 new</i>	1	42.00	✓	42.00
REAR TAILGATE WINDSCREEN MOULDING L/R	2	65.00	✓	130.00
REAR TAILGATE WINDSCREEN UPPER SEAL	1	38.00	✓	38.00
Subtotal before discount				8,426.45
Percentage discount 25%				2,106.61
Sub-total 1				6,319.84
REAR BUMPER CLIPS - SET <i>me</i>	1	50.00	30	50.00
REAR BUMPER END SEAL COVER CLIPS L/R - SET <i>new</i>	2	25.00	+	50.00
REAR BUMPER REVERSE SENSOR - SET <i>2 new</i>	1	280.00	20	280.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>me</i>	1	30.00	10	30.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>new</i>	2	50.00	+	100.00
REAR LH TAILLAMP CLIPS - SET <i>me</i>	1	25.00	10	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>me</i>	1	50.00	30	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new me</i>	1	30.00	✗	30.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 86872100

ESTIMATE

Repair Code : CLM16542
Date in : 12/11/2020
Vehicle Num. : SLS3071H
Model : TOYOTA PRIUS ALPHA 1.8S CVT
Chassis/Eng# : ZVW400025607/2ZR1969857

REAR TAILGATE WINDSCREEN SEALANT	1	80.00	60	80.00
				340
				Subtotal before discount
				695.00
Percentage discount	0%			0.00
				Sub-total 2
				695.00
				Parts-total
				7,014.84

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

50 80.00
120 150.00
60 120.00
700 1,000.00
600 1,000.00
60 80.00
✓ 80.00
Labour Total 2,510.00
Parts & Labour Total 9,524.84

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 3

Admin L
1/5 13/11/20
total: 9,524.84 050 days.
1/5: 3.9K ✓