



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

UNITED OVERSEAS INSURANCE LTD #28-01 SPRINGLEAF TOWER 3 ANSON RD SINGAPORE 079909 ATTN: MOTOR CLAIMS FAX: SLL7967J		NAME: Mdm Sia Lu-Ming Eugenie ADDRESS: TEL: 97771494		WIP: 39885 EXCESS: DATE: 18-Nov-20	
VEH NO:	SLL7967J	DATE IN:		CONTACT PERSON:	JOBI THOMAS 6331 0682
CHASSIS NO:	WMWX5520302F21270	MILEAGE:		TYPE OF CLAIM:	OWN DAMAGE CLAIM
MODEL:	MINI COOPER	DATE REG.:	10-Mar-17	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
S/NO	QTY			REVISED	PRICES
1	EXCH CATALYT ? X	1	B18.32.7.634.628		\$ 1,694.80
2	REGULATING L ? X	1	B11.78.8.600.992		\$ 557.40
3	LAMBDA MONIT ? X	1	B11.78.8.604.889		\$ 445.90
4	AIR FILTER E / soaked	1	M13.71.8.513.944		\$ 90.55
5	RP POWER TRA ? new	1	B11.00.2.455.307		\$ 16,512.40
6	MINI OIL 1L 5W 30W 10 / new	4.25	LMINIOIL		\$ 170.00
7	TURBOCHARGER ? new	1	B11.65.9.470.992		\$ 4,570.25
8	SCREW CLAMP ? new	1	B18.30.7.606.136		\$ 43.05
9	GASKET RING ? new	1	B18.30.7.581.970		\$ 30.45
10	OIL RETURN L ? X	1	B11.42.7.617.537		\$ 115.15
11	OIL SUPPLY L ? X	1	B11.42.8.487.372		\$ 115.15
12	GASKET FOR E ? new	1	B11.65.7.618.035		\$ 17.30
13	BRACKET, EXH ? X	1	B11.62.8.678.767		\$ 86.30
14	O-RING ? new	2	B11.53.7.610.049		\$ 5.40
15	ISA SCREW ? X	4	B07.12.9.905.867		\$ 5.00
16	WIRING HARNE ? new	1	B12.51.8.617.710		\$ 436.60
17	WIRING HARNE ? new	1	B12.51.8.644.492		\$ 436.60
18	CABLE HARNES ? new	1	M12.51.8.625.072		\$ 174.65
19	WIRING HARNE ? new	1	B12.53.8.617.707		\$ 174.65
20	WIRING LOOM, ? new	1	B12.51.8.617.722		\$ 174.65
21	BASE CONTROL ? new	1	M12.14.8.674.258		\$ 2,783.60
22	IGNITION COI ? ?	3	M12.13.8.643.360		\$ 317.55
23	RP INJECTOR ? ?	3	B13.53.8.625.396		\$ 1,608.00
24	ATF 6 ? new	6	B83.22.2.355.599		\$ 400.20
TOTAL PARTS					\$ 30,965.60
TOTAL PARTS COST					\$ 30,965.60
Labour Description					
1	REMOVING AND REPLACING ENGINE. ?		NETT	\$ 2,240.00	
2	REMOVING AND REPLACING EXHAUST TURBOCHARGER. ?		NETT	\$ 840.00	

3	REMOVING AND REPLACING ENGINE ELECTRICAL SYSTEM / ENGINE SENSOR SYSTEM MODULE VEHICLE ? WIRING HARNESS.	NETT	\$ 560.00	✓
4	ENGINE ELECTRICAL SYSTEM / WORKING TIME WITHOUT FRU SPECIFICATION/ENGINE ? ELECTRICAL SYSTEM. (PROGRAMMING)	NETT	\$ 560.00	✓
5	DRAWING OFF, EVACUATING AND TOPPING UP REFRIGERANT. ?	NETT	\$ 140.00	✓
6	APPLY NEW ENGINE BLOCK NUMBER AT LTA REGISTRATION FEE. ?	NETT	\$ 200.00	✓
7	SEND CAR TO INSPECTION CENTRE FOR ENGINE REPLACEMENT. ?	NETT	\$ 500.00	✓
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00	✓
9	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	NETT	\$ 200.00	✓
10	SUNDRIES.	NETT	\$ 20 50.00	✓
TOTAL LABOUR		\$ -	\$ 5,540.00	
TOTAL PARTS		\$ -	\$ 30,965.60	
TOTAL		\$ -	\$ 36,505.60	
LESS EXCESS		\$ -	\$ -	
TOTAL AFTER EXCESS		\$ -	\$ -	
GST 7%		\$ -	\$ -	
GRAND TOTAL		\$ -	\$ -	

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Karl
26/11/2020

Resurvey on 26/11/2020

Rasul
Hp 90010068

14 days

13/11/2020

EXCESS: 500

Revert

Resurvey before repair