



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0658/2020/NS
DATE : 14-Sep-20
WIP : 49175

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TAN CHUN WEI
ADDRESS : BLK 161 MEI LING STREET
#13-317
SINGAPORE 140161
TELEPHONE : HP +65 98198528
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800155391
VEHICLE NO : **SMH 2417 Y**
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 16/1/2019
ENGINE NO : CHZ B22295
CHASSIS NO : WAUZZZ8V8KA008925
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Sep-20
PLACE OF ACCIDENT : AYE(MCE) 12.5KM



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 2417 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N	\$ 280.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.	S/N	\$ 480.00	✓
3	TO RENEW REAR WINDSCREEN.	S/N	\$ 480.00	✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N	\$ 400.00	✓
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N	\$ 200.00	150.
6	TO DISLODGE AND REINSTALL ROOFTOP LINING TO FACILITATE RENEWAL OF REAR LID HINGES.	S/N	\$ 280.00	X
7	TO DISMANTLE AND RENEW REAR BUMPER, REAR BUMPER LOWER SPOILER AND REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 2,100.00	1000.
8	TO RESPRAY REAR BUMPER, SPOILER, REAR LID AND HINGES.		\$ 2,200.00	1400. 550 x 2 = 1100 Spoiler 150 x 2 = 300 1400
9	TO REALIGN REAR EXHAUST SILENCER TO POSITION.	S/N	\$ 280.00	X
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	✓
TOTAL LABOUR CHARGES		:	\$ 6,892.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 2417 Y

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER <i>Dented</i>		\$	1,847.00	✓
2 REAR BUMPER FIXING PARTS <i>new</i>		\$	191.00	+
3 REAR BUMPER LOCKING MECHANISM - LH / RH <i>new</i>	2	\$	28.00	+
4 WHEEL HOUSING LINER ADAPTER - LH / RH <i>new</i>	2	\$	74.00	+
5 REAR BUMPER SPOILER <i>new</i>		\$	234.00	+
6 REAR LIGHT REFLECTOR - LH / RH <i>?</i>	2	\$	60.00	?
7 LED TAIL LIGHT - LH / RH OUTER <i>new</i>	2	\$	1,734.00	+
8 LED TAIL LIGHT - LH / RH INNER <i>new</i>	2	\$	1,734.00	+
9 ADDITIONAL BRAKE LIGHT <i>new</i>		\$	179.00	+
10 LED LICENSE PLATE LIGHT <i>new</i>	2	\$	197.00	+
11 REAR REINFROCEMENT BEAM <i>new</i>		\$	565.00	+
12 REAR BUMPER BRACKET - LH <i>new</i>		\$	27.00	+
13 REAR BUMPER BRACKET - RH <i>new</i>		\$	28.00	+
14 REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$	132.00	+
15 REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2		TBC	+
16 REAR LID <i>Dented</i>		\$	1,981.00	✓
17 REAR LID ATTACHMENT PARTS <i>?</i>		\$	291.00	?
18 REAR LID HINGE <i>new</i>	2	\$	283.00	+
19 FLAP GASKET <i>new</i>		\$	203.00	+
20 REAR LID LOCK <i>new</i>		\$	169.00	+
SUB TOTAL SPARE PARTS	:	\$	9,957.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 2417 Y

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 LID LOCK PUSH BUTTON <i>new</i>		\$	172.00	+
22 PACKING ADHESIVE <i>new</i>		\$	18.00	✓
23 REAR LID LOCK STRIKER <i>new</i>		\$	85.00	+
24 AUDI EMBLEM <i>3 new</i>		\$	122.00	✓
25 A3 INSCRIPTION		\$	95.00	✓
26 REAR WINDSCREEN <i>new</i>		\$	805.00	✓
27 PRIMER		\$	19.00	✓
28 REAR CROSS PANEL TRIM <i>3 new</i>	S/N	\$	153.00	+
29 REAR LID TRIM PANEL - LOWER		\$	563.00	+
30 REAR WINDSCREEN SEALANT <i>new</i>	S/N	\$	200.00	✓
31 REAR NO PLATE <i>new</i>	S/N	\$	60.00	+
<i>photos</i> 32 REAR BUMPER SPOILER - LH/RH <i>new</i>		\$	290.00	✓
33 REAR BUMPER DIFFUSER <i>at</i>		\$	597.00	✓
34 SUNDRIES		\$	300.00	?
TOTAL SPARE PARTS	:	\$	12,539.00	
TOTAL LABOUR CHARGES	:	\$	6,892.00	
GRAND TOTAL	:	\$	19,431.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *11/11/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 0\$ pays.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR
CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR,
WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT