



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



### ESTIMATE

Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<tr> <td>Cust No/Name</td><td>KCV11912/CHAI KOH FONG</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMN6276D / 22/08/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 12211</td></tr> <tr> <td>Chassis No</td><td>GF7W0602104</td></tr> <tr> <td>Engine No</td><td>4J11BK5751</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY OUTLANDER 2.0 STYLE(994)</td></tr> <tr> <td>Colour/Trim</td><td>X04 BLACK / BK BLACK</td></tr>	Cust No/Name	KCV11912/CHAI KOH FONG	Reg No/Reg Date	SMN6276D / 22/08/201	Date In/Mileage	/ 12211	Chassis No	GF7W0602104	Engine No	4J11BK5751	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)	Colour/Trim	X04 BLACK / BK BLACK
Cust No/Name	KCV11912/CHAI KOH FONG														
Reg No/Reg Date	SMN6276D / 22/08/201														
Date In/Mileage	/ 12211														
Chassis No	GF7W0602104														
Engine No	4J11BK5751														
Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)														
Colour/Trim	X04 BLACK / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	12/11/2020/ 17:31	BLE	261 / Edwin Caina	59536
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW FRT BUMPER, FRT BUMPER BODY KIT, LHF FENDER & BONNET REPAIR FRT SUPPORT, LHF DOOR & RHF FENDER	@450 X 4			1800 2700.00
E PNT98000	RESPRAY FRT BUMPER, FRT BUMPER BODY KIT, FRT SUPPORT, BONNET LHF FENDER, LHF DOOR & RHF FENDER	@350 X 4			1400 2450.00
A 25000001	REMOVE & REFIT AC COND & RADIATOR TO FACILITATE REPAIR				? 100.00
A 25000001	TOP UP AIRCON GAS				? 80.00
A 54900099	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				30 60.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS				60 80.00
M SUNDRY	SUPPLY FRT NUMBER PLATE WITH CASING				X 50.00
M SUNDRY	Sundries				30.00
M	FACE, FR BUMPER	1.00	1048.00	23.00	806.96
M	EXTENSION, FR BUMPER	1.00	515.00	23.00	396.55
M	BRACKET, FR BUMPER SIDE, LHF	1.00	18.00	23.00	13.86
M	BRACKET, FR BUMPER SIDE, RH	1.00	18.00	23.00	13.86
M	COVER, FR BUMPER	1.00	359.00	23.00	276.43
M	GARNISH, FR BUMPER, LHF	1.00	48.00	23.00	36.96
M	GARNISH, FR BUMPER SIDE	1.00	48.00	23.00	36.96
M	GARNISH, FR BUMPER SIDE	1.00	220.00	23.00	169.40
M	GARNISH, FR BUMPER SIDE	1.00	112.00	23.00	86.24
M	REINFORCEMENT, FR BUMPER	1.00	490.00	23.00	377.30
M	BAR, FR BUMPER GUARD	1.00	130.00	23.00	100.10
M	REINFORCEMENT, FR BUMPER	1.00	134.00	23.00	103.18

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

## ESTIMATE

Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr><td>Cust No/Name</td><td>KCV11912/CHAI KOH FONG</td></tr> <tr><td>Reg No/Reg Date</td><td>SMN6276D / 22/08/201</td></tr> <tr><td>Date In/Mileage</td><td>/ 12211</td></tr> <tr><td>Chassis No</td><td>GF7W0602104</td></tr> <tr><td>Engine No</td><td>4J11BK5751</td></tr> <tr><td>Make/Model</td><td>MIT/19MY OUTLANDER 2.0 STYLE(994)</td></tr> <tr><td>Colour/Trim</td><td>X04 BLACK / BK BLACK</td></tr> </table>	Cust No/Name	KCV11912/CHAI KOH FONG	Reg No/Reg Date	SMN6276D / 22/08/201	Date In/Mileage	/ 12211	Chassis No	GF7W0602104	Engine No	4J11BK5751	Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)	Colour/Trim	X04 BLACK / BK BLACK
Cust No/Name	KCV11912/CHAI KOH FONG														
Reg No/Reg Date	SMN6276D / 22/08/201														
Date In/Mileage	/ 12211														
Chassis No	GF7W0602104														
Engine No	4J11BK5751														
Make/Model	MIT/19MY OUTLANDER 2.0 STYLE(994)														
Colour/Trim	X04 BLACK / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	12/11/2020/ 17:31	BLE	261 / Edwin Caina	59536
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M REINF,FR BUMPER SIDE,LH ?		1.00	60.00	23.00	46.20
M COVER,HEADLAMP SUPT PANEL ?		1.00	50.00	23.00	38.50
M COVER,FR BUMPER ?		1.00	25.00	23.00	19.25
M GRILLE ASSY,RADIATOR ?		1.00	548.00	23.00	421.96
M HOOD ?		1.00	697.00	23.00	536.69
M HINGE,HOOD,LH ?		1.00	68.00	23.00	52.36
M HINGE,HOOD,RH ?		1.00	68.00	23.00	52.36
M CLIP,HOOD INSULATOR ?		8.00	3.00	23.00	18.48
M PLUG,HOOD ?		4.00	4.00	23.00	12.32
M LATCH,HOOD X		1.00	76.00	23.00	58.52
M FENDER,FR LH ?		1.00	688.00	23.00	529.76
M INSULATOR,FR FENDER,LH ?		1.00	60.00	23.00	46.20
M PNL,HEADLAMP SUPT,UPR LH ?		1.00	58.00	23.00	44.66
M PANEL,HEADLAMP SUPPORT,UPR ?		1.00	182.00	23.00	140.14
M PANEL,HEADLAMP SUPPORT,LWR ?		1.00	107.00	23.00	82.39
M HEADLAMP ASSY,LH ?		1.00	1938.00	23.00	1492.26
M LAMP ASSY,FOG,FR LH ?		1.00	348.00	23.00	267.96
M MOULDING,FR BUMPER,LH ?		1.00	116.00	23.00	89.32
M MOULDING,FR WHEEL ARCH,LH ?		1.00	160.00	23.00	123.20
M SHIELD,FR WHEELHOUSE,LH ?		1.00	164.00	23.00	126.28
M BODY KIT, OUTLANDER ?		1.00	1554.00	20.00	1243.20
M ENGINE HOOD EMBLEM ?		1.00	80.00	23.00	61.60
M LLC 4L ?		1.00	26.00	23.00	20.02

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Estimate

SURVEYOR NAME: Ronal - Hp 50010068

SURVEYOR SIGNATURE: PM

Confirm & accepted by DATE: 13/11/2020 @ 16:25

REMARKS: EXCESS: TAA / REPAIR  
7 days  
Resurvey before paint

Authorized signatory and company stamp

Nett	13,691.43
7% GST on	13691.43
Total Payable	14,649.83

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.