



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2101118

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 22/02/2021
Reference CC6/CTI20012476/Kra3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SJS 909K
Insured Veh. SJH 6984K
Claim No. SNM20D204372/LKKDS
Policy No. DMCVSNW00004382000
Accident Date 11/11/2020
Inspection Date 16/11/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20012476/Kra3q2 Date: 22/02/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJH 6984K	Veh. Inspected	SJS 909K
	Policy No.	DMCVSNW00004382000	Coverage (\$)	0.00
	Claim No.	SNM20D204372/LKKDS	Excess (\$)	0.00
	Assign From		Assign Date	13/11/2020
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E250 (A)	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WDD2120362A799561	Colour	METALLIC DARK BLUE
	Odometer	99211 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R18	CONTINENTAL	8 mm
	L/H Front Tyre	245/40 R18	CONTINENTAL	8 mm
	R/H Rear Tyre	245/40 R18	GOODYEAR	8 mm
	L/H Rear Tyre	245/40 R18	GOODYEAR	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/11/2020	Inspection Date	16/11/2020
	Survey held at	KING'S AUTO SPRAY PAINT PTE LTD 160 SIN MING DRIVE #05-10 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 909K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	TO REPAIR SEE LABOUR	3,244.00	-
1	REAR BOOT LID LOGO	NECESSARY	54.00	54.00
1	REAR BOOT LID E 250 EMBLEM	NECESSARY	93.00	93.00
1	REAR BOOT LID TG-TRONIC EMBLEM	NECESSARY	101.00	101.00
2	REAR BOOT LID REFLECTOR @\$527.00	SCRATCHED	1,054.00	1,054.00
1	REAR BOOT LID NUMBER PLATE MLDG	SERVICEABLE	132.00	-
1	REAR BOOT LID LOCK	DENTED	354.00	354.00
2	REAR TAIL LAMP @\$817.00	SCRATCHED / CRACKED	1,634.00	1,634.00
1	REAR BUMPER	BENT / CRACKED	1,921.00	1,821.00
2	REAR BUMPER RETAINER SIDE @\$53.00	SERVICEABLE	106.00	-
1	REAR BUMPER COVER	SERVICEABLE	50.00	-
1	REAR BUMPER BEAM	BENT	949.00	949.00
2	REAR BUMPER BRACKETS @\$27.00	O/S DISTORTED	54.00	27.00
2	REAR BUMPER MLDG SIDE @\$149.00	NECESSARY	298.00	298.00
6	REAR BUMPER SENSOR @\$199.00	MISSING	1,194.00	199.00
1	REAR BUMPER LOWER SPOILER	DISTORTED	369.00	369.00
1	REAR BUMPER SPOILER MLDG CENTER	CRACKED	222.00	222.00
2	REAR EXHAUST MLDG PIPE @\$356.00	O/S DENTED	712.00	287.00
1	REAR CENTER PANEL	BENT	1,452.00	1,452.00
1	REAR PANEL TOP TRIM INNER	CRACKED	316.00	213.00
10	REAR PANEL TRIM CLIPS @\$6.00	NECESSARY	60.00	60.00
	LESS 10% DISCOUNT		-1,436.90	-918.70
			12,932.10	8,268.30
1	REAR BOOT LID RUBBER (50%) (SN)	DISTORTED / DENTED	212.00	106.00
	LESS 10% DISCOUNT		-21.20	-
			190.80	106.00

Report Ref No. CC6/CTI20012476/Kra3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>NETT ITEMS</u>			
1	EXHAUST PIPE (N)	BENT	1,560.00	1,560.00
	LESS 10% DISCOUNT		-	-156.00
			1,560.00	1,404.00
	<u>LABOUR</u>			
	CHECK WIRING .		40.00	20.00
	TO RENEW THE ABOVE MENTIONED PARTS KNOCKING CUTTING ,WELDING & STRAIGHTEN DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR BOOT LID .		1,200.00	700.00
	SPRAY PAINTING.		1,000.00	660.00
			2,240.00	1,380.00
GRAND TOTAL			16,922.90	11,158.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,900.00

Report Ref No. CC6/CTI20012476/Kra3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJS 909K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJS 909K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJS 909K

RE-INSPECTION

