

LEE LIPLIN

King's Auto Spray Paint Pte Ltd
Blk 160 Sin Ming Drive #05-10
sin ming Autocity Singapore 575722

Not Withheld
11 Sep @ 8900h
Resurvey After Rainy
6 days

Re: Estimate cost for SJS 909K MERCEDES-BENZ

SUPPLY OF PARTS:

1pc rear boot lid		R	#3244	X
1pc rear boot lid logo		na	54	—
1pc rear boot lid E 250 emblem		na	93	—
1pc rear boot lid 7G-TRONIC emblem		n	101	—
2pc rear boot lid reflector	527 @	na	1054	—
1pc rear boot lid numberplate mldg		sn	132	X
1pc rear boot lid rubber		106SN	Dis/mr 212	506m
1pc rear boot lid lock		na	354	—
2pc rear tail lamp	817 @ C	na/na	1634	—
1pc rear bumper	1121	Bl/CM	1921	—
2pc rear bumper retainer side	53 @	sn	106	X
1pc rear bumper cover		sn	50	X
1pc rear bumper beam		R	949	—
2pc rear bumper brackets	27 @	cls/dit	54	—
2pc rear bumper mldg side	149 @	n	298	—
1pc rear bumper sensor	199 @	mit	1194	—
1pc rear bumper lower spoiler		dit	369	—
1pc rear bumper spoiler mldg center		cm	222	—
2pc rear exhaust mldg pipe	@356	cls/dit	712	4287
1pc rear center panel		R	1452	—
1pc rear panel top trimmer	213	cm	316	—
10p rear panel trim clips	@6	n	#60	—

14581.00
1458.10
#13122.90
108 R 40.00 2cl
1560.00 ?
1200.00 70a
#1000 660l
16922.90

LABOUR:

check wiring
1pc exhaust pipe

To renew the above mentioned Parts
Knocking, cutting, welding & straighten
damaged parts
spray painting

LKK Auto Consultants hence notify 10%
the Repairer of the following:
• To resurvey before spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: