



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103826

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 01/06/2021  
Reference CC6/CTI20012480/Kes3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SJU 9403H  
Insured Veh. GBD 5644P  
Claim No. SNM20D204317/C02  
Policy No. DMCVSN30756319011  
Accident Date 09/11/2020  
Inspection Date 17/11/2020

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                              |                                                                                                                                        |            |                             |               |
|------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|------------|-----------------------------|---------------|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909 |                                                                                                                                        |            | Ref: CC6/CTI20012480/Kes3q2 |               |
|                                                                                                |                                                                                                                                        |            | Date: 01/06/2021            |               |
|                                                                                                |                                                                                                                                        |            | Code: CTI                   |               |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                              |                                                                                                                                        |            |                             |               |
| Insured Veh.                                                                                   | GBD 5644P                                                                                                                              |            | Veh. Inspected              | SJU 9403H     |
| Policy No.                                                                                     | DMCVSN30756319011                                                                                                                      |            | Coverage (\$)               | 0.00          |
| Claim No.                                                                                      | SNM20D204317/C02                                                                                                                       |            | Excess (\$)                 | 0.00          |
| Assign From                                                                                    |                                                                                                                                        |            | Assign Date                 | 17/11/2020    |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                  |                                                                                                                                        |            |                             |               |
| Make & Model                                                                                   | HYUNDAI I30 (A)                                                                                                                        |            | c.c                         | 1591          |
| Engine No.                                                                                     | HIDDEN                                                                                                                                 |            | Year of Reg.                | 2010          |
| Chassis No.                                                                                    | KMHDC51DMAU231186                                                                                                                      |            | Colour                      | METALLIC GREY |
| Odometer                                                                                       | 211241 KM                                                                                                                              |            | Steering                    | IN ORDER      |
| Brakes                                                                                         | IN ORDER                                                                                                                               |            | Modification                | SPORTS RIM    |
| General                                                                                        | GOOD                                                                                                                                   |            |                             |               |
| <b>3. Conditions of Tyres</b>                                                                  |                                                                                                                                        |            |                             |               |
|                                                                                                |                                                                                                                                        | Size       | Make                        | Balance       |
| R/H Front Tyre                                                                                 |                                                                                                                                        | 205/55 R16 | PIRELLI                     | 7 mm          |
| L/H Front Tyre                                                                                 |                                                                                                                                        | 205/55 R16 | PIRELLI                     | 7 mm          |
| R/H Rear Tyre                                                                                  |                                                                                                                                        | 205/55 R16 | PIRELLI                     | 7 mm          |
| L/H Rear Tyre                                                                                  |                                                                                                                                        | 205/55 R16 | PIRELLI                     | 7 mm          |
| <b>4. Description of Damages</b>                                                               |                                                                                                                                        |            |                             |               |
|                                                                                                | THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.<br><br>DAMAGES SEE DETAILS.                                                 |            |                             |               |
| <b>5. General Information</b>                                                                  |                                                                                                                                        |            |                             |               |
| Accident Date                                                                                  | 09/11/2020                                                                                                                             |            | Inspection Date             | 17/11/2020    |
| Survey held at                                                                                 | ALAN'S UNITED AUTO PTE LTD<br>BLK 7 SIN MING INDUSTRIAL ESTATE<br>#01-76<br>SINGAPORE 575642                                           |            |                             |               |
| <b>5a. Remarks</b>                                                                             |                                                                                                                                        |            |                             |               |
|                                                                                                | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |            |                             |               |
| <b>5b. Estimate Days of Repair</b>                                                             |                                                                                                                                        |            |                             |               |
|                                                                                                | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |            | 18 Working Days             |               |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 9403H

| Qty | Description of Parts                | Condition                 | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------|---------------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>  |                           |                           |                   |
| 1   | FRONT BUMPER FASCIA                 | BUCKLED                   | 485.00                    | 485.00            |
| 1   | FRONT BUMPER REINFORCEMENT          | BENT                      | 258.20                    | 258.20            |
| 1   | FRONT BUMPER SPONGE                 | MISSING                   | 182.10                    | 182.10            |
| 1   | FRONT BUMPER LOWER GRILLE           | DISTORTED / DENTED        | 93.20                     | 93.20             |
| 2   | FRONT BUMPER SIDE RETAINER @\$35.90 | DISTORTED                 | 71.80                     | 71.80             |
| 1   | RADIATOR GRILLE                     | DENTED                    | 135.20                    | 135.20            |
| 1   | RADIATOR GRILLE LOGO                | NECESSARY                 | 33.00                     | 33.00             |
| 1   | RADIATOR GRILLE CHROME              | MTG CRACKED               | 191.00                    | 191.00            |
| 2   | HEADLAMP @\$606.20                  | O/S CUT / N/S MTG CRACKED | 1,212.40                  | 1,212.40          |
| 1   | FRONT SUPPORT PANEL                 | BENT                      | 863.90                    | 863.90            |
| 1   | BONNET                              | BENT                      | 1,885.60                  | 1,885.60          |
| 1   | REAR O/S FENDER                     | BUCKLED                   | 1,754.10                  | 1,754.10          |
| 1   | REAR O/S FENDER INNER TRIM          | CRACKED                   | 163.00                    | 163.00            |
| 2   | REAR FENDER INNER SHIELD @\$75.00   | CRACKED                   | 150.00                    | 150.00            |
| 2   | REAR FENDER AIR VENT @\$29.10       | CRACKED                   | 58.20                     | 58.20             |
| 1   | REAR WINDSCREEN GLASS               | SHATTERED                 | 563.90                    | 563.90            |
| 1   | TAIL GATE                           | BENT                      | 2,045.70                  | 2,045.70          |
| 1   | TAIL GATE WIPER MOTOR               | JAMMED                    | 387.20                    | 387.20            |
| 1   | TAIL GATE WIPER ARM                 | SERVICEABLE               | 76.90                     | -                 |
| 1   | TAIL GATE WIPER BLADE               | CRACKED                   | 33.20                     | 33.20             |
| 1   | TAIL GATE INNER TRIM COVER          | CRACKED                   | 272.30                    | 272.30            |
| 1   | TAIL GATE INNER LOCK                | DENTED                    | 166.80                    | 166.80            |
| 1   | TAIL GATE INNER TRIM LAMP           | MISSING                   | 15.00                     | 15.00             |
| 1   | TAIL GATE 'HYUNDAI' EMBLEM          | NECESSARY                 | 26.10                     | 26.10             |
| 1   | TAIL GATE LOGO                      | NECESSARY                 | 18.00                     | 18.00             |
| 1   | TAIL GATE 'I30' EMBLEM              | NECESSARY                 | 28.70                     | 28.70             |
| 2   | TAILLAMP @\$533.60                  | CRACKED                   | 1,067.20                  | 1,067.20          |
| 2   | TAILLAMP CORNER PANEL @\$175.70     | O/S BENT                  | 351.40                    | 175.70            |
| 1   | REAR END PANEL                      | BENT                      | 499.30                    | 499.30            |

Report Ref No. CC6/CTI20012480/Kes3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | END PANEL TOP GARNISH                              | DISTORTED            | 75.20                     | 75.20             |
| 1   | REAR SPARE TYRE PANEL                              | BENT                 | 584.40                    | 584.40            |
| 1   | REAR SPARE TYRE BOARD                              | DEFORMED             | 288.90                    | 288.90            |
| 1   | REAR BUMPER FASCIA                                 | BENT                 | 460.40                    | 460.40            |
| 1   | REAR BUMPER REINFORCEMENT                          | BENT                 | 370.00                    | 370.00            |
| 2   | BUMPER REINFORCEMENT BRACKET @\$89.20              | BENT                 | 178.40                    | 178.40            |
| 1   | REAR BUMPER SPONGE                                 | CRACKED              | 135.20                    | 135.20            |
| 2   | REINFORCEMENT BRACKET (TOP) @\$5.20                | CRACKED              | 10.40                     | 10.40             |
| 3   | REINFORCEMENT BRACKET (LOW) @\$14.60               | CRACKED              | 43.80                     | 43.80             |
| 1   | SET REAR LICENSE PLATE LAMP                        | MISSING              | 62.50                     | 62.50             |
| 2   | REAR BUMPER SIDE RETAINER @\$25.90                 | CRACKED              | 51.80                     | 51.80             |
| 2   | REAR BUMPER UNDER COVER @\$97.90                   | CRACKED              | 195.80                    | 195.80            |
| 1   | REAR O/S CHASSIS MEMBER                            | TO REPAIR SEE LABOUR | 657.20                    | -                 |
| 1   | REAR EXHAUST SILENCER BOX                          | BENT                 | 711.70                    | 711.70            |
| 1   | AIR CON CONDENSER (ADDITIONAL)                     | PUNCTURE             | 990.90                    | 990.90            |
| 1   | RADIATOR ASSY (ADDITIONAL)                         | PUNCTURE             | 588.76                    | 588.76            |
| 2   | AIR CON CONDENSER SIDE GUIDE @\$14.70 (ADDITIONAL) | CRACKED              | 29.40                     | 29.40             |
|     | LESS 20% DISCOUNT                                  |                      | -3,704.63                 | -3,522.67         |
|     |                                                    |                      | 14,818.53                 | 14,090.69         |
| 1   | TAIL GATE RUBBER (50%) (SN)                        | CUT                  | 124.30                    | 62.15             |
|     | LESS 20% DISCOUNT                                  |                      | -24.86                    | -                 |
|     |                                                    |                      | 99.44                     | 62.15             |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                   |                      |                           |                   |
| 1   | REAR NO.PLATE WITH BOX (SN)                        | DENTED               | 50.00                     | 45.00             |
| 1   | FRONT NO.PLATE WITH BOX (SN)                       | DENTED               | 50.00                     | 45.00             |
| 1   | REAR BUMPER REVERSE SENSOR (SN)                    | SHORTED              | 300.00                    | 200.00            |
| 1   | SET REAR IN CAR CAMERA (SN)                        | MISSING              | 480.00                    | 350.00            |
| 1   | REAR W/S GLASS SOLAR FILM (SN)                     | NECESSARY            | 300.00                    | 150.00            |
| 1   | REAR W/S GLASS SEALANT (SN)                        | NECESSARY            | 60.00                     | 40.00             |

Report Ref No. CC6/CTI20012480/Kes3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                         | Description of Parts                                                                                                                                  | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
| 1                                                                           | TIN RADIATOR COOLANT (SN) (ADDITIONAL)                                                                                                                | NECESSARY | 30.00                     | 30.00             |
|                                                                             |                                                                                                                                                       |           | 1,270.00                  | 860.00            |
|                                                                             | <b>LABOUR</b>                                                                                                                                         |           |                           |                   |
|                                                                             | TO TOWING .                                                                                                                                           |           | 50.00                     | 50.00             |
|                                                                             | TO REMOVE & RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.                                                                                  |           | 150.00                    | 120.00            |
|                                                                             | TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET .                                                                                  |           | 200.00                    | 120.00            |
|                                                                             | TO APPLY UNDERSEALING .                                                                                                                               |           | 280.00                    | 150.00            |
|                                                                             | TO REMOVE AND RENEW EXHAUST SILENCER BOX .                                                                                                            |           | 60.00                     | 60.00             |
|                                                                             | TO PUTTY AND SPRAY REPLACED PARTS.                                                                                                                    |           | 1,800.00                  | 1,600.00          |
|                                                                             | TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR O/S CHASSIS MEMBER . |           | 2,200.00                  | 2,000.00          |
|                                                                             | TO REMOVE AIR CON CONDENSER ,PIPES & DRIER ,VACUUM AIR CON AND TO RECHARGE GAS. (ADDITIONAL)                                                          |           | 120.00                    | 100.00            |
|                                                                             | TO SEND VEHICLE FOR PTE HIRE DECAL INSPECTION AND INSTALL NEW DECAL. (ADDITIONAL)                                                                     |           | 40.00                     | 40.00             |
|                                                                             |                                                                                                                                                       |           | 4,900.00                  | 4,240.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                                                       |           | <b>21,087.97</b>          | <b>19,252.84</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                                       |           |                           | <b>15,400.00</b>  |

Report Ref No. CC6/CTI20012480/Kes3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJU 9403H

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJU 9403H

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SJU 9403H**

**RE-INSPECTION**

