

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20012482/T1QF3E2

Date: 31/03/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00101222000
Claimant Vehicle No: SBS8416H Insured Vehicle No: SMU3093Y
Date of Loss: 07/11/2020 Nature of Claim: TP Claim No: SNM20D204348/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS8416H**
Make & Model: SCANIA KUB4X2, 8.9 ABS TURBO 2WD (A) Engine No: 6378934
Reg. Date: 28/11/2008 (Man. Year: 2008) Chassis No: YS2K4X20001862176
Colour: Multi-colour Odometer: 932540 km
Engine Capacity: 8867 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	900.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	900.00	900.00	0.00	0.00
+ GST 7.00/7.00% (\$\$)	63.00	63.00	0.00	0.00
Nett Amount (\$\$)	963.00	963.00	0.00	0.00

INSPECTION

Date of Assignment: 13/11/2020
Date Inspected: 27/11/2020 Inspected At: Sbs Transit Ltd (Bedok) (HQ)
1470 BEDOK NORTH AVE 4
Singapore 489946
Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 Mar 2021)	
Parts:	N/A	SCANIA KUB4X2 8.9 ABS TURBO 2WD (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS8416H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CONTRACTOR LABOUR COST	New	900.00	900.00
Gross Labour Cost (\$\$)			900.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >